



# AUTOHUB CAR CARE SERVICES (ACCS)

BY: SUPREME AUTOZONE PHILIPPINES INC.

Sitio Buroi Cabrera Road, Brgy San Juan, Taytay, Rizal

Tel. No. (632) 533-6398

VAT REG. TIN: 236-978-189-00006

30

## BILLING STATEMENT

No: **06161**

CUSTOMER No. 211006	CUSTOMER NAME AND ADDRESS TIN: NOTOITALIA PHILS. INC. #234 ORTIGAS AVENUE NORTH GREENHILLS SAN JUAN CITY MMN 000		ADVISOR Older Padilla	COLOR YELLOW	TEAM NH GENE
DOC. DATE 22/12/22	REG. No. UNREG		YEAR/MAKE/MODEL 22/NEXTHUB/SPRINT	TAG No.	
STOCK No.	PURCHASE ORDER No.		MODEL No. UNREG	CAR LINE VESPA	ENG./TRANS.
DRIVER		CONTACT No.	CHASSIS No.	KILOMETERS	PROD. DATE
HOME PHONE		BUSINESS PHONE	CONTACT NAME	CONTRACT EXR KMS	EXP. DATE
CA <input type="checkbox"/>	PC <input type="checkbox"/>	CH <input type="checkbox"/>	SELLING DEALER	DELIVERY KMS	DELIVERY DATE
QC <input type="checkbox"/>	VAR <input type="checkbox"/>	INT <input type="checkbox"/>	DATE AND TIME PROMISED 21/12/22 09:00pm	TIME RECEIVED 10:35am	QUOTE PRICE
VEHICLE ID RRAMA2221NV07920		ENGINE No. 5185273	AIR PWR TURBO		

Labour  
J# 1 76NAZZZZZ002

PDI CLEAN  
\* PDI UNIT  
\* BRAND NEW UNIT  
\* CHECK AND EVALUATED CONCERN  
\* PERFORMED PDI INSPECTION

Tech(s) : 48061 3125.00

Total - Labour 3125.00

Totals=====

Total Labour. 3125.00  
Total Parts.. 0.00  
Total Other.. 0.00  
Total P.O.L.. 0.00  
Total Misc... 0.00  
VAT 375.00

Total Invoice 3500.00

*RJR*  
12/22/22

[ End of Invoice ]

ROAD TESTED		<b>ACKNOWLEDGMENT</b>	
ORDER NO.	SUBLET REPAIRS	RECEIVED above vehicle from AUTOHUB CAR CARE SERVICES (ACCS) in good condition and with all repair work enumerated completed to my satisfaction.	
		All works carried out at these premises are subject to a warranty of _____ days or _____ whichever comes first on all labor and materials.	
		SIGNATURE OF OWNER _____	
		I AGREE TO PAY for all works required for all the above described repair at your retail charge. It is understood that any estimate given is provisional and all repairs are undertaken on a cash basis unless prior arrangements for credit have been approved.	
		I have READ AND ACCEPTED your terms and conditions.	

## CHECKLIST

10428

PAGE 1

Client :

Chassis # :

NV079206

Color:

Yellow

Make/Model :

Sprint

Engine # :

5185273

Date :

10-22-2002

### EMBLEMS

- ( ) Piaggio Emblem ( Front )  
( ) PVG Emblem ( Crankcase )

### SIDE MIRROR

- ( ) LH Side View Mirror  
( ) RH Side View Mirror

### ELECTRICAL BUTTONS

- ( ) Start Button  
( ) Horn Button  
( ) High&Low Button  
( ) Passing Button ( Optional )  
( ) Left Signal Button  
( ) Right Signal Button  
( ) Cut Off Engine Button ( Optional )  
( ) Start & Stop Button  
( ) ASR Button  
( ) Mode  
( ) Saddle Button  
( ) Toggle Switch

### LIGHTS

- ( ) Park Light  
( ) High & Low Beam  
( ) Front Right Signal  
( ) Rear Right Signal  
( ) Front Left Signal  
( ) Rear Left Signal  
( ) Backlight  
( ) Brakelights  
( ) Instrumental Panel Gauges  
( ) Plate Light

### FLUID LEVELS

- ( ) Engine Oil  
( ) Gear Oil  
( ) Brake Fluid  
( ) Coolant

### SCRATCHES

- ( ) No Scratches  
( ) W/ Scratches  
\*Encircle parts that has/have scratches

### COLOR

- ( ) Evenly Painted  
( ) Not Evenly Painted

### BATTERY/ HORN

- ( ) Battery  
Brand: Duracell Battery Voltage: \_\_\_\_\_  
( ) Horn

### TIRES

- ( ) Good Quality  
( ) Bad Quality  
Brand: Maxxis  
Tire Pressure: \_\_\_\_\_ Front \_\_\_\_\_ Rear \_\_\_\_\_

### PADS DIAGNOSTIC TOOL

- ( ) PADS Checkup  
Fault : \_\_\_\_\_  
Remarks: \_\_\_\_\_

### SADDLE

- ( ) Good Quality  
( ) Bad Quality  
KEYS/ MANUAL/ TOOLS  
( ) Master Key  
( ) Duplicate Key  
( ) Service Manual  
( ) Warranty Booklet  
( ) Set of Screw  
( ) Battery Holder  
( ) Plate Holder  
( ) reflectors ( Optional )  
( ) Under Body Caps ( Optional )  
( ) 1 Set of Tools  
( ) Rear Shock Adjuster  
( ) Screw Driver  
( ) Fuse Removal Tool  
( ) Screw driver ( FLOWER KEY )  
( ) Sparkplug Wrench

Remarks :

Complete accessories and Battery

I understand all the above items as explained to me by the releasing Officer/ Manager. I also agree that any failure on my part to adhere to any of the instructions given that may result in damages on the above mentioned parts will not be covered by warranty.

Inspected by :

Technician/PDI Personnel

Approved by :

Service Manager

Approved by :

Sales Department



CHECKLIST

Client :

Chassis # :

NV079206

Color:

10428  
Yellow

PAGE 2

Make/Model :


Sprint

Engine # :

5185273

Date :

10-22-2003



W. Abrea

LEGEND

S- Scratched

L- Loose

D- Dented

M- Missing

DD-Damaged

F- Faded

Remarks:

Buffing all Funnels on Wax



# AUTOHUB CAR CARE SERVICES (ACCS)

BY: SUPREME AUTOZONE PHILIPPINES INC.

Silio Buroi Cabrera Road, Brgy. San Juan, Taytay, Rizal

Tel. No. (632) 533-6398

VAT REG TIN: 236-978-189-00006

## BILLING STATEMENT

No: **06162**

CUSTOMER No.	CUSTOMER NAME AND ADDRESS		ADVISOR	COLOR	TEAM
DOC. DATE	TIN: MOTOITALIA PHILS. INC.		YEAR/MAKE/MODEL	40054 YELLOW	NH GENER
REG. No.	#234 ORTIGAS AVENUE		22/NEXTHUB/SPRINT		TAG No.
STOCK No.	NORTH GREENHILLS		MODEL No.	UNREG	ENG./TRANS.
PURCHASE ORDER No.	DRIVER	CONTACT No.	CHASSIS No.	KILOMETERS	PROD. DATE
	HOME PHONE	BUSINESS PHONE	CONTACT NAME	CONTRACT EXP KMS	EXP. DATE
<input type="checkbox"/> CA <input type="checkbox"/> F/C <input type="checkbox"/> CH	VEHICLE ID	ENGINE No.	SELLING DEALER	DELIVERY KMS	DELIVERY DATE
<input type="checkbox"/> OC <input type="checkbox"/> WAR <input type="checkbox"/> INT	RPAM8222INV079117 5182424		DATE AND TIME PROMISED	TIME RECEIVED	QUOTE PRICE
			21/12/22 09:00pm	10:36am	AIR PWR TURBO

Labour J# 1 76NAZZZZZ002

PD CLEAN Tech(s) : 48061 3125.00

\* PDI UNIT  
\* BRAND NEW UNIT  
\* CHECK AND EVALUATED CONCERN  
\* PERFORMED PDI INSPECTION

Total - Labour 3125.00

Totals=====

Total Labour. 3125.00  
Total Parts.. 0.00  
Total Other.. 0.00  
Total P.O.L.. 0.00  
Total Misc... 0.00  
VAT 375.00  
Total Invoice 3500.00

*Signature*  
12/22/22

ROAD TESTED		ACKNOWLEDGMENT	
ORDER NO.	SUBLET REPAIRS	RECEIVED above vehicle from AUTOHUB CAR CARE SERVICES (ACCS) in good condition and with all repair work enumerated completed to my satisfaction.	I AGREE TO PAY for all works required for all the above described repair at your retail charge. It is understood that any estimate given is provisional and all repairs are undertaken on a cash basis unless prior arrangements for credit have been approved.
		All works carried out at these premises are subject to a warranty of _____ days or _____ whichever comes first on all labor and materials.	I have READ AND ACCEPTED your terms and conditions.
		SIGNATURE OF OWNER _____	



## CHECKLIST

10429

PAGE 1

Client :

Chassis # :

NV079117

Color :

Yellow

Make/Model :

Sprint

Engine # :

5782424

Date :

10-22-2022

### EMBLEMS

- ☐ Piaggio Emblem ( Front )
- ☐ PVG Emblem ( Crankcase )

### SIDE MIRROR

- ☐ LH Side View Mirror
- ☐ RH Side View Mirror

### ELECTRICAL BUTTONS

- ☐ Start Button
- ☐ Horn Button
- ☐ High&Low Button
- ☐ Passing Button ( Optional )
- ☐ Left Signal Button
- ☐ Right Signal Button
- ☐ Cut Off Engine Button ( Optional )
- ☐ Start & Stop Button
- ☐ ASR Button
- ☐ Mode
- ☐ Saddle Button
- ☐ Toggle Switch

### LIGHTS

- ☐ Park Light
- ☐ High & Low Beam
- ☐ Front Right Signal
- ☐ Rear Right Signal
- ☐ Front Left Signal
- ☐ Rear Left Signal
- ☐ Backlight
- ☐ Brakelights
- ☐ Instrumental Panel Gauges
- ☐ Plate Light

### FLUID LEVELS

- ☐ Engine Oil
- ☐ Gear Oil
- ☐ Brake Fluid
- ☐ Coolant

### SCRATCHES

- ☐ No Scratches
- ☐ W/ Scratches
- \*Encircle parts that has/have scratches

### COLOR

- ☐ Evenly Painted
- ☐ Not Evenly Painted

### BATTERY/ HORN

- ☐ Battery
- Brand: DESKON Battery Voltage: \_\_\_\_\_
- ☐ Horn

### TIRES

- ☐ Good Quality
- ☐ Bad Quality
- Brand: MAXXIS
- Tire Pressure: \_\_\_\_\_ Front \_\_\_\_\_ Rear \_\_\_\_\_

### PADS DIAGNOSTIC TOOL

- ☐ PADS Checkup
- Fault: \_\_\_\_\_
- Remarks: \_\_\_\_\_

### SADDLE

- ☐ Good Quality
- ☐ Bad Quality
- KEYS/ MANUAL/ TOOLS
- ☐ Master Key
- ☐ Duplicate Key
- ☐ Service Manual
- ☐ Warranty Booklet
- ☐ Set of Screw
- ☐ Battery Holder
- ☐ Plate Holder
- ☐ reflectors ( Optional )
- ☐ Under Body Caps ( Optional )
- ☐ 1 Set of Tools
- ☐ Rear Shock Adjuster
- ☐ Screw Driver
- ☐ Fuse Removal Tool
- ☐ Screw driver ( FLOWER KEY )
- ☐ Sparkplug Wrench

Remarks :

Complete accesories and Battery

I understand all the above items as explained to me by the releasing Officer/ Manager. I also agree that any failure on my part to adhere to any of the instructions given that may result in damages on the above mentioned parts will not be covered by warranty.

Inspected by :

W. Abrea

Technician/PDI Personnel

Approved by :

Service Manager

Approved by :

Sales Department



CHECKLIST

10429

PAGE 2

Client :

Chassis # :

NV079117

Color:

Yellow

Make/Model :


Sprint

Engine # :

5182424

Date :

10-22-2022



LEGEND

S- Scratched

L- Loose

D- Dented

M- Missing

DD-Damaged

F- Faded

Remarks:

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_





# AUTOHUB CAR CARE SERVICES (ACCS)

BY: SUPREME AUTOZONE PHILIPPINES INC.

Sitio Buroi Cabrera Road, Brgy. San Juan, Taytay, Rizal

Tel. No.: (632) 533-6398

VAT REG TIN: 236-978-189-00006

## BILLING STATEMENT

No: 06163

CUSTOMER No. 211806	CUSTOMER NAME AND ADDRESS TIN: MOTOITALIA PHILS. INC. #234 ORTIGAS AVENUE NORTH GREENHILLS SAN JUAN CITY MMN 000		ADVISOR Aldrin Padilla	COLOR 4004 BLUE	TEAM NH GENER
DOC. DATE 22/12/22	REG. No. UNREG		YEAR/MAKE/MODEL 22/NEXTHUB/SPRINT	TAG No.	
STOCK No.	PURCHASE ORDER No.		MODEL No. UNREG	CAR LINE VESPA	ENG./TRANS.
DRIVER		CONTACT No.	CHASSIS No.	KILOMETERS 2	PROD. DATE
HOME PHONE		BUSINESS PHONE	CONTACT NAME	CONTRACT EXP KMS	EXP. DATE
CA <input type="checkbox"/>	FC <input type="checkbox"/>	CH <input type="checkbox"/>	SELLING DEALER	DELIVERY KMS	DELIVERY DATE
C/C <input type="checkbox"/>	WAR <input type="checkbox"/>	INT <input type="checkbox"/>	DATE AND TIME PROMISED 21/12/22 09:00pm	TIME RECEIVED 10:36am	QUOTE PRICE
VEHICLE ID RDAM82221NV07917		ENGINE No. 51A5513	AIR PWR TURBO		

Labour  
J# 1 76NAZZZZZ002

PDI CLEAN  
PDI UNIT  
BRAND NEW UNIT  
CHECK AND EVALUATED CONCERN  
PERFORMED PDI INSPECTION

Tech(s) : 48061 3125.00

Totals===== Total - Labour 3125.00

Total Labour. 3125.00  
Total Parts.. 0.00  
Total Other.. 0.00  
Total P.O.L.. 0.00  
Total Misc... 0.00  
VAT 375.00  
Total Invoice 3500.00

*JFH*  
12/22/22

ROAD TESTED		ACKNOWLEDGMENT	
ORDER NO.	SUBLET REPAIRS	RECEIVED above vehicle from AUTOHUB CAR CARE SERVICES (ACCS) in good condition and with all repair work enumerated completed to my satisfaction.	
		All works carried out at these premises are subject to a warranty of _____ days or _____ whichever comes first on all labor and materials.	
		SIGNATURE OF OWNER _____	
		I AGREE TO PAY for all works required for all the above described repair at your retail charge. It is understood that any estimate given is provisional and all repairs are undertaken on a cash basis unless prior arrangements for credit have been approved.	
		I have READ AND ACCEPTED your terms and conditions.	

CHECKLIST

10437

PAGE 1

Client :

Chassis # :

NV079172

Color:

Blue

Make/Model :

Sprint

Engine # :

5185513

Date :

10-22-2022

EMBLEMS

- ( ) Piaggio Emblem ( Front )  
( ) PVG Emblem ( Crankcase )

SIDE MIRROR

- ( ) LH Side View Mirror  
( ) RH Side View Mirror

ELECTRICAL BUTTONS

- ( ) Start Button  
( ) Horn Button  
( ) High&Low Button  
( ) Passing Button ( Optional )  
( ) Left Signal Button  
( ) Right Signal Button  
( ) Cut Off Engine Button ( Optional )  
( ) Start & Stop Button  
( ) ASR Button  
( ) Mode  
( ) Saddle Button  
( ) Toggle Switch

LIGHTS

- ( ) Park Light  
( ) High & Low Beam  
( ) Front Right Signal  
( ) Rear Right Signal  
( ) Front Left Signal  
( ) Rear Left Signal  
( ) Backlight  
( ) Brakelights  
( ) Instrumental Panel Gauges  
( ) Plate Light

FLUID LEVELS

- ( ) Engine Oil  
( ) Gear Oil  
( ) Brake Fluid  
( ) Coolant

SCRATCHES

- ( ) No Scratches  
( ) W/ Scratches  
\*Encircle parts that has/have scratches

COLOR

- ( ) Evenly Painted  
( ) Not Evenly Painted

BATTERY/ HORN

- ( ) Battery  
Brand: Dongfeng Battery Voltage: \_\_\_\_\_  
( ) Horn

TIRES

- ( ) Good Quality  
( ) Bad Quality  
Brand: Pirelli  
Tire Pressure: \_\_\_\_\_ Front \_\_\_\_\_ Rear \_\_\_\_\_

PADS DIAGNOSTIC TOOL

- ( ) PADS Checkup  
Fault : \_\_\_\_\_  
Remarks: \_\_\_\_\_

SADDLE

- ( ) Good Quality  
( ) Bad Quality

KEYS/ MANUAL/ TOOLS

- ( ) Master Key  
( ) Duplicate Key  
( ) Service Manual  
( ) Warranty Booklet  
( ) Set of Screw  
( ) Battery Holder  
( ) Plate Holder  
( ) reflectors ( Optional )  
( ) Under Body Caps ( Optional )  
( ) 1 Set of Tools  
( ) Rear Shock Adjuster  
( ) Screw Driver  
( ) Fuse Removal Tool  
( ) Screw driver ( FLOWER KEY )  
( ) Sparkplug Wrench

Remarks :

Complete accessories and Battery

I understand all the above items as explained to me by the releasing Officer/ Manager. I also agree that any failure on my part to adhere to any of the instructions given that may result in damages on the above mentioned parts will not be covered by warranty.

Inspected by :

W. Abrog

Technician/PDI Personnel

Approved by :

Service Manager

Approved by :

Sales Department



CHECKLIST

10437

PAGE 2

Client :

Chassis # :

NV079172

Color:

Blue

Make/Model :


Sprint

Engine # :

5185513

Date :

10-22-2022



W-Porea

LEGEND

S- Scratched

L- Loose

D- Dented

M- Missing

DD-Damaged

F- Faded

Remarks:

Buff and Wax all Funnell



# AUTOHUB CAR CARE SERVICES (ACCS)

BY: SUPREME AUTOZONE PHILIPPINES INC.  
Sito Buroi Cabrera Road, Brgy. San Juan, Taytay, Rizal  
Tel. No.: (632) 533-8398  
VAT REG. TIN: 236-978-189-00006

## BILLING STATEMENT

No: **06164**

CUSTOMER No. 211806		CUSTOMER NAME AND ADDRESS TIN: OTOITALIA PHILS. INC. #234 ORTIGAS AVENUE NORTH GREENHILLS SAN JUAN CITY MMN 000		ADVISOR Aldrin Padilla 48061 YELLOW		COLOR		TEAM NH GENER	
DOC. DATE 22/12/22		REQ. No. UNREG		STOCK No.		YEAR/MAKE/MODEL 22/NEXTHUB/SPRINT		TAG No.	
PURCHASE ORDER No.		DRIVER		CONTACT No.		MODEL No. UNREG		CAR LINE VESPA	
CHASSIS No.		KILOMETERS		PROD. DATE		EXP. DATE		ENG./TRANS.	
HOME PHONE		BUSINESS PHONE		TERMS		CONTACT NAME		CONTRACT EXP KMS	
VEHICLE ID RDAM82221NV079208		ENGINE No. 5185286		DATE AND TIME PROMISED 21/12/22 09:00pm		TIME RECEIVED 10:37am		QUOTE PRICE	
AIR		PWR		TURBO					

Labour  
JW 1 76NAZZZZ7002

PDI CLEAN  
\* PDI UNIT  
\* BRAND NEW UNIT  
\* CHECK AND EVALUATED CONCERN  
PERFORMED PDI INSPECTION

Tech(s) : 48061 3125.00

Total - Labour 3125.00

Totals=====

Total Labour. 3125.00  
Total Parts.. 0.00  
Total Other.. 0.00  
Total P.O.L.. 0.00  
Total Misc... 0.00  
VAT 375.00

Total Invoice 3500.00

*RJR*  
12/22/22

ROAD TESTED		ACKNOWLEDGMENT		I AGREE TO PAY for all works required for all the above described repair at your retail charge. It is understood that any estimate given is provisional and all repairs are undertaken on a cash basis unless prior arrangements for credit have been approved.	
ORDER NO.	SUBLET REPAIRS	RECEIVED above vehicle from AUTOHUB CAR CARE SERVICES (ACCS) in good condition and with all repair work enumerated completed to my satisfaction.		I have READ AND ACCEPTED your terms and conditions.	
		All works carried out at these premises are subject to a warranty of _____ days or _____ whichever comes first on all labor and materials.			
		SIGNATURE OF OWNER _____			



## CHECKLIST

10432

PAGE 1

Client :

Chassis # : NV079208

Color : Yellow

Make/Model : Sprint

Engine # : 5185286

Date : 10-22-2022

### EMBLEMS

- ( ) Piaggio Emblem ( Front )  
( ) PVG Emblem ( Crankcase )

### SIDE MIRROR

- ( ) LH Side View Mirror  
( ) RH Side View Mirror

### ELECTRICAL BUTTONS

- ( ) Start Button  
( ) Horn Button  
( ) High&Low Button  
( ) Passing Button ( Optional )  
( ) Left Signal Button  
( ) Right Signal Button  
( ) Cut Off Engine Button ( Optional )  
( ) Start & Stop Button  
( ) ASR Button  
( ) Mode  
( ) Saddle Button  
( ) Toggle Switch

### LIGHTS

- ( ) Park Light  
( ) High & Low Beam  
( ) Front Right Signal  
( ) Rear Right Signal  
( ) Front Left Signal  
( ) Rear Left Signal  
( ) Backlight  
( ) Brakelights  
( ) Instrumental Panel Gauges  
( ) Plate Light

### FLUID LEVELS

- ( ) Engine Oil  
( ) Gear Oil  
( ) Brake Fluid  
( ) Coolant

### SCRATCHES

- ( ) No Scratches  
( ) W/ Scratches

\*Encircle parts that has/have scratches

### COLOR

- ( ) Evenly Painted  
( ) Not Evenly Painted

### BATTERY/ HORN

- ( ) Battery  
Brand : Denon Battery Voltage : \_\_\_\_\_  
( ) Horn

### TIRES

- ( ) Good Quality  
( ) Bad Quality

Brand : \_\_\_\_\_  
Tire Pressure : \_\_\_\_\_ Front \_\_\_\_\_ Rear \_\_\_\_\_

### PADS DIAGNOSTIC TOOL

- ( ) PADS Checkup

Fault : \_\_\_\_\_

Remarks : \_\_\_\_\_

### SADDLE

- ( ) Good Quality  
( ) Bad Quality

### KEYS/ MANUAL/ TOOLS

- ( ) Master Key  
( ) Duplicate Key  
( ) Service Manual  
( ) Warranty Booklet  
( ) Set of Screw  
( ) Battery Holder  
( ) Plate Holder  
( ) reflectors ( Optional )  
( ) Under Body Caps ( Optional )  
( ) 1 Set of Tools  
( ) Rear Shock Adjuster  
( ) Screw Driver  
( ) Fuse Removal Tool  
( ) Screw driver ( FLOWER KEY )  
( ) Sparkplug Wrench

Remarks :

Complete accessories and Battery

I understand all the above items as explained to me by the releasing Officer/ Manager. I also agree that any failure on my part to adhere to any of the instructions given that may result in damages on the above mentioned parts will not be covered by warranty.

Inspected by : W. Abrea  
Technician/PDI Personnel

Approved by :

Service Manager

Approved by :

Sales Department



CHECKLIST

10432 PAGE 2

Client :


Chassis # : NV079208

Color: Yellow

Make/Model : Sprint

Engine # : 5185286

Date : 10-22-2022



W. Abreg

LEGEND

S- Scratched	L- Loose
D- Dented	M- Missing
DD-Damaged	F- Faded

Remarks:

Butting all 5 mm / and down





# AUTOHUB CAR CARE SERVICES (ACCS)

BY: SUPREME AUTOZONE PHILIPPINES INC.

Sitio Buroi Cabrera Road, Brgy. San Juan, Taytay, Rizal

Tel. No.: (632) 533-6398

VAT REG. TIN: 236-978-189-00006

## BILLING STATEMENT

No: **06165**

CUSTOMER No. 211806		CUSTOMER NAME AND ADDRESS MOTOITALIA PHILS. INC. #234 ORTIGAS AVENUE NORTH GREENHILLS SAN JUAN CITY MMN 000		ADVISOR Aldrin Padilla		COLOR 48074 YELLOW		TEAM NH GENER	
DOC. DATE 22/12/22		REG. No. UNREG		YEAR/MAKE/MODEL 22/NEXTHUB/SPRINT		TAG No.			
STOCK No.		PURCHASE ORDER No.		MODEL No. UNREG		CAR LINE VESPA		ENG./TRANS.	
DRIVER		CONTACT No.		CHASSIS No.		KILOMETERS		PROD. DATE	
HOME PHONE		BUSINESS PHONE		CONTACT NAME		CONTRACT EXP KMS		EXP DATE	
C/A <input type="checkbox"/>		C/C <input type="checkbox"/>		SELLING DEALER		DELIVERY KMS		DELIVERY DATE	
P/C <input type="checkbox"/>		W/A <input type="checkbox"/>		DATE AND TIME PROMISED		TIME RECEIVED		QUOTE PRICE	
CH <input type="checkbox"/>		INT <input type="checkbox"/>		VEHICLE ID RDAMA2221NU079113		ENGINE No. 51A2124		AIR PWR TURBO	

Labour  
J# 1 76NAZZZZ72002

PDI CLEAN  
\* PDI UNIT  
\* BRAND NEW UNIT  
\* CHECK AND EVALUATED CONCERN  
PERFORMED PDI INSPECTION

Tech(s) : 48061 3125.00

Total - Labour 3125.00

Totals=====

Total Labour..	3125.00
Total Parts..	0.00
Total Other..	0.00
Total P.O.L..	0.00
Total Misc...	0.00
VAT	375.00
Total Invoice	3500.00

*[Signature]*  
2/22/22

ROAD TESTED		ACKNOWLEDGMENT	
ORDER NO.	SUBLET REPAIRS	RECEIVED above vehicle from AUTOHUB CAR CARE SERVICES (ACCS) in good condition and with all repair work enumerated completed to my satisfaction.	
		All works carried out at these premises are subject to a warranty of _____ days or _____ whichever comes first on all labor and materials.	
		SIGNATURE OF OWNER _____	
		I AGREE TO PAY for all works required for all the above described repair at your retail charge. It is understood that any estimate given is provisional and all repairs are undertaken on a cash basis unless prior arrangements for credit have been approved.	
		I have READ AND ACCEPTED your terms and conditions.	

## CHECKLIST

10433

PAGE 1

Client :

Chassis # :

NV079118

Color :

Yellow

Make/Model :

Sprint

Engine # :

5182134

Date :

10-22-2000

### EMBLEMS

- ( ) Piaggio Emblem ( Front )  
( ) PVG Emblem ( Crankcase )

### SIDE MIRROR

- ( ) LH Side View Mirror  
( ) RH Side View Mirror

### ELECTRICAL BUTTONS

- ( ) Start Button  
( ) Horn Button  
( ) High&Low Button  
( ) Passing Button ( Optional )  
( ) Left Signal Button  
( ) Right Signal Button  
( ) Cut Off Engine Button ( Optional )  
( ) Start & Stop Button  
( ) ASR Button  
( ) Mode  
( ) Saddle Button  
( ) Toggle Switch

### LIGHTS

- ( ) Park Light  
( ) High & Low Beam  
( ) Front Right Signal  
( ) Rear Right Signal  
( ) Front Left Signal  
( ) Rear Left Signal  
( ) Backlight  
( ) Brakelights  
( ) Instrumental Panel Gauges  
( ) Plate Light

### FLUID LEVELS

- ( ) Engine Oil  
( ) Gear Oil  
( ) Brake Fluid  
( ) Coolant

### SCRATCHES

- ( ) No Scratches  
( ) W/ Scratches  
\*Encircle parts that has/have scratches

### COLOR

- ( ) Evenly Painted  
( ) Not Evenly Painted

### BATTERY/ HORN

- ( ) Battery  
Brand: Dongfeng Battery Voltage: \_\_\_\_\_  
( ) Horn

### TIRES

- ( ) Good Quality  
( ) Bad Quality  
Brand: Movis  
Tire Pressure: \_\_\_\_\_ Front \_\_\_\_\_ Rear \_\_\_\_\_

### PADS DIAGNOSTIC TOOL

- ( ) PADS Checkup  
Fault : \_\_\_\_\_  
Remarks: \_\_\_\_\_

### SADDLE

- ( ) Good Quality  
( ) Bad Quality

### KEYS/ MANUAL/ TOOLS

- ( ) Master Key  
( ) Duplicate Key  
( ) Service Manual  
( ) Warranty Booklet  
( ) Set of Screw  
( ) Battery Holder  
( ) Plate Holder  
( ) reflectors ( Optional )  
( ) Under Body Caps ( Optional )  
( ) 1 Set of Tools  
( ) Rear Shock Adjuster  
( ) Screw Driver  
( ) Fuse Removal Tool  
( ) Screw driver ( FLOWER KEY )  
( ) Sparkplug Wrench

Remarks :

Complete accesories and Battery

I understand all the above items as explained to me by the releasing Officer/ Manager. I also agree that any failure on my part to adhere to any of the instructions given that may result in damages on the above mentioned parts will not be covered by warranty.

Inspected by :

J. Abreg

Technician/PDI Personnel

Approved by :

Service Manager

Approved by :

Sales Department



CHECKLIST

10433

PAGE 2

Client :

Chassis # :

NV079118

Color :

Yellow

Make/Model :


Sprint

Engine # :

5182124

Date :

10-22-2022



W/ Abran

LEGEND

- |              |            |
|--------------|------------|
| S- Scratched | L- Loose   |
| D- Dented    | M- Missing |
| DD-Damaged   | F- Faded   |

Remarks:

Buffing all Fannel and Wax



# AUTOHUB CAR CARE SERVICES (ACCS)

BY: SUPREME AUTOZONE PHILIPPINES INC.

Sitio Buroi Cabrera Road, Brgy. San Juan, Taytay, Rizal

Tel. No.: (632) 533-8398

VAT REG. TIN: 236-978-189-00006

## BILLING STATEMENT

No: **06166**

CUSTOMER No. 211805	CUSTOMER NAME AND ADDRESS TIN: MOTOITALIA PHILS. INC. #234 ORTIGAS AVENUE NORTH GREENHILLS SAN JUAN CITY MMN 000	ADVISOR Oldrin Padilla	COLOR 48054 BLUE	TEAM NH GENER
DOC. DATE 22/12/22	REG. No. UNREG	YEAR/MAKE/MODEL 22/NEXTHUB/SPRINT	MODEL No. UNREG	ENG./TRANS.
STOCK No.	PURCHASE ORDER No.	CHASSIS No.	KILOMETERS	PROD. DATE
CA <input type="checkbox"/> F/C <input type="checkbox"/> CH <input type="checkbox"/> C/C <input type="checkbox"/> WAR <input type="checkbox"/> INT <input type="checkbox"/>	DRIVER	CONTACT No.	CONTACT NAME	CONTRACT EXP. KMS
HOME PHONE	BUSINESS PHONE	TERMS	SELLING DEALER	DELIVERY KMS
VEHICLE ID	ENGINE No.	DATE AND TIME PROMISED	TIME RECEIVED	QUOTE PRICE
RDAMA22221NU07932	513556A	21/12/22 09:00pm	10:37am	AIR <input type="checkbox"/> PWR <input type="checkbox"/> TURBO <input type="checkbox"/>

Labour  
J# 1 76NAZZZZ7002

PDI CLEAN  
\* PDI UNIT  
\* BRAND NEW UNIT  
\* CHECK AND EVALUATED CONCERN  
PERFORMED PDI INSPECTION

Tech(s) : 48061 3125.00

Total - Labour 3125.00

Totals=====

Total Labour.	3125.00
Total Parts..	0.00
Total Other..	0.00
Total P.O.L..	0.00
Total Misc...	0.00
VAT	375.00
Total Invoice	3500.00

*Signature*  
12/12/22

[ End of Invoice ]

ROAD TESTED		<b>ACKNOWLEDGMENT</b>	
ORDER NO.	SUBLET REPAIRS	RECEIVED above vehicle from AUTOHUB CAR CARE SERVICES (ACCS) in good condition and with all repair work enumerated completed to my satisfaction.	
		All works carried out at these premises are subject to a warranty of _____ days or _____ whichever comes first on all labor and materials.	
		SIGNATURE OF OWNER _____	



## CHECKLIST

10438

PAGE 1

Client :

Chassis # :

NV079394

Color:

Blue

Make/Model :

Sprint

Engine # :

5185568

Date :

10-22-2022

### EMBLEMS

- ( ) Piaggio Emblem ( Front )  
( ) PVG Emblem ( Crankcase )

### SIDE MIRROR

- ( ) LH Side View Mirror  
( ) RH Side View Mirror

### ELECTRICAL BUTTONS

- ( ) Start Button  
( ) Horn Button  
( ) High&Low Button  
( ) Passing Button ( Optional )  
( ) Left Signal Button  
( ) Right Signal Button  
( ) Cut Off Engine Button ( Optional )  
( ) Start & Stop Button  
( ) ASR Button  
( ) Mode  
( ) Saddle Button  
( ) Toggle Switch

### LIGHTS

- ( ) Park Light  
( ) High & Low Beam  
( ) Front Right Signal  
( ) Rear Right Signal  
( ) Front Left Signal  
( ) Rear Left Signal  
( ) Backlight  
( ) Brakelights  
( ) Instrumental Panel Gauges  
( ) Plate Light

### FLUID LEVELS

- ( ) Engine Oil  
( ) Gear Oil  
( ) Brake Fluid  
( ) Coolant

### SCRATCHES

- ( ) No Scratches  
( ) W/ Scratches  
\*Encircle parts that has/have scratches

### COLOR

- ( ) Evenly Painted  
( ) Not Evenly Painted

### BATTERY/ HORN

- ( ) Battery  
Brand: Dynalene Battery Voltage: \_\_\_\_\_  
( ) Horn

### TIRES

- ( ) Good Quality  
( ) Bad Quality  
Brand: Maxxis  
Tire Pressure: \_\_\_\_\_ Front \_\_\_\_\_ Rear \_\_\_\_\_

### PADS DIAGNOSTIC TOOL

- ( ) PADS Checkup  
Fault : \_\_\_\_\_  
Remarks: \_\_\_\_\_

### SADDLE

- ( ) Good Quality  
( ) Bad Quality  
**KEYS/ MANUAL/ TOOLS**  
( ) Master Key  
( ) Duplicate Key  
( ) Service Manual  
( ) Warranty Booklet  
( ) Set of Screw  
( ) Battery Holder  
( ) Plate Holder  
( ) reflectors ( Optional )  
( ) Under Body Caps ( Optional )  
( ) 1 Set of Tools  
( ) Rear Shock Adjuster  
( ) Screw Driver  
( ) Fuse Removal Tool  
( ) Screw driver ( FLOWER KEY )  
( ) Sparkplug Wrench

Remarks :

Complete accessories and Battery

I understand all the above items as explained to me by the releasing Officer/ Manager. I also agree that any failure on my part to adhere to any of the instructions given that may result in damages on the above mentioned parts will not be covered by warranty.

Inspected by :

Technician/PDI Personnel

Approved by :

Service Manager


Approved by :

Sales Department



PAGE 2

10-22-2022



F- Faded

Buffing and Wax all Funnel





# AUTOHUB CAR CARE SERVICES (ACCS)

BY: SUPREME AUTOZONE PHILIPPINES INC.

Sitio Buroi Cabrera Road, Brgy. San Juan, Taytay, Rizal

Tel. No.: (632) 533-6398

VAT REG. TIN: 236-978-189-00006

## BILLING STATEMENT

No: **06167**

CUSTOMER No.	CUSTOMER NAME AND ADDRESS		ADVISOR	COLOR	TEAM
211806	MOTOITALIA PHILS. INC.		Older Padilla	4004 BLACK	NH GENER
DOC. DATE	TIN		YEAR/MAKE/MODEL	TAG No.	
22/12/22	#234 ORTIGAS AVENUE		22/NEXTHUB/SPRINT		
REG. No.	NORTH GREENHILLS		MODEL No.	CAR LINE	ENG./TRANS.
UNREG	SAN JUAN CITY MMN 000		UNREG	VESPA	
STOCK No.	PURCHASE ORDER No.	DRIVER	CHASSIS No.	KILOMETERS	PROD. DATE
		CONTACT No.	CONTACT NAME	CONTRACT EXP KMS	EXP. DATE
CA <input type="checkbox"/>	FC <input type="checkbox"/>	CH <input type="checkbox"/>	HOME PHONE	BUSINESS PHONE	TERMS
OC <input type="checkbox"/>	WAR <input type="checkbox"/>	INT <input type="checkbox"/>	VEHICLE ID	ENGINE No.	DATE AND TIME PROMISED
			BDAM82221N07344	5185420	22/12/22 09:00pm 01:30pm
			DATE AND TIME RECEIVED	QUOTE PRICE	AIR PWR TURBO

Labour J# 1 76NAZZZZZ002

PDI CLEAN  
PDI UNIT  
BRAND NEW UNIT  
CHECK AND EVALUATED CONCERN  
PERFORMED PDI INSPECTION

Tech(s) : 48048 3125.00

Total - Labour 3125.00

Totals=====

Total Labour..	3125.00
Total Parts..	0.00
Total Other..	0.00
Total P.O.L..	0.00
Total Misc..	0.00
VAT	375.00
Total Invoice	3500.00

*Handwritten signature and date: 12/12/22*

[ End of Invoice ]

ROAD TESTED		ACKNOWLEDGMENT	
ORDER NO.	SUBLET REPAIRS	RECEIVED above vehicle from AUTOHUB CAR CARE SERVICES (ACCS) in good condition and with all repair work enumerated completed to my satisfaction.	
		All works carried out at these premises are subject to a warranty of _____ days or _____ whichever comes first on all labor and materials.	
		SIGNATURE OF OWNER _____	

## CHECKLIST

19601 PAGE 1

Client : \_\_\_\_\_ Chassis # : 79940 Color: Black  
 Make/Model : SPRINT Engine # : 5185420 Date : 10-17-76

### EMBLEMS

- ( ) Piaggio Emblem ( Front )  
 ( ) PVG Emblem ( Crankcase )

### SIDE MIRROR

- ( ) LH Side View Mirror  
 ( ) RH Side View Mirror

### ELECTRICAL BUTTONS

- ( ) Start Button  
 ( ) Horn Button  
 ( ) High&Low Button  
 ( ) Passing Button ( Optional )  
 ( ) Left Signal Button  
 ( ) Right Signal Button  
 ( ) Cut Off Engine Button ( Optional )  
 ( ) Start & Stop Button  
 ( ) ASR Button  
 ( ) Mode  
 ( ) Saddle Button  
 ( ) Toggle Switch

### LIGHTS

- ( ) Park Light  
 ( ) High & Low Beam  
 ( ) Front Right Signal  
 ( ) Rear Right Signal  
 ( ) Front Left Signal  
 ( ) Rear Left Signal  
 ( ) Backlight  
 ( ) Brakelights  
 ( ) Instrumental Panel Gauges  
 ( ) Plate Light

### FLUID LEVELS

- ( ) Engine Oil  
 ( ) Gear Oil  
 ( ) Brake Fluid  
 ( ) Coolant

### SCRATCHES

- ( ) No Scratches  
 ( ) W/ Scratches  
 \*Encircle parts that has/have scratches

### COLOR

- ( ) Evenly Painted  
 ( ) Not Evenly Painted

### BATTERY/ HORN

- ( ) Battery  
 Brand: \_\_\_\_\_ Battery Voltage: \_\_\_\_\_  
 ( ) Horn

### TIRES

- ( ) Good Quality  
 ( ) Bad Quality  
 Brand: \_\_\_\_\_  
 Tire Pressure: \_\_\_\_\_ Front \_\_\_\_\_ Rear \_\_\_\_\_

### PADS DIAGNOSTIC TOOL

- ( ) PADS Checkup  
 Fault : \_\_\_\_\_  
 Remarks: \_\_\_\_\_

### SADDLE

- ( ) Good Quality  
 ( ) Bad Quality  
 KEYS/ MANUAL/ TOOLS  
 ( ) Master Key  
 ( ) Duplicate Key  
 ( ) Service Manual  
 ( ) Warranty Booklet  
 ( ) Set of Screw  
 ( ) Battery Holder  
 ( ) Plate Holder  
 ( ) reflectors ( Optional )  
 ( ) Under Body Caps ( Optional )  
 ( ) 1 Set of Tools  
 ( ) Rear Shock Adjuster  
 ( ) Screw Driver  
 ( ) Fuse Removal Tool  
 ( ) Screw driver ( FLOWER KEY )  
 ( ) Sparkplug Wrench

Remarks :

Complete tools

Battery

Oil service

I understand all the above items as explained to me by the releasing Officer/ Manager. I also agree that any failure on my part to adhere to any of the instructions given that may result in damages on the above mentioned parts will not be covered by warranty.

Inspected by :

J. Bayco

Technician/PDI Personnel

Approved by :

Service Manager

Approved by :

Sales Department



CHECKLIST

19601 PAGE 2

Client :


Chassis # : 79940

Color: Black

Make/Model : Sprint

Engine # : 5185420

Date : 10-17-22



LEGEND

S- Scratched      L- Loose  
D- Dented      M- Missing  
DD-Damaged      F- Faded

Remarks:

Complete tools  
Battery  
Accessories



# AUTOHUB CAR CARE SERVICES (ACCS)

BY: SUPREME AUTOZONE PHILIPPINES INC.

Sitio Buroi Cabrera Road, Brgy. San Juan, Taytay, Rizal

Tel. No.: (632) 533-6398

VAT REG. TIN: 236-978-189-00006

## BILLING STATEMENT

No: **06168**

CUSTOMER No. 211806	CUSTOMER NAME AND ADDRESS TIN: MOTOITALIA PHILS. INC.		ADVISOR Aldrin Padilla	COLOR 48014 BLACK	TEAM NH GENER
DOC. DATE 22/12/22	#234 ORTIGAS AVENUE		YEAR/MAKE/MODEL 22/NEXTHUB/SPRINT	TAG No.	
REG. No. UNREG	NORTH GREENHILLS		MODEL No. UNREG	CAR LINE VESPA	ENG./TRANS.
STOCK No.	SAN JUAN CITY MMN 000		CHASSIS No.	KILOMETERS 2	PROD. DATE
PURCHASE ORDER No.	DRIVER	CONTACT No.	CONTACT NAME	CONTRACT EXP. KMS	EXP. DATE
CA <input type="checkbox"/>	FC <input type="checkbox"/>	CH <input type="checkbox"/>	HOME PHONE	BUSINESS PHONE	TERMS
C/C <input type="checkbox"/>	VIAR <input type="checkbox"/>	INT <input type="checkbox"/>	VEHICLE ID RD8M82221NV073468	ENGINE No. 5185158	DATE AND TIME PROMISED 22/12/22 09:00pm
			SELLING DEALER	DELIVERY KMS	DELIVERY DATE
			TIME RECEIVED	QUOTE PRICE	AIR PWR TURBO

Labour  
J# 1 76NAZZZZZ002

PDI CLEAN  
\* PDI UNIT  
\* BRAND NEW UNIT  
\* CHECK AND EVALUATED CONCERN  
PERFORMED PDI INSPECTION

Tech(s) : 48048 3125.00

Total - Labour 3125.00

Totals=====

Total Labour..	3125.00
Total Parts..	0.00
Total Other..	0.00
Total P.O.L..	0.00
Total Misc...	0.00
VAT	375.00
Total Invoice	3500.00

*[Signature]*  
12/22/22

ROAD TESTED		ACKNOWLEDGMENT	
ORDER NO.	SUBLET REPAIRS	RECEIVED above vehicle from AUTOHUB CAR CARE SERVICES (ACCS) in good condition and with all repair work enumerated completed to my satisfaction.	
		All works carried out at these premises are subject to a warranty of _____ days or _____ whichever comes first on all labor and materials.	
		SIGNATURE OF OWNER _____	
		I AGREE TO PAY for all works required for all the above described repair at your retail charge. It is understood that any estimate given is provisional and all repairs are undertaken on a cash basis unless prior arrangements for credit have been approved.	
		I have READ AND ACCEPTED your terms and conditions.	



CHECKLIST

19602

PAGE 1

Client :

Chassis # :

79468

Color:

Black

Make/Model :

SPRINT

Engine # :

518515K

Date :

10-17-26

EMBLEMS

- ( ) Piaggio Emblem ( Front )  
( ) PVG Emblem ( Crankcase )

SIDE MIRROR

- ( ) LH Side View Mirror  
( ) RH Side View Mirror

ELECTRICAL BUTTONS

- ( ) Start Button  
( ) Horn Button  
( ) High&Low Button  
( ) Passing Button ( Optional )  
( ) Left Signal Button  
( ) Right Signal Button  
( ) Cut Off Engine Button ( Optional )  
( ) Start & Stop Button  
( ) ASR Button  
( ) Mode  
( ) Saddle Button  
( ) Toggle Switch

LIGHTS

- ( ) Park Light  
( ) High & Low Beam  
( ) Front Right Signal  
( ) Rear Right Signal  
( ) Front Left Signal  
( ) Rear Left Signal  
( ) Backlight  
( ) Brakelights  
( ) Instrumental Panel Gauges  
( ) Plate Light

FLUID LEVELS

- ( ) Engine Oil  
( ) Gear Oil  
( ) Brake Fluid  
( ) Coolant

SCRATCHES

- ( ) No Scratches  
( ) W/ Scratches

\*Encircle parts that has/have scratches

COLOR

- ( ) Evenly Painted  
( ) Not Evenly Painted

BATTERY/ HORN

- ( ) Battery

Brand: Panasonic Battery Voltage: 12V

- ( ) Horn

TIRES

- ( ) Good Quality  
( ) Bad Quality

Brand: Pirelli

Tire Pressure: 30 Front 30 Rear

PADS DIAGNOSTIC TOOL

- ( ) PADS Checkup

Fault: None

Remarks: Complete check

SADDLE

- ( ) Good Quality  
( ) Bad Quality

KEYS/ MANUAL/ TOOLS

- ( ) Master Key  
( ) Duplicate Key  
( ) Service Manual  
( ) Warranty Booklet  
( ) Set of Screw  
( ) Battery Holder  
( ) Plate Holder  
( ) reflectors ( Optional )  
( ) Under Body Caps ( Optional )  
( ) 1 Set of Tools  
( ) Rear Shock Adjuster  
( ) Screw Driver  
( ) Fuse Removal Tool  
( ) Screw driver ( FLOWER KEY )  
( ) Sparkplug Wrench

Remarks :

Complete check

I understand all the above items as explained to me by the releasing Officer/ Manager. I also agree that any failure on my part to adhere to any of the instructions given that may result in damages on the above mentioned parts will not be covered by warranty.

Inspected by :

Technician/PDI Personnel

Approved by :

Service Manager

Approved by :

Sales Department

CHECKLIST

19602 PAGE 2

Client :

Chassis # :

79468

Color:

Black

Make/Model :


Sprint

Engine # :

5185188

Date :

10-17-22



LEGEND

S- Scratched

L- Loose

D- Dented

M- Missing

DD-Damaged

F- Faded

Remarks:

Complete fuel  
battery  
starter.





# AUTOHUB CAR CARE SERVICES (ACCS)

BY: SUPREME AUTOZONE PHILIPPINES INC.

Sito Burol Cabrera Road, Brgy. San Juan, Taytay, Rizal

Tel. No.: (632) 533-6398

VAT REG. TIN: 236-978-189-00006

## BILLING STATEMENT

No: **06169**

CUSTOMER No. 211806		CUSTOMER NAME AND ADDRESS TIN: OTOITALIA PHILS. INC. #234 ORTIGAS AVENUE NORTH GREENHILLS SAN JUAN CITY MMN 000		ADVISOR Aldrin Padilla 48014 BLACK/		COLOR		TEAM NH GENER	
DOC. DATE 22/12/22		REG. No. UNREG		YEAR/MAKE/MODEL 22/NEXTHUB/SPRINT		MODEL No. UNREG		CARLINE VESPA	
STOCK No.		PURCHASE ORDER No.		CONTACT No.		CONTACT NAME		CONTRACT EXP KMS	
CA <input type="checkbox"/>		FC <input type="checkbox"/>		CH <input type="checkbox"/>		HOME PHONE		BUSINESS PHONE	
C/C <input type="checkbox"/>		WAR <input type="checkbox"/>		INT <input type="checkbox"/>		VEHICLE ID RD6MA2221NV079473		ENGINE No. 5185162	
						DATE AND TIME PROMISED 22/12/22 09:00am		TIME RECEIVED 01:31pm	
						QUOTE PRICE		AIR PWR TURBO	

Labour  
J# 1 76NAZ7722002

PDI CLEAN  
PDI UNIT  
BRAND NEW UNIT  
CHECK AND EVALUATED CONCERN  
PERFORMED PDI INSPECTION

Tech(s) : 48048 3125.00

Totals=====

Total - Labour 3125.00

Total Labour. 3125.00  
Total Parts.. 0.00  
Total Other.. 0.00  
Total P.O.L.. 0.00  
Total Misc... 0.00  
VAT 375.00

Total Invoice 3500.00

*[Signature]*  
12/22/22

ROAD TESTED		ACKNOWLEDGMENT	
ORDER NO.	SUBLET REPAIRS	RECEIVED above vehicle from AUTOHUB CAR CARE SERVICES (ACCS) in good condition and with all repair work enumerated completed to my satisfaction.	
		All works carried out at these premises are subject to a warranty of _____ days or _____ whichever comes first on all labor and materials.	
		SIGNATURE OF OWNER _____	
		I AGREE TO PAY for all works required for all the above described repair at your retail charge. It is understood that any estimate given is provisional and all repairs are undertaken on a cash basis unless prior arrangements for credit have been approved.	
		I have READ AND ACCEPTED your terms and conditions.	

## CHECKLIST

Client :

Chassis # :

79470

Color:

Black

19603

PAGE 1

Make/Model :

Sprint

Engine # :

51X5142

Date :

2016-10-17-12

### EMBLEMS

- ( ) Piaggio Emblem ( Front )  
( ) PVG Emblem ( Crankcase )

### SIDE MIRROR

- ( ) LH Side View Mirror  
( ) RH Side View Mirror

### ELECTRICAL BUTTONS

- ( ) Start Button  
( ) Horn Button  
( ) High & Low Button  
( ) Passing Button ( Optional )  
( ) Left Signal Button  
( ) Right Signal Button  
( ) Cut Off Engine Button ( Optional )  
( ) Start & Stop Button  
( ) ASR Button  
( ) Mode  
( ) Saddle Button  
( ) Toggle Switch

### LIGHTS

- ( ) Park Light  
( ) High & Low Beam  
( ) Front Right Signal  
( ) Rear Right Signal  
( ) Front Left Signal  
( ) Rear Left Signal  
( ) Backlight  
( ) Brakelights  
( ) Instrumental Panel Gauges  
( ) Plate Light

### FLUID LEVELS

- ( ) Engine Oil  
( ) Gear Oil  
( ) Brake Fluid  
( ) Coolant

### SCRATCHES

- ( ) No Scratches  
( ) W/ Scratches  
\*Encircle parts that has/have scratches

### COLOR

- ( ) Evenly Painted  
( ) Not Evenly Painted

### BATTERY/ HORN

- ( ) Battery  
Brand: \_\_\_\_\_ Battery Voltage: \_\_\_\_\_  
( ) Horn

### TIRES

- ( ) Good Quality  
( ) Bad Quality  
Brand: \_\_\_\_\_  
Tire Pressure: \_\_\_\_\_ Front \_\_\_\_\_ Rear \_\_\_\_\_

### PADS DIAGNOSTIC TOOL

- ( ) PADS Checkup  
Fault : \_\_\_\_\_  
Remarks: \_\_\_\_\_

### SADDLE

- ( ) Good Quality  
( ) Bad Quality  
KEYS/ MANUAL/ TOOLS  
( ) Master Key  
( ) Duplicate Key  
( ) Service Manual  
( ) Warranty Booklet  
( ) Set of Screw  
( ) Battery Holder  
( ) Plate Holder  
( ) reflectors ( Optional )  
( ) Under Body Caps ( Optional )  
( ) 1 Set of Tools  
( ) Rear Shock Adjuster  
( ) Screw Driver  
( ) Fuse Removal Tool  
( ) Screw driver ( FLOWER KEY )  
( ) Sparkplug Wrench

Remarks :

Complete task  
Batteries  
Checked

I understand all the above items as explained to me by the releasing Officer/ Manager. I also agree that any failure on my part to adhere to any of the instructions given that may result in damages on the above mentioned parts will not be covered by warranty.

Inspected by :

Technician/PDI Personnel

Approved by :

Service Manager

Approved by :

Sales Department



CHECKLIST

Client :

Chassis # :

79470

Color:

Black

19603

PAGE 2

Make/Model :


SPRINT

Engine # :

5185162

Date :

10-13-2017



LEGEND

S- Scratched

L- Loose

D- Dented

M- Missing

DD-Damaged

F- Faded

Remarks:

Complete fools

Ballon

Attended



# AUTOHUB CAR CARE SERVICES (ACCS)

BY: SUPREME AUTOZONE PHILIPPINES INC.  
Sitio Buroi Cabrera Road, Brgy. San Juan, Taytay, Rizal  
Tel. No.: (632) 533-6398  
VAT REG. TIN: 236-978-189-00006

## BILLING STATEMENT

No: **06170**

Service Invoice Page 1 of 1 Doc # : ATCJ E23197				
CUSTOMER No. 211006	CUSTOMER NAME AND ADDRESS TIN: OTOITALIA PHILS. INC.	ADVISOR Aldrin Padilla	COLOR 48054 BLUE/	TEAM NH GENER
DOC. DATE 22/12/22	#234 ORTIGAS AVENUE	YEAR/MAKE/MODEL 22/NEXTHUB/SPRINT 150		TAG No.
REG. No. UNREG	NORTH GREENHILLS	MODEL No. UNREG	CAR LINE VESPA	ENG./TRANS.
STOCK No.	SAN JUAN CITY MMN 000	CHASSIS No.	KILOMETERS 2	PROD. DATE
PURCHASE ORDER No.	DRIVER	CONTACT No.	CONTACT NAME	CONTRACT EXP. KMS
DA <input type="checkbox"/>	HOME PHONE	BUSINESS PHONE	TERMS	EXR DATE
OC <input type="checkbox"/>	VEHICLE ID RP8MB2221NV07740	ENGINE No. 5179672	SELLING DEALER	DELIVERY KMS
CH <input type="checkbox"/>			DATE AND TIME PROMISED 22/12/22 09:00pm	DELIVERY DATE
WAR <input type="checkbox"/>			TIME RECEIVED 01:32pm	QUOTE PRICE
INT <input type="checkbox"/>				AIR PWR TURBO

Labour  
J# 1 76NAZZZZZ002

PDI CLEAN  
\* PDI UNIT  
\* BRAND NEW UNIT  
\* CHECK AND EVALUATED CONCERN PERFORMED PDI INSPECTION

Tech(s) : 48055 3125.00

Totals=====

Total - Labour 3125.00

Total Labour. 3125.00  
Total Parts.. 0.00  
Total Other.. 0.00  
Total P.O.L.. 0.00  
Total Misc... 0.00  
VAT 375.00

Total Invoice 3500.00

*RJR*  
12/22/22

ROAD TESTED		ACKNOWLEDGMENT	
ORDER NO.	SUBLET REPAIRS	RECEIVED above vehicle from: AUTOHUB CAR CARE SERVICES (ACCS) in good condition and with all repair work enumerated completed to my satisfaction.	I AGREE TO PAY for all works required for all the above described repair at your retail charge. It is understood that any estimate given is provisional and all repairs are undertaken on a cash basis unless prior arrangements for credit have been approved.
		All works carried out at these premises are subject to a warranty of _____ days or _____ whichever comes first on all labor and materials.	I have READ AND ACCEPTED your terms and conditions
		SIGNATURE OF OWNER _____	



## CHECKLIST

Client: VESPA

Chassis #: 077461

19584 PAGE 1

Make/Model: SPRINT 150

Engine #: 5179672

Color: BLK.

Date: 10-13-22

### EMBLEMS

- ( ) Piaggio Emblem ( Front )  
( ) PVG Emblem ( Crankcase )

### SIDE MIRROR

- ( ) LH Side View Mirror  
( ) RH Side View Mirror

### ELECTRICAL BUTTONS

- ( ) Start Button  
( ) Horn Button  
( ) High & Low Button  
( ) Passing Button ( Optional )  
( ) Left Signal Button  
( ) Right Signal Button  
( ) Cut Off Engine Button ( Optional )  
( ) Start & Stop Button  
( ) ASR Button  
( ) Mode  
( ) Saddle Button  
( ) Toggle Switch

### LIGHTS

- ( ) Park Light  
( ) High & Low Beam  
( ) Front Right Signal  
( ) Rear Right Signal  
( ) Front Left Signal  
( ) Rear Left Signal  
( ) Backlight  
( ) Brakelights  
( ) Instrumental Panel Gauges  
( ) Plate Light

### FLUID LEVELS

- ( ) Engine Oil  
( ) Gear Oil  
( ) Brake Fluid  
( ) Coolant

### SCRATCHES

- ( ) No Scratches  
( ) W/ Scratches  
\*Encircle parts that has/have scratches

### COLOR

- ( ) Evenly Painted  
( ) Not Evenly Painted

### BATTERY/ HORN

- ( ) Battery  
Brand: YONGYU Battery Voltage: 12V  
( ) Horn

### TIRES

- ( ) Good Quality  
( ) Bad Quality  
Brand: MAXXIS  
Tire Pressure: Front \_\_\_\_\_ Rear \_\_\_\_\_

### PADS DIAGNOSTIC TOOL

- ( ) PADS Checkup  
Fault: \_\_\_\_\_  
Remarks: \_\_\_\_\_

### SADDLE

- ( ) Good Quality  
( ) Bad Quality  
KEYS/ MANUAL/ TOOLS  
( ) Master Key  
( ) Duplicate Key  
( ) Service Manual  
( ) Warranty Booklet  
( ) Set of Screw  
( ) Battery Holder  
( ) Plate Holder  
( ) reflectors ( Optional )  
( ) Under Body Caps ( Optional )  
( ) 1 Set of Tools  
( ) Rear Shock Adjuster  
( ) Screw Driver  
( ) Fuse Removal Tool  
( ) Screw driver ( FLOWER KEY )  
( ) Sparkplug Wrench

Remarks:

I understand all the above items as explained to me by the releasing Officer/ Manager. I also agree that any failure on my part to adhere to any of the instructions given that may result in damages on the above mentioned parts will not be covered by warranty.

Inspected by: [Signature]  
Technician/PDI Personnel

Approved by: \_\_\_\_\_  
Service Manager

Approved by: \_\_\_\_\_  
Sales Department

CHECKLIST

Client:

VESPA

Chassis #:

077461

Color:

19584

PAGE 2

BLK

Make/Model:


SPRINT 150

Engine #:

5179672

Date:

10-13-22



LEGEND

S- Scratched

D- Dented

DD-Damaged

L- Loose

M- Missing

F- Faded

Remarks:

D. TALAMISAN





# AUTOHUB CAR CARE SERVICES (ACCS)

BY: SUPREME AUTOZONE PHILIPPINES INC.

Sito Buroi Cabrera Road, Brgy. San Juan, Taytay, Rizal

Tel No (632) 533-6398

VAT REG TIN: 236-978-189-00006

28

## BILLING STATEMENT

No: **06171**

CUSTOMER No. 211806		CUSTOMER NAME AND ADDRESS TIN: MOTOITALIA PHILS. INC. #234 ORTIGAS AVENUE NORTH GREENHILLS SAN JUAN CITY, MMN 002		ADVISOR Aldrin Padilla 48054 BLACK/		COLOR		TEAM NH GENER	
DOC. DATE 22/12/22		REG. No. UNREG		YEAR/MAKE/MODEL 22/NEXTHUB/SPRINT 150		TAG No.		ENG./TRANS.	
STOCK No.		PURCHASE ORDER No.		DRIVER		CONTACT No.		CONTACT NAME	
CA <input type="checkbox"/> F/C <input type="checkbox"/> CH <input type="checkbox"/>		HOME PHONE		BUSINESS PHONE		TERMS		SELLING DEALER	
C/C <input type="checkbox"/> WAR <input type="checkbox"/> INT <input type="checkbox"/>		VEHICLE ID RDAMA2221NV077448		ENGINE No. 5179702		DATE AND TIME PROMISED 22/12/22 09:00pm		TIME RECEIVED 01:32pm	
						KILOMETERS		PROD. DATE	
						CONTRACT EXP. KMS		EXP. DATE	
						DELIVERY KMS		DELIVERY DATE	
						QUOTE PRICE		AIR PWR TURBO	

Labour  
J# 1 76NAZ7777002

PDI CLEAN  
\* PDI UNIT  
\* BRAND NEW UNIT  
\* CHECK AND EVALUATED CONCERN  
PERFORMED PDI INSPECTION

Tech(s) : 48055 3125.00

Totals===== Total - Labour 3125.00

Total Labour. 3125.00  
Total Parts.. 0.00  
Total Other.. 0.00  
Total P.O.L.. 0.00  
Total Misc... 0.00  
VAT 375.00  
Total Invoice 3500.00

*RMD*  
*12/22*

ROAD TESTED		ACKNOWLEDGMENT	
ORDER NO.		SUBLET REPAIRS	
		SIGNATURE OF OWNER	

## CHECKLIST

19585

PAGE 1

Client: VESPA

Chassis #: 077413

Color: BLK

Make/Model: SPRINT 150

Engine #: 517 9702

Date: 10-13-22

### EMBLEMS

- ( ) Piaggio Emblem ( Front )  
( ) PVG Emblem ( Crankcase )

### SIDE MIRROR

- ( ) LH Side View Mirror  
( ) RH Side View Mirror

### ELECTRICAL BUTTONS

- ( ) Start Button  
( ) Horn Button  
( ) High&Low Button  
( ) Passing Button ( Optional )  
( ) Left Signal Button  
( ) Right Signal Button  
( ) Cut Off Engine Button ( Optional )  
( ) Start & Stop Button  
( ) ASR Button  
( ) Mode  
( ) Saddle Button  
( ) Toggle Switch

### LIGHTS

- ( ) Park Light  
( ) High & Low Beam  
( ) Front Right Signal  
( ) Rear Right Signal  
( ) Front Left Signal  
( ) Rear Left Signal  
( ) Backlight  
( ) Brakelights  
( ) Instrumental Panel Gauges  
( ) Plate Light

### FLUID LEVELS

- ( ) Engine Oil  
( ) Gear Oil  
( ) Brake Fluid  
( ) Coolant

### SCRATCHES

- ( ) No Scratches  
( ) W/ Scratches  
\*Encircle parts that has/have scratches

### COLOR

- ( ) Evenly Painted  
( ) Not Evenly Painted

### BATTERY/ HORN

- ( ) Battery  
Brand: DOJENAM Battery Voltage: 12V  
( ) Horn

### TIRES

- ( ) Good Quality  
( ) Bad Quality  
Brand: MAXXIS  
Tire Pressure: Front \_\_\_\_\_ Rear \_\_\_\_\_

### PADS DIAGNOSTIC TOOL

- ( ) PADS Checkup  
Fault: \_\_\_\_\_  
Remarks: \_\_\_\_\_

### SADDLE

- ( ) Good Quality  
( ) Bad Quality

### KEYS/ MANUAL/ TOOLS

- ( ) Master Key  
( ) Duplicate Key  
( ) Service Manual  
( ) Warranty Booklet  
( ) Set of Screw  
( ) Battery Holder  
( ) Plate Holder  
( ) reflectors ( Optional )  
( ) Under Body Caps ( Optional )  
( ) 1 Set of Tools  
( ) Rear Shock Adjuster  
( ) Screw Driver  
( ) Fuse Removal Tool  
( ) Screw driver ( FLOWER KEY )  
( ) Sparkplug Wrench

Remarks:

COMPLETE W/ BATTERY

understand all the above items as explained to me by the releasing Officer/ Manager. I also agree that any failure on my part  
o adhere to any of the instructions given that may result in damages on the above mentioned parts will not be covered by warranty.

Inspected by: D. AMISAN  
technician/PDI Personnel

Approved by: \_\_\_\_\_  
Service Manager

Approved by: \_\_\_\_\_  
Sales Department



CHECKLIST

19585 PAGE 2

Client: VESPA


Chassis #: 077443

Color: BLK

Make/Model: SPRINT 150

Engine #: 5179702

Date: 10-13-22



LEGEND

S- Scratched	L- Loose
D- Dented	M- Missing
DD-Damaged	F- Faded

Remarks:


D. TALAMILSON

**BILLING STATEMENT**

No: **06172**

CUSTOMER No.	CUSTOMER NAME AND ADDRESS			ADVISOR	COLOR	TEAM
DOC. DATE	TIN: MOTOITALIA PHILS. INC.			YEAR/MAKE/MODEL	2024 BLACK	TEAM GENES
REG. No.	#234 ORTIGAS AVENUE			MODEL No.	2024/NEXTHUB/SPRINT 150	TAG No.
STOCK No.	NORTH GREENHILLS			CHASSIS No.	UNREG	ENG./TRANS.
PURCHASE ORDER No.	DRIVER	CONTACT No.	CONTACT NAME	CONTRACT EXP. KMS	EXP. DATE	
CA <input type="checkbox"/>	HOME PHONE	BUSINESS PHONE	SELLING DEALER	DELIVERY KMS	DELIVERY DATE	
FC <input type="checkbox"/>	VEHICLE ID	ENGINE No.	DATE AND TIME PROMISED	TIME RECEIVED	QUOTE PRICE	AIR PWR TURBO
CH <input type="checkbox"/>	RDAMA2221NU077457 5179632			22/12/22 09:00pm	01:41pm	
C/C <input type="checkbox"/>						
WAR <input type="checkbox"/>						
INT <input type="checkbox"/>						

Labour  
J# 1 76NAZZZZ002

PDI CLEAN  
\* PDI UNIT  
\* BRAND NEW UNIT  
\* CHECK AND EVALUATED CONCERN  
PERFORMED PDI INSPECTION

Tech(s) : 48055 3125.00

Totals=====

Total - Labour 3125.00

Total Labour. 3125.00  
Total Parts.. 0.00  
Total Other.. 0.00  
Total P.O.L.. 0.00  
Total Misc... 0.00  
VAT 375.00  
Total Invoice 3500.00

*[Signature]*  
12/22/22

ROAD TESTED		<b>ACKNOWLEDGMENT</b>	
ORDER NO.	SUBLET REPAIRS	RECEIVED above vehicle from AUTOHUB CAR CARE SERVICES (ACCS) in good condition and with all repair work enumerated completed to my satisfaction.	I AGREE TO PAY for all works required for all the above described repair at your retail charge. It is understood that any estimate given is provisional and all repairs are undertaken on a cash basis unless prior arrangements for credit have been approved.
		All works carried out at these premises are subject to a warranty of _____ days or _____ whichever comes first on all labor and materials.	I have READ AND ACCEPTED your terms and conditions.
		SIGNATURE OF OWNER _____	





**NEXTHUB AUTO CARE**  
**SUPREME AUTOZONE PHILIPPINES**  
Sitio Buroi Cabrera Road, Brgy. San Juan, Taytay, Rizal  
Tel. No.: (632) 533-6398  
VAT REG. TIN: 236-978-189-00000

**REPAIR ORDER  
& CLAIM STUB**

Repair Order Page 1 of 1 Doc # : EE3199

CUSTOMER No	CUSTOMER NAME/TIN AND ADDRESS	ADVISOR	COLOR	TEAM
DOC. DATE	#234 ORTIGAS AVENUE	YEAR/MAKE/MODEL	480	GENE
REG. No	NORTH GREENHILLS	MODEL No.	HUB/SPRINT 150	TAG No.
STOCK No	SAN JUAN CITY MMN 000	CHASSIS No.	UNREG	ENG./TRANS
PURCHASE ORDER No	DRIVER	CONTACT No	KILOMETERS	PROD. DATE
<input type="checkbox"/> CA <input type="checkbox"/> CC <input type="checkbox"/> RC <input type="checkbox"/> WAR <input type="checkbox"/> CH <input type="checkbox"/> INT	HOME PHONE	CONTACT NAME	CONTRACT EXP. KMS	EXP. DATE
	BUSINESS PHONE	SELLING DEALER	DELIVERY KMS	DELIVERY DATE
	VEHICLE ID	DATE AND TIME PROMISED	TIME RECEIVED	QUOTE PRICE
	ENGINE No			AIR PWR TURBO

Date	RO. No	Kms Adv#	Tech. Type	Operation	Description
21/10/22	S34849	3396 1444	0001	9977BPADNT	BODY AND PAINT

Job	Operation No.	Instructions	
1 J.C	76NAZZZZZ002 0.0	PDI CLEAN	Open
		PDI UNIT	

**Claim Stub**

1. This copy will serve as your claim stub.
2. Please present this claim stub to your service advisor when claiming your vehicle
3. Loss of claim stub should be reported to us immediately, vehicle will only be released after sufficient proof of ownership is established.

[ End of repair order ]

ROAD TESTED		<b>REPAIR AGREEMENT</b> I as the owner or as the authorized representative of the owner hereby authorize the work on the above motor vehicle and the purchasing on any parts required for the work and accept the following conditions: A) Promises made as to the completion of the work are dependent on conditions which may become beyond the control of the repairer and therefore not intended to be binding. B) The repairer is not responsible for the loss of or damage to the motor vehicle, its equipment or contents either by fire or theft except loss or damage caused by gross negligence on the part of the repairer or his employees. C) The repairer or his employees or agents are authorized to drive the motor vehicle on the highway for the purpose of testing and without responsibility on them except loss or damage caused by gross negligence on the part of the repairer or his employees. D) Transactions are on a cash delivery basis, unless prior arrangements are made. E) Parts to be replaced will be returned to the owner, if requested prior to commencement of work.	
ORDER NO	SUBLET REPAIRS	SIGNATURE OF/FOR OWNER	

009024

## CHECKLIST

19583

PAGE 1

Client :

VE3AA

Chassis # :

027457

Color :

BLK.

Make/Model :

SPRINT 150

Engine # :

5179622

Date :

10-13-22

### EMBLEMS

- ( ) Piaggio Emblem ( Front )  
( ) PVG Emblem ( Crankcase )

### SIDE MIRROR

- ( ) LH Side View Mirror  
( ) RH Side View Mirror

### ELECTRICAL BUTTONS

- ( ) Start Button  
( ) Horn Button  
( ) High&Low Button  
( ) Passing Button ( Optional )  
( ) Left Signal Button  
( ) Right Signal Button  
( ) Cut Off Engine Button ( Optional )  
( ) Start & Stop Button  
( ) ASR Button  
( ) Mode  
( ) Saddle Button  
( ) Toggle Switch

### LIGHTS

- ( ) Park Light  
( ) High & Low Beam  
( ) Front Right Signal  
( ) Rear Right Signal  
( ) Front Left Signal  
( ) Rear Left Signal  
( ) Backlight  
( ) Brakelights  
( ) Instrumental Panel Gauges  
( ) Plate Light

### FLUID LEVELS

- ( ) Engine Oil  
( ) Gear Oil  
( ) Brake Fluid  
( ) Coolant

### SCRATCHES

- ( ) No Scratches  
( ) W/ Scratches

\*Encircle parts that has/have scratches

### COLOR

- ( ) Evenly Painted  
( ) Not Evenly Painted

### BATTERY/ HORN

- ( ) Battery  
Brand: PIAGGIO Battery Voltage: 12V  
( ) Horn

### TIRES

- ( ) Good Quality  
( ) Bad Quality  
Brand: MAXXIS  
Tire Pressure: Front \_\_\_\_\_ Rear \_\_\_\_\_

### PADS DIAGNOSTIC TOOL

- ( ) PADS Checkup  
Fault : \_\_\_\_\_  
Remarks: \_\_\_\_\_

### SADDLE

- ( ) Good Quality  
( ) Bad Quality  
KEYS/ MANUAL/ TOOLS  
( ) Master Key  
( ) Duplicate Key  
( ) Service Manual  
( ) Warranty Booklet  
( ) Set of Screw  
( ) Battery Holder  
( ) Plate Holder  
( ) reflectors ( Optional )  
( ) Under Body Caps ( Optional )  
( ) 1 Set of Tools  
( ) Rear Shock Adjuster  
( ) Screw Driver  
( ) Fuse Removal Tool  
( ) Screw driver ( FLOWER KEY )  
( ) Sparkplug Wrench

Remarks :

COMPLETE W/ BATTERY

I understand all the above items as explained to me by the releasing Officer/ Manager. I also agree that any failure on my part to adhere to any of the instructions given that may result in damages on the above mentioned parts will not be covered by warranty.

Inspected by :

Technician/PDI Personnel

Approved by :

Service Manager

Approved by :

Sales Department



CHECKLIST

19583 PAGE 2

Client: VESPA


Chassis #: 077457

Color: BLUE

Make/Model: SPRINT 150

Engine #: 579622

Date: 10-13-22



LEGEND

S- Scratched  
D- Dented  
DD-Damaged  
L- Loose  
M- Missing  
F- Faded

Remarks:

D. TALAMISAN

**BILLING STATEMENT**

No: **06173**

CUSTOMER No.	CUSTOMER NAME AND ADDRESS			ADVISOR	COLOR	TEAM
DOC. DATE	TIN: MOTOITALIA PHILS. INC.			YEAR/MAKE/MODEL	4005 WHITE/	MM GENE
REG. No.	#234 ORTIGAS AVENUE			22/NEXTHUB/SPRINT JUSTINE BIEBER 150		TAG No.
STOCK No.	NORTH GREENHILLS			MODEL No.	UNREG	ENG./TRANS.
PURCHASE ORDER No.	DRIVER	CONTACT No.	CONTACT NAME	KILOMETERS	PROD. DATE	
	HOME PHONE	BUSINESS PHONE	SELLING DEALER	CONTRACT EXR KMS	EXP. DATE	
CA <input type="checkbox"/> F/C <input type="checkbox"/> CH <input type="checkbox"/>	VEHICLE ID	ENGINE No.	DATE AND TIME PROMISED	DELIVERY KMS	DELIVERY DATE	
C/C <input type="checkbox"/> WAR <input type="checkbox"/> INT <input type="checkbox"/>	RDAMA2221NU077195	5178692	22/12/22 09:00pm	01:42pm	QUOTE PRICE	AIR PWR TURBO

Labour  
J# 1 76NAZZZZZ002

Tech(s) : 48055 3125.00

PDI CLEAN

- \* PDI UNIT
- \* BRAND NEW UNIT
- \* CHECK AND EVALUATED CONCERN
- \* PERFORMED PDI INSPECTION

Total - Labour 3125.00

Totals=====

Total Labour..	3125.00
Total Parts..	0.00
Total Other..	0.00
Total P.O.L..	0.00
Total Misc...	0.00
VAT	375.00
<b>Total Invoice</b>	<b>3500.00</b>

*[Signature]*  
12/22/22

[ End of Invoice ]

ROAD TESTED		<b>ACKNOWLEDGMENT</b>	
ORDER NO.	SUBLET REPAIRS	<p>RECEIVED above vehicle from AUTOHUB CAR CARE SERVICES (ACCS) in good condition and with all repair work enumerated completed to my satisfaction.</p> <p>All works carried out at these premises are subject to a warranty of _____ days or _____ whichever comes first on all labor and materials.</p> <p>SIGNATURE OF OWNER _____</p>	
		<p>I AGREE TO PAY for all works required for all the above described repair at your retail charge. It is understood that any estimate given is provisional and all repairs are undertaken on a cash basis unless prior arrangements for credit have been approved.</p> <p>I have READ AND ACCEPTED your terms and conditions.</p>	



## CHECKLIST

17105

PAGE 1

Client : VESPA

Chassis # : NVD 77195

Color : WHITE

Make/Model : SPRINT JUSO 110 BIEBER 150

Engine # : 5178692

Date : 9/17/22

### EMBLEMS

- ( ) Piaggio Emblem ( Front )  
( ) PVG Emblem ( Crankcase )

### SIDE MIRROR

- ( ) LH Side View Mirror  
( ) RH Side View Mirror

### ELECTRICAL BUTTONS

- ( ) Start Button  
( ) Horn Button  
( ) High&Low Button  
( ) Passing Button ( Optional )  
( ) Left Signal Button  
( ) Right Signal Button  
( ) Cut Off Engine Button ( Optional )  
( ) Start & Stop Button  
( ) ASR Button  
( ) Mode  
( ) Saddle Button  
( ) Toggle Switch

### LIGHTS

- ( ) Park Light  
( ) High & Low Beam  
( ) Front Right Signal  
( ) Rear Right Signal  
( ) Front Left Signal  
( ) Rear Left Signal  
( ) Backlight  
( ) Brakelights  
( ) Instrumental Panel Gauges  
( ) Plate Light

### FLUID LEVELS

- ( ) Engine Oil  
( ) Gear Oil  
( ) Brake Fluid  
( ) Coolant

### SCRATCHES

- ( ) No Scratches  
( ) W/ Scratch

\*Encircle parts that has/have scratches

### CC

- ( ) Evenly Painted  
( ) Not Evenly Painted

### BATTERY/ HORN

- ( ) Battery  
Brand : AMAL Battery Voltage : 12V  
( ) Horn

### TIRES

- ( ) Good Quality  
( ) Bad Quality

Brand : CST

Tire Pressure : Front \_\_\_\_\_ Rear \_\_\_\_\_

### PADS DIAGNOSTIC TOOL

- ( ) PADS Checkup

Fault : \_\_\_\_\_

Remarks : \_\_\_\_\_

### SADDLE

- ( ) Good Quality  
( ) Bad Quality

### KEYS/ MANUAL/ TOOLS

- ( ) Master Key  
( ) Duplicate Key  
( ) Service Manual  
( ) Warranty Booklet  
( ) Set of Screw  
( ) Battery Holder  
( ) Plate Holder  
( ) reflectors ( Optional )  
( ) Under Body Caps ( Optional )  
( ) 1 Set of Tools  
( ) Rear Shock Adjuster  
( ) Screw Driver  
( ) Fuse Removal Tool  
( ) Screw driver ( FLOWER KEY )  
( ) Sparkplug Wrench

Remarks :

I understand all the above items as explained to me by the releasing Officer/ Manager. I also agree that any failure on my part or adhere to any of the instructions given that may result in damages on the above mentioned parts will not be covered by warranty.

Inspected by :  
Technician/ PD Personnel

Approved by :  
Service Manager

Approved by :  
Sales Department

CHECKLIST

17105 PAGE 2

Client: VESPA


Chassis #: NV077195

Color: WHITE

Make/Model: SPRINT JUSTIN BIEBER 150

Engine #: 5178692

Date: 9/17/22



LEGEND

S- Scratched	L- Loose
D- Dented	M- Missing
DD-Damaged	F- Faded

Remarks:

COMPLETE ACCESSORIES W/ ENTRY

D. TH. AMISAN



**BILLING STATEMENT**

No: **06174**

CUSTOMER No. 211806	CUSTOMER NAME AND ADDRESS MOTOITALIA PHILS. INC.		ADVISOR Aldrin Padilla	COLOR 4A054 WHITE	TEAM NH GENER
DOC. DATE 22/12/22	REG. No. UNREG		YEAR/MAKE/MODEL 22/NEXTHUB/SPRINT JUSTIN BIEBER 150	TAG No.	
STOCK No.	PURCHASE ORDER No.		MODEL No. UNREG	CAR LINE VESPA	ENG./TRANS.
DRIVER		CONTACT No.	CHASSIS No.	KILOMETERS 2	PROD. DATE
HOME PHONE		BUSINESS PHONE	CONTACT NAME	CONTRACT EXP. KMS	EXP. DATE
CA <input type="checkbox"/>	FC <input type="checkbox"/>	CH <input type="checkbox"/>	SELLING DEALER	DELIVERY KMS	DELIVERY DATE
C/C <input type="checkbox"/>	WAR <input type="checkbox"/>	INT <input type="checkbox"/>	VEHICLE ID BPAMA2221NU077145	ENGINE No. 5178731	DATE AND TIME PROMISED 22/12/22 09:00pm
			TIME RECEIVED 01:43pm	QUOTE PRICE	AIR PWR TURBO

Labour  
J# 1 76NAZZZZZ002

PDI CLEAN

- \* PDI UNIT
- \* BRAND NEW UNIT
- \* CHECK AND EVALUATED CONCERN PERFORMED PDI INSPECTION

Tech(s) : 48055

3125.00

Total - Labour 3125.00

Totals=====

Total Labour. 3125.00  
Total Parts.. 0.00  
Total Other.. 0.00  
Total P.O.L.. 0.00  
Total Misc... 0.00  
VAT 375.00

Total Invoice 3500.00

*[Signature]*  
12/22/22

[ End of Invoice ]

ROAD TESTED		ACKNOWLEDGMENT	
ORDER NO.	SUBLET REPAIRS	RECEIVED above vehicle from AUTOHUB CAR CARE SERVICES (ACCS) in good condition and with all repair work enumerated completed to my satisfaction.	
		All works carried out at these premises are subject to a warranty of _____ days or _____ whichever comes first on all labor and materials.	
		SIGNATURE OF OWNER	

I AGREE TO PAY for all works required for all the above described repair at your retail charge. It is understood that any estimate given is provisional and all repairs are undertaken on a cash basis unless prior arrangements for credit have been approved.

I have READ AND ACCEPTED your terms and conditions.

## CHECKLIST

17103

PAGE 1

Client: VESPA

Chassis #: NV077146

Color: WHITE

Make/Model: SPRINT JUSTIN DIEBER 150

Engine #: 5178731

Date: 9/16/22

### EMBLEMS

- ( ) Piaggio Emblem ( Front )  
( ) PVG Emblem ( Crankcase )

### SIDE MIRROR

- ( ) LH Side View Mirror  
( ) RH Side View Mirror

### ELECTRICAL BUTTONS

- ( ) Start Button  
( ) Horn Button  
( ) High&Low Button  
( ) Passing-Button ( Optional )  
( ) Left Signal Button  
( ) Right Signal Button  
( ) Cut Off Engine Button ( Optional )  
( ) Start & Stop Button  
( ) ASR Button  
( ) Mode  
( ) Saddle Button  
( ) Toggle Switch

### LIGHTS

- ( ) Park Light  
( ) High & Low Beam  
( ) Front Right Signal  
( ) Rear Right Signal  
( ) Front Left Signal  
( ) Rear Left Signal  
( ) Backlight  
( ) Brakelights  
( ) Instrumental Panel Gauges  
( ) Plate Light

### FLUID LEVELS

- ( ) Engine Oil  
( ) Gear Oil  
( ) Brake Fluid  
( ) Coolant

### SCRATCHES

- ( ) No Scratches  
( ) W/ Scratches  
\*Encircle parts that has/have scratches

### COLOR

- ( ) Evenly Painted  
( ) Not Evenly Painted

### BATTERY/ HORN

- ( ) Battery  
Brand: DECEA Battery Voltage: 12V  
( ) Horn

### TIRES

- ( ) Good Quality  
( ) Bad Quality  
Brand: \_\_\_\_\_  
Tire Pressure: \_\_\_\_\_ Front \_\_\_\_\_ Rear \_\_\_\_\_

### PADS DIAGNOSTIC TOOL

- ( ) PADS Checkup  
Fault: \_\_\_\_\_  
Remarks: \_\_\_\_\_

### SADDLE

- ( ) Good Quality  
( ) Bad Quality  
KEYS/ MANUAL/ TOOLS  
( ) Master Key  
( ) Duplicate Key  
( ) Service Manual  
( ) Warranty Booklet  
( ) Set of Screw  
( ) Battery Holder  
( ) Plate Holder  
( ) reflectors ( Optional )  
( ) Under Body Caps ( Optional )  
( ) 1 Set of Tools  
( ) Rear Shock Adjuster  
( ) Screw Driver  
( ) Fuse Removal Tool  
( ) Screw driver ( FLOWER KEY )  
( ) Sparkplug Wrench

Remarks:

COMPLETE ACCESSORIES W/ BATTERY

I understand all the above items as explained to me by the releasing Officer/ Manager. I also agree that any failure on my part to adhere to any of the instructions given that may result in damages on the above mentioned parts will not be covered by warranty.

Inspected by:

Technician/PDI Personnel

Approved by:

Service Manager

Approved by:

Sales Department



CHECKLIST

17103 PAGE 2

Client: VESPA


Chassis #: NV077146

Color: WHITE

Make/Model: SPRINT JUSTIN BIEBER 150

Engine #: 5178731

Date: 9/16/22



LEGEND

S- Scratched	L- Loose
D- Dented	M- Missing
DD- Damaged	F- Faded

Remarks:

COMPLETE ACCESSORIES W/ BATTERY

D. TALAMISAN



# AUTOHUB CAR CARE SERVICES (ACCS)

BY: SUPREME AUTOZONE PHILIPPINES INC.  
Sitio Buroi Cabrera Road, Brgy. San Juan, Taytay, Rizal  
Tel. No : (632) 533-6398  
VAT REG. TIN: 236-978-189-00006

## BILLING STATEMENT

No: **06175**

CUSTOMER No. 211806		CUSTOMER NAME AND ADDRESS TIN: MOTOITALIA PHILS. INC. #234 ORTIGAS AVENUE NORTH GREENHILLS SAN JUAN CITY MMN 000		ADVISOR Aldrin Padilla 48054 BRONZE/		COLOR		TEAM NH GENER	
DOC. DATE 22/12/22		REG. No. UNREG		STOCK No.		YEAR/MAKE/MODEL 22/NEXTHUB/SPRINT TFI		TAG No.	
PURCHASE ORDER No.		DRIVER		CONTACT No.		MODEL No. UNREG		CAR LINE VESPA	
CHASSIS No.		KILOMETERS		PROD. DATE		EXP. DATE		ENG./TRANS.	
CONTACT NAME		CONTRACT EXP. KMS		DELIVERY KMS		DELIVERY DATE		QUOTE PRICE	
SELLING DEALER		DATE AND TIME PROMISED		TIME RECEIVED		AIR		PWR	
VEHICLE ID RD8MA2221NV07398		ENGINE No. 5185646		DATE AND TIME RECEIVED 22/12/22 09:00am		TIME RECEIVED 01:45pm		TURBO	

Labour		Tech(s) : 48051		3125.00	
J# 1 76NAZZZZZ002		PDI CLEAN			
* PDI UNIT					
* BRAND NEW UNIT					
* CHECK AND EVALUATED CONCERN					
PERFORMED PDI INSPECTION					
Total - Labour				3125.00	
Totals					
Total Labour.				3125.00	
Total Parts..				0.00	
Total Other..				0.00	
Total P.O.L..				0.00	
Total Misc...				0.00	
VAT				375.00	
Total Invoice				3500.00	

*[Signature]*  
12/22/22

ROAD TESTED		ACKNOWLEDGMENT	
ORDER NO.		SUBLET REPAIRS	
RECEIVED above vehicle from AUTOHUB CAR CARE SERVICES (ACCS) in good condition and with all repair work enumerated completed to my satisfaction.		I AGREE TO PAY for all works required for all the above described repair at your retail charge. It is understood that any estimate given is provisional and all repairs are undertaken on a cash basis unless prior arrangements for credit have been approved.	
All works carried out at these premises are subject to a warranty of _____ days or _____ whichever comes first on all labor and materials.		I have READ AND ACCEPTED your terms and conditions.	
SIGNATURE OF OWNER			



CHECKLIST

17330 PAGE 1

Client :

Chassis # :

Color :

Make/Model :

Engine # :

Date :

EMBLEMS

- ( ) Piaggio Emblem ( Front )  
( ) PVG Emblem ( Crankcase )

SIDE MIRROR

- ( ) LH Side View Mirror  
( ) RH Side View Mirror

ELECTRICAL BUTTONS

- ( ) Start Button  
( ) Horn Button  
( ) High&Low Button  
( ) Passing Button ( Optional )  
( ) Left Signal Button  
( ) Right Signal Button  
( ) Cut Off Engine Button ( Optional )  
( ) Start & Stop Button  
( ) ASR Button  
( ) Mode  
( ) Saddle Button  
( ) Toggle Switch

LIGHTS

- ( ) Park Light  
( ) High & Low Beam  
( ) Front Right Signal  
( ) Rear Right Signal  
( ) Front Left Signal  
( ) Rear Left Signal  
( ) Backlight  
( ) Brakelights  
( ) Instrumental Panel Gauges  
( ) Plate Light

FLUID LEVELS

- ( ) Engine Oil  
( ) Gear Oil  
( ) Brake Fluid  
( ) Coolant

SCRATCHES

- ( ) No Scratches  
( ) W/ Scratches  
\*Encircle parts that has/have scratches

COLOR

- ( ) Evenly Painted  
( ) Not Evenly Painted

BATTERY/ HORN

- ( ) Battery  
Brand: \_\_\_\_\_ Battery Voltage: \_\_\_\_\_  
( ) Horn

TIRES

- ( ) Good Quality  
( ) Bad Quality  
Brand: \_\_\_\_\_  
Tire Pressure: \_\_\_\_\_ Front \_\_\_\_\_ Rear \_\_\_\_\_

PADS DIAGNOSTIC TOOL

- ( ) PADS Checkup  
Fault: \_\_\_\_\_  
Remarks: \_\_\_\_\_

SADDLE

- ( ) Good Quality  
( ) Bad Quality  
KEYS/ MANUAL/ TOOLS  
( ) Master Key  
( ) Duplicate Key  
( ) Service Manual  
( ) Warranty Booklet  
( ) Set of Screw  
( ) Battery Holder  
( ) Plate Holder  
( ) reflectors ( Optional )  
( ) Under Body Caps ( Optional )  
( ) 1 Set of Tools  
( ) Rear Shock Adjuster  
( ) Screw Driver  
( ) Fuse Removal Tool  
( ) Screw driver ( FLOWER KEY )  
( ) Sparkplug Wrench

Remarks :

I understand all the above items as explained to me by the releasing Officer/ Manager. I also agree that any failure on my part to adhere to any of the instructions given that may result in damages on the above mentioned parts will not be covered by warranty.

Inspected by :

Approved by :

Approved by :

Technician/PDI Personnel


Service Manager

Sales Department

CHECKLIST

17330 PAGE 2

Client: Vespa Chassis #: NV1079980 Color: Bronze  
Make/Model: Sprint TFT Engine #: 5185646 Date: 10-27-22



LEGEND

S- Scratched	L- Loose
D- Dented	M- Missing
DD-Damaged	F- Faded

Remarks:






## CHECKLIST

17332 PAGE 1

Client: Vespa

Chassis #: AV080012

Color: Black

Make/Model: Spring TFT

Engine #: 5125671

Date: 10-27-22

### EMBLEMS

- ( ) Piaggio Emblem ( Front )  
( ) PVG Emblem ( Crankcase )

### SIDE MIRROR

- ( ) LH Side View Mirror  
( ) RH Side View Mirror

### ELECTRICAL BUTTONS

- ( ) Start Button  
( ) Horn Button  
( ) High&Low Button  
( ) Passing Button ( Optional )  
( ) Left Signal Button  
( ) Right Signal Button  
( ) Cut Off Engine Button ( Optional )  
( ) Start & Stop Button  
( ) ASR Button  
( ) Mode  
( ) Saddle Button  
( ) Toggle Switch

### LIGHTS

- ( ) Park Light  
( ) High & Low Beam  
( ) Front Right Signal  
( ) Rear Right Signal  
( ) Front Left Signal  
( ) Rear Left Signal  
( ) Backlight  
( ) Brakelights  
( ) Instrumental Panel Gauges  
( ) Plate Light

### FLUID LEVELS

- ( ) Engine Oil  
( ) Gear Oil  
( ) Brake Fluid  
( ) Coolant

### SCRATCHES

- ( ) No Scratches  
( ) W/ Scratches  
\*Encircle parts that has/have scratches

### COLOR

- ( ) Evenly Painted  
( ) Not Evenly Painted

### BATTERY/ HORN

- ( ) Battery  
Brand: \_\_\_\_\_ Battery Voltage: \_\_\_\_\_  
( ) Horn

### TIRES

- ( ) Good Quality  
( ) Bad Quality  
Brand: \_\_\_\_\_  
Tire Pressure: \_\_\_\_\_ Front \_\_\_\_\_ Rear \_\_\_\_\_

### PADS DIAGNOSTIC TOOL

- ( ) PADS Checkup  
Fault : \_\_\_\_\_  
Remarks: \_\_\_\_\_

### SADDLE

- ( ) Good Quality  
( ) Bad Quality  
**KEYS/ MANUAL/ TOOLS**  
( ) Master Key  
( ) Duplicate Key  
( ) Service Manual  
( ) Warranty Booklet  
( ) Set of Screw  
( ) Battery Holder  
( ) Plate Holder  
( ) reflectors ( Optional )  
( ) Under Body Caps ( Optional )  
( ) 1 Set of Tools  
( ) Rear Shock Adjuster  
( ) Screw Driver  
( ) Fuse Removal Tool  
( ) Screw driver ( FLOWER KEY )  
( ) Sparkplug Wrench

Remarks :

Complete Acc. tools w/ battery

I understand all the above items as explained to me by the releasing Officer/ Manager. I also agree that any failure on my part to adhere to any of the instructions given that may result in damages on the above mentioned parts will not be covered by warranty.

Inspected by:

Approved by :

Approved by :

Technician/PDI Personnel

Service Manager

Sales Department



CHECKLIST

17332 PAGE 2

Client:

Vespa

Chassis #:

NV080012

Color:

Black

Make/Model:


Sprint TPT

Engine #:

5185671

Date:

10-27-21



LEGEND

S- Scratched

L- Loose

D- Dented

M- Missing

DD-Damaged

F- Faded

Remarks:




# AUTOHUB CAR CARE SERVICES (ACCS)

BY: SUPREME AUTOZONE PHILIPPINES INC.

Sitio Buroi Cabrera Road, Brgy. San Juan, Taytay, Rizal

Tel. No.: (832) 533-8398

VAT REG. TIN: 236-978-189-00006

## BILLING STATEMENT

No: **06177**

CUSTOMER No.	CUSTOMER NAME AND ADDRESS		ADVISOR	COLOR	TEAM
DOC. DATE	TIN: POTOITALIA PHILS. INC.		YEAR/MAKE/MODEL	2024 PRONZE/	NEW GENER
REG. No.	#234 ORTIGAS AVENUE		MODEL No.	22/NEXTHUB/SPRINT TET	TAG No.
STOCK No.	NORTH GREENHILLS		CHASSIS No.	UNREG	ENG./TRANS.
PURCHASE ORDER No.	DRIVER	CONTACT No.	CONTACT NAME	CONTRACT EXP KMS	EXP. DATE
CA <input type="checkbox"/>	FC <input type="checkbox"/>	CH <input type="checkbox"/>	HOME PHONE	BUSINESS PHONE	TERMS
C/C <input type="checkbox"/>	WAR <input type="checkbox"/>	INT <input type="checkbox"/>	VEHICLE ID	ENGINE No.	DATE AND TIME PROMISED
RDAMA2221NW079975 51A5600			22/12/22 - 09:00pm 01:48pm		

Labour  
J# 1 76NAZZZZZ002

PDI CLEAN  
\* PDI UNIT  
\* BRAND NEW UNIT  
\* CHECK AND EVALUATED CONCERN  
PERFORMED PDI INSPECTION

Tech(s) : 4805P 3125.00

Total - Labour 3125.00

Totals=====

Total Labour.	3125.00
Total Parts..	0.00
Total Other..	0.00
Total P.O.L..	0.00
Total Misc...	0.00
VAT	375.00
Total Invoice	3500.00

*[Signature]*  
12/22/22

ROAD TESTED		<b>ACKNOWLEDGMENT</b>	
ORDER NO.	SUBLET REPAIRS	RECEIVED above vehicle from AUTOHUB CAR CARE SERVICES (ACCS) in good condition and with all repair work enumerated completed to my satisfaction.	
		All works carried out at these premises are subject to a warranty of _____ days or _____ whichever comes first on all labor and materials.	
		SIGNATURE OF OWNER _____	



## CHECKLIST

17331

PAGE 1

Client :

Chassis # :

Color :

Make/Model :

Engine # :

Date :

### EMBLEMS

- ( ) Piaggio Emblem ( Front )  
( ) PVG Emblem ( Crankcase )

### SIDE MIRROR

- ( ) LH Side View Mirror  
( ) RH Side View Mirror

### ELECTRICAL BUTTONS

- ( ) Start Button  
( ) Horn Button  
( ) High&Low Button  
( ) Passing Button ( Optional )  
( ) Left Signal Button  
( ) Right Signal Button  
( ) Cut Off Engine Button ( Optional )  
( ) Start & Stop Button  
( ) ASR Button  
( ) Mode  
( ) Saddle Button  
( ) Toggle Switch

### LIGHTS

- ( ) Park Light  
( ) High & Low Beam  
( ) Front Right Signal  
( ) Rear Right Signal  
( ) Front Left Signal  
( ) Rear Left Signal  
( ) Backlight  
( ) Brakelights  
( ) Instrumental Panel Gauges  
( ) Plate Light

### FLUID LEVELS

- ( ) Engine Oil  
( ) Gear Oil  
( ) Brake Fluid  
( ) Coolant

### SCRATCHES

- ( ) No Scratches  
( ) W/ Scratches  
\*Encircle parts that has/have scratches

### COLOR

- ( ) Evenly Painted  
( ) Not Evenly Painted

### BATTERY/ HORN

- ( ) Battery  
Brand: \_\_\_\_\_ Battery Voltage: \_\_\_\_\_  
( ) Horn

### TIRES

- ( ) Good Quality  
( ) Bad Quality  
Brand: \_\_\_\_\_  
Tire Pressure: \_\_\_\_\_ Front \_\_\_\_\_ Rear \_\_\_\_\_

### PADS DIAGNOSTIC TOOL

- ( ) PADS Checkup  
Fault : \_\_\_\_\_  
Remarks: \_\_\_\_\_

### SADDLE

- ( ) Good Quality  
( ) Bad Quality  
KEYS/ MANUAL/ TOOLS  
( ) Master Key  
( ) Duplicate Key  
( ) Service Manual  
( ) Warranty Booklet  
( ) Set of Screw  
( ) Battery Holder  
( ) Plate Holder  
( ) reflectors ( Optional )  
( ) Under Body Caps ( Optional )  
( ) 1 Set of Tools  
( ) Rear Shock Adjuster  
( ) Screw Driver  
( ) Fuse Removal Tool  
( ) Screw driver (FLOWER KEY)  
( ) Sparkplug Wrench

Remarks :

I understand all the above items as explained to me by the releasing Officer/ Manager. I also agree that any failure on my part to adhere to any of the instructions given that may result in damages on the above mentioned parts will not be covered by warranty.

Inspected by :  
Technician/PDI Personnel

Approved by :  
Service Manager

Approved by :  
Sales Department

CHECKLIST

17331 PAGE 2

Client :

Vespa

Chassis # :

NV0799179

Color:

Brown

Make/Model :


Sprint TFE

Engine # :

5125600

Date :

10-27-22



LEGEND

S- Scratched

D- Dented

DD-Damaged

L- Loose

M- Missing

F- Faded

Remarks:






# AUTOHUB CAR CARE SERVICES (ACCS)

BY: SUPREME AUTOZONE PHILIPPINES INC.

Sitio Buroi Cabrera Road, Brgy. San Juan, Taytay, Rizal

Tel. No.: (632) 533-6398

VAT REG. TIN: 236-978-189-00006

## BILLING STATEMENT

No: **06178**

CUSTOMER No. 311826	CUSTOMER NAME AND ADDRESS TIN: MOTOITALIA PHILS. INC.		ADVISOR Aldrin Padilla	COLOR WHITE	TEAM M. GENE
DOC. DATE 22/12/22	#234 ORTIGAS AVENUE		YEAR/MAKE/MODEL 22/NEXTHUB/SPRING JUSTIN B	TAG No.	
REG. No. UNREG	NORTH GREENHILLS		MODEL No. UNREG	CAR LINE VESPA	ENG./TRANS.
STOCK No.	SAN JUAN CITY MMN 000		CHASSIS No.	KILOMETERS	PROD. DATE
PURCHASE ORDER No.	DRIVER	CONTACT No.	CONTACT NAME	CONTRACT EXR KMS	EXR DATE
CA <input type="checkbox"/>	P/C <input type="checkbox"/>	CH <input type="checkbox"/>	HOME PHONE	BUSINESS PHONE	TERMS
C/C <input type="checkbox"/>	WAR <input type="checkbox"/>	INT <input type="checkbox"/>	VEHICLE ID RP8M62221NV07719	ENGINE No. 5178685	DATE AND TIME PROMISED 22/12/22 09:00pm
			SELLING DEALER	DELIVERY KMS	DELIVERY DATE
			TIME RECEIVED 01:51pm	QUOTE PRICE	AIR PWR TURBO

Labour  
J# 1 76NAZZZZ002

PD1 CLEAN  
\* PD1 UNIT  
\* BRAND NEW UNIT  
\* CHECK AND EVALUATED CONCERN  
PERFORMED PD1 INSPECTION

Tech(s) : 48051 3125.00

Total - Labour 3125.00

Totals=====

Total Labour.	3125.00
Total Parts..	0.00
Total Other..	0.00
Total P.O.L..	0.00
Total Misc...	0.00
VAT	375.00
Total Invoice	3500.00

*[Signature]*  
12/24/22

[ End of Invoice ]

ROAD TESTED		<b>ACKNOWLEDGMENT</b>	
ORDER NO.	SUBLET REPAIRS	RECEIVED above vehicle from AUTOHUB CAR CARE SERVICES (ACCS) in good condition and with all repair work enumerated completed to my satisfaction.	
		All works carried out at these premises are subject to a warranty of _____ days or _____ whichever comes first on all labor and materials.	
		SIGNATURE OF OWNER _____	
		I AGREE TO PAY for all works required for all the above described repair at your retail charge. It is understood that any estimate given is provisional and all repairs are undertaken on a cash basis unless prior arrangements for credit have been approved.	
		I have READ AND ACCEPTED your terms and conditions.	

CHECKLIST

Client: Vespa Chassis #: NV077192 Color: White 17099 PAGE 1  
Make/Model: Sprint 125 B Engine #: 5178683 Date: 9-22-22

EMBLEMS

- ☐ Piaggio Emblem ( Front )  
☐ PVG Emblem ( Crankcase )

SIDE MIRROR

- ☐ LH Side View Mirror  
☐ RH Side View Mirror

ELECTRICAL BUTTONS

- ☐ Start Button  
☐ Horn Button  
☐ High&Low Button  
☐ Passing Button ( Optional )  
☐ Left Signal Button  
☐ Right Signal Button  
☐ Cut Off Engine Button ( Optional )  
☐ Start & Stop Button  
☐ ASR Button  
☐ Mode  
☐ Saddle Button  
☐ Toggle Switch

LIGHTS

- ☐ Park Light  
☐ High & Low Beam  
☐ Front Right Signal  
☐ Rear Right Signal  
☐ Front Left Signal  
☐ Rear Left Signal  
☐ Backlight  
☐ Brakelights  
☐ Instrumental Panel Gauges  
☐ Plate Light

FLUID LEVELS

- ☐ Engine Oil  
☐ Gear Oil  
☐ Brake Fluid  
☐ Coolant

SCRATCHES

- ☐ No Scratches  
☐ W/ Scratches  
\*Encircle parts that has/have scratches

COLOR

- ☐ Evenly Painted  
☐ Not Evenly Painted

BATTERY/HORN

- ☐ Battery  
Brand: \_\_\_\_\_ Battery Voltage: \_\_\_\_\_  
☐ Horn

TIRES

- ☐ Good Quality  
☐ Bad Quality  
Brand: \_\_\_\_\_  
Tire Pressure: \_\_\_\_\_ Front \_\_\_\_\_ Rear \_\_\_\_\_

PADS DIAGNOSTIC TOOL

- ☐ PADS Checkup  
Fault: \_\_\_\_\_  
Remarks: \_\_\_\_\_

SADDLE

- ☐ Good Quality  
☐ Bad Quality  
KEYS/ MANUAL/ TOOLS  
☐ Master Key  
☐ Duplicate Key  
☐ Service Manual  
☐ Warranty Booklet  
☐ Set of Screw  
☐ Battery Holder  
☐ Plate Holder  
☐ reflectors ( Optional )  
☐ Under Body Caps ( Optional )  
☐ 1 Set of Tools  
☐ Rear Shock Adjuster  
☐ Screw Driver  
☐ Fuse Removal Tool  
☐ Screw driver ( FLOWER KEY )  
☐ Sparkplug Wrench

Remarks :

Complete tools & Accessories w/ battery

I understand all the above items as explained to me by the releasing Officer/ Manager. I also agree that any failure on my part to adhere to any of the instructions given that may result in damages on the above mentioned parts will not be covered by warranty.

Inspected by : Technician  
Technician/PDI Personnel

Approved by : \_\_\_\_\_  
Service Manager

Approved by : \_\_\_\_\_  
Sales Department



CHECKLIST

17099 PAGE 2

Client: Vespa


Chassis #: NV077912

Color: white

Make/Model: Sprint Justin B.

Engine #: 5178685

Date: 9-22-22



LEGEND

S- Scratched  
D- Dented  
DD-Damaged  
L- Loose  
M- Missing  
F- Faded

Remarks:

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_



# AUTOHUB CAR CARE SERVICES (ACCS)

BY: SUPREME AUTOZONE PHILIPPINES INC.

Sitio Buroi Cabrera Road, Brgy. San Juan, Taytay, Rizal

Tel. No.: (632) 533-6398

VAT REG. TIN: 238-978-189-00006

## BILLING STATEMENT

No: 06179

CUSTOMER No. 211806	CUSTOMER NAME AND ADDRESS TIN: 0000000000 #234 ORTIGAS AVENUE NORTH GREENHILLS SAN JUAN CITY MMN 000		ADVISOR Aldrin Padilla	COLOR WHITE	TEAM NH GENER
DOC. DATE 22/12/22	REG. No. UNREG		YEAR/MAKE/MODEL 22/NEXTHUB/SPRINT JUSTIN B	TAG No.	
STOCK No.	PURCHASE ORDER No.		MODEL No. UNREG	CAR LINE VESPA	ENG/TRANS.
DRIVER		CONTACT No.	CHASSIS No.	KILOMETERS	PROD. DATE
HOME PHONE		BUSINESS PHONE	CONTACT NAME	CONTRACT EXP KMS	EXP. DATE
CA <input type="checkbox"/>	R/C <input type="checkbox"/>	CH <input type="checkbox"/>	SELLING DEALER	DELIVERY KMS	DELIVERY DATE
OC <input type="checkbox"/>	WAR <input type="checkbox"/>	INT <input type="checkbox"/>	DATE AND TIME PROMISED 22/12/22 09:00am	TIME RECEIVED 01:54pm	QUOTE PRICE
VEHICLE ID RP8M82221NV077167		ENGINE No. 5178709	AIR PWR TURBO		

Labour  
J# 1 76NAZZZZZ002

PDI CLEAN  
\* PDI UNIT  
\* BRAND NEW UNIT  
\* CHECK AND EVALUATED CONCERN  
\* PERFORMED PDI INSPECTION

Tech(s) : 48051 3125.00

Totals=====

Total - Labour 3125.00

Total Labour. 3125.00  
Total Parts.. 0.00  
Total Other.. 0.00  
Total P.O.L.. 0.00  
Total Misc... 0.00  
VAT 375.00  
Total Invoice 3500.00

*[Signature]*  
12/20/22

ROAD TESTED		ACKNOWLEDGMENT	
ORDER NO.	SUBLET REPAIRS	RECEIVED above vehicle from AUTOHUB CAR CARE SERVICES (ACCS) in good condition and with all repair work enumerated completed to my satisfaction.	
		All works carried out at these premises are subject to a warranty of _____ days or _____ whichever comes first on all labor and materials.	
		SIGNATURE OF OWNER _____	
		I AGREE TO PAY for all works required for all the above described repair at your retail charge. It is understood that any estimate given is provisional and all repairs are undertaken on a cash basis unless prior arrangements for credit have been approved.	
		I have READ AND ACCEPTED your terms and conditions.	



## CHECKLIST

17080

PAGE 1

Client :

Chassis # :

Color:

Make/Model :

Engine # :

Date :

### EMBLEMS

- ( ) Piaggio Emblem ( Front )  
( ) PVG Emblem ( Crankcase )

### SIDE MIRROR

- ( ) LH Side View Mirror  
( ) RH Side View Mirror

### ELECTRICAL BUTTONS

- ( ) Start Button  
( ) Horn Button  
( ) High&Low Button  
( ) Passing Button ( Optional )  
( ) Left Signal Button  
( ) Right Signal Button  
( ) Cut Off Engine Button ( Optional )  
( ) Start & Stop Button  
( ) ASR Button  
( ) Mode  
( ) Saddle Button  
( ) Toggle Switch

### LIGHTS

- ( ) Park Light  
( ) High & Low Beam  
( ) Front Right Signal  
( ) Rear Right Signal  
( ) Front Left Signal  
( ) Rear Left Signal  
( ) Backlight  
( ) Brakelights  
( ) Instrumental Panel Gauges  
( ) Plate Light

### FLUID LEVELS

- ( ) Engine Oil  
( ) Gear Oil  
( ) Brake Fluid  
( ) Coolant

### SCRATCHES

- ( ) No Scratches  
( ) W/ Scratches

\*Encircle parts that has/have scratches

### COLOR

- ( ) Evenly Painted  
( ) Not Evenly Painted

### BATTERY/ HORN

- ( ) Battery  
Brand: \_\_\_\_\_ Battery Voltage: \_\_\_\_\_  
( ) Horn

### TIRES

- ( ) Good Quality  
( ) Bad Quality  
Brand: \_\_\_\_\_  
Tire Pressure: \_\_\_\_\_ Front \_\_\_\_\_ Rear \_\_\_\_\_

### PADS DIAGNOSTIC TOOL

- ( ) PADS Checkup  
Fault: \_\_\_\_\_  
Remarks: \_\_\_\_\_

### SADDLE

- ( ) Good Quality  
( ) Bad Quality

### KEYS/ MANUAL/ TOOLS

- ( ) Master Key  
( ) Duplicate Key  
( ) Service Manual  
( ) Warranty Booklet  
( ) Set of Screw  
( ) Battery Holder  
( ) Plate Holder  
( ) reflectors ( Optional )  
( ) Under Body Caps ( Optional )  
( ) 1 Set of Tools  
( ) Rear Shock Adjuster  
( ) Screw Driver  
( ) Fuse Removal Tool  
( ) Screw driver ( FLOWER KEY )  
( ) Sparkplug Wrench

Remarks :

I understand all the above items as explained to me by the releasing Officer/ Manager. I also agree that any failure on my part to adhere to any of the instructions given that may result in damages on the above mentioned parts will not be covered by warranty.

Inspected by :

Approved by :

Approved by :


Technician/PDI Personnel

Service Manager

Sales Department

CHECKLIST

Client: Vespa Chassis #: 11V077167 Color: white 17080 PAGE 2  
Make/Model: Sprint Justin B. Engine #: 5178709 Date: 9-16-22



LEGEND

S- Scratched	L- Loose
D- Dented	M- Missing
DD-Damaged	F- Faded

Remarks:

ca look my glove box morning Bubbles





# AUTOHUB CAR CARE SERVICES (ACCS)

BY: SUPREME AUTOZONE PHILIPPINES INC.

Sitio Buroi Cabrera Road, Brgy. San Juan, Taytay, Rizal

Tel. No.: (632) 533-6398

VAT REG. TIN: 238-978-189-00006

42

## BILLING STATEMENT

No: **06180**

CUSTOMER No. 211806		CUSTOMER NAME AND ADDRESS TIN: MOTOITALIA PHILS. INC. #234 ORTIGAS AVENUE NORTH GREENHILLS SAN JUAN CITY MMN 000		ADVISOR Aldrin Padilla		COLOR 4A054 WHITE/		TEAM NH GENER	
DOC. DATE 22/12/22				YEAR/MAKE/MODEL 22/NEXTHUB/SPRINT JUSTIN B				TAG No.	
REG. No. UNREG				MODEL No. UNREG		CAR LINE VESPA		ENG./TRANS.	
STOCK No.				CHASSIS No.		KILOMETERS 2		PROD. DATE	
PURCHASE ORDER No.		DRIVER		CONTACT No.		CONTACT NAME		CONTRACT EXP. KMS	
		HOME PHONE		BUSINESS PHONE		SELLING DEALER		DELIVERY KMS	
		VEHICLE ID		ENGINE No.		DATE AND TIME PROMISED		TIME RECEIVED	
		RDAMA2221NU077190		517866B1		22/12/22 09:00am		01:55pm	
CA <input type="checkbox"/> F/C <input type="checkbox"/> CH <input type="checkbox"/>		HOME PHONE		BUSINESS PHONE		DELIVERY DATE		QUOTE PRICE	
C/D <input type="checkbox"/> WAR <input type="checkbox"/> INT <input type="checkbox"/>								AIR PWR TURBO	

Labour  
J# 1 76NAZZZZZ002

PDI CLEAN  
\* PDI UNIT  
\* BRAND NEW UNIT  
\* CHECK AND EVALUATED CONCERN  
PERFORMED PDI INSPECTION

Tech(s) : 48051 3125.00

Total - Labour 3125.00

Totals=====

Total Labour. 3125.00  
Total Parts.. 0.00  
Total Other.. 0.00  
Total P.O.L.. 0.00  
Total Misc... 0.00  
VAT 375.00  
Total Invoice 3500.00

*RJR*  
12/22/22

[ End of Invoice ]

ROAD TESTED		ACKNOWLEDGMENT		I AGREE TO PAY for all works required for all the above described repair at your retail charge. It is understood that any estimate given is provisional and all repairs are undertaken on a cash basis unless prior arrangements for credit have been approved.	
ORDER NO.	SUBLET REPAIRS	RECEIVED above vehicle from AUTOHUB CAR CARE SERVICES (ACCS) in good condition and with all repair work enumerated completed to my satisfaction.		I have READ AND ACCEPTED your terms and conditions.	
		All works carried out at these premises are subject to a warranty of _____ days or _____ whichever comes first on all labor and materials.			
		SIGNATURE OF OWNER _____			

CHECKLIST

17082

PAGE 1

Client : Vespa

Chassis # : NVO 77190

Color : white

Make/Model : Sprint Justin B.

Engine # : 5178681

Date : 9-17-23

EMBLEMS

- ( ) Piaggio Emblem ( Front )  
( ) PVG Emblem ( Crankcase )

SIDE MIRROR

- ( ) LH Side View Mirror  
( ) RH Side View Mirror

ELECTRICAL BUTTONS

- ( ) Start Button  
( ) Horn Button  
( ) High&Low Button  
( ) Passing Button ( Optional )  
( ) Left Signal Button  
( ) Right Signal Button  
( ) Cut Off Engine Button ( Optional )  
( ) Start & Stop Button  
( ) ASR Button  
( ) Mode  
( ) Saddle Button  
( ) Toggle Switch

LIGHTS

- ( ) Park Light  
( ) High & Low Beam  
( ) Front Right Signal  
( ) Rear Right Signal  
( ) Front Left Signal  
( ) Rear Left Signal  
( ) Backlight  
( ) Brakelights  
( ) Instrumental Panel Gauges  
( ) Plate Light

FLUID LEVELS

- ( ) Engine Oil  
( ) Gear Oil  
( ) Brake Fluid  
( ) Coolant

SCRATCHES

- ( ) No Scratches  
( ) W/ Scratches  
\*Encircle parts that has/have scratches

COLOR

- ( ) Evenly Painted  
( ) Not Evenly Painted

BATTERY/ HORN

- ( ) Battery  
Brand : \_\_\_\_\_ Battery Voltage : \_\_\_\_\_  
( ) Horn

TIRES

- ( ) Good Quality  
( ) Bad Quality  
Brand : \_\_\_\_\_  
Tire Pressure : \_\_\_\_\_ Front \_\_\_\_\_ Rear \_\_\_\_\_

PADS DIAGNOSTIC TOOL

- ( ) PADS Checkup  
Fault : \_\_\_\_\_  
Remarks : \_\_\_\_\_

SADDLE

- ( ) Good Quality  
( ) Bad Quality  
KEYS/ MANUAL/ TOOLS  
( ) Master Key  
( ) Duplicate Key  
( ) Service Manual  
( ) Warranty Booklet  
( ) Set of Screw  
( ) Battery Holder  
( ) Plate Holder  
( ) reflectors ( Optional )  
( ) Under Body Caps ( Optional )  
( ) 1 Set of Tools  
( ) Rear Shock Adjuster  
( ) Screw Driver  
( ) Fuse Removal Tool  
( ) Screw driver ( FLOWER KEY )  
( ) Sparkplug Wrench

*Complete Accessories 11/23*

Remarks :

I understand all the above items as explained to me by the releasing Officer/ Manager. I also agree that any failure on my part to adhere to any of the instructions given that may result in damages on the above mentioned parts will not be covered by warranty.

Inspected by : [Signature]  
Technician/PDI Personnel


Approved by : \_\_\_\_\_  
Service Manager

Approved by : \_\_\_\_\_  
Sales Department



CHECKLIST

Client: Vespa Chassis #: NV077190 Color: white 17082 PAGE 2  
Make/Model: Sprint Justin B. Engine #: 5178681 Date: 9-17-22



LEGEND

S- Scratched	L- Loose
D- Dented	M- Missing
DD-Damaged	F- Faded

Remarks: little stain saddle





## CHECKLIST

17084

PAGE 1

Client: Vespa

Chassis #: UV077152

Color: white

Make/Model: Vespa 125cc

Engine #: 5178708

Date: 9-17-22

### EMBLEMS

- ( ) Piaggio Emblem ( Front )  
( ) PVG Emblem ( Crankcase )

### SIDE MIRROR

- ( ) LH Side View Mirror  
( ) RH Side View Mirror

### ELECTRICAL BUTTONS

- ( ) Start Button  
( ) Horn Button  
( ) High&Low Button  
( ) Passing Button ( Optional )  
( ) Left Signal Button  
( ) Right Signal Button  
( ) Cut Off Engine Button ( Optional )  
( ) Start & Stop Button  
( ) ASR Button  
( ) Mode  
( ) Saddle Button  
( ) Toggle Switch

### LIGHTS

- ( ) Park Light  
( ) High & Low Beam  
( ) Front Right Signal  
( ) Rear Right Signal  
( ) Front Left Signal  
( ) Rear Left Signal  
( ) Backlight  
( ) Brakelights  
( ) Instrumental Panel Gauges  
( ) Plate Light

### FLUID LEVELS

- ( ) Engine Oil  
( ) Gear Oil  
( ) Brake Fluid  
( ) Coolant

### SCRATCHES

- ( ) No Scratches  
( ) W/ Scratches  
\*Encircle parts that has/have scratches

### COLOR

- ( ) Evenly Painted  
( ) Not Evenly Painted

### BATTERY/ HORN

- ( ) Battery  
Brand: \_\_\_\_\_ Battery Voltage: \_\_\_\_\_  
( ) Horn

### TIRES

- ( ) Good Quality  
( ) Bad Quality  
Brand: \_\_\_\_\_  
Tire Pressure: \_\_\_\_\_ Front \_\_\_\_\_ Rear \_\_\_\_\_

### PADS DIAGNOSTIC TOOL

- ( ) PADS Checkup  
Fault: \_\_\_\_\_  
Remarks: \_\_\_\_\_

### SADDLE

- ( ) Good Quality  
( ) Bad Quality  
KEYS/ MANUAL/ TOOLS  
( ) Master Key  
( ) Duplicate Key  
( ) Service Manual  
( ) Warranty Booklet  
( ) Set of Screw  
( ) Battery Holder  
( ) Plate Holder  
( ) reflectors ( Optional )  
( ) Under Body Caps ( Optional )  
( ) 1 Set of Tools  
( ) Rear Shock Adjuster  
( ) Screw Driver  
( ) Fuse Removal Tool  
( ) Screw driver ( FLOWER KEY )  
( ) Sparkplug Wrench

Remarks: Complete Accessories / Battery

I understand all the above items as explained to me by the releasing Officer/ Manager. I also agree that any failure on my part to adhere to any of the instructions given that may result in damages on the above mentioned parts will not be covered by warranty.

Inspected by: \_\_\_\_\_

Technician/PDI Personnel

Approved by: \_\_\_\_\_

Service Manager

Approved by: \_\_\_\_\_

Sales Department

CHECKLIST

Client: Vespa


Chassis #: NV077152

Color: white 17084 PAGE 2

Make/Model: Sprint Justin B.

Engine #: 5178708

Date: 9-17-22



LEGEND

S- Scratched	L- Loose
D- Dented	M- Missing
DD-Damaged	F- Faded

Remarks:






# AUTOHUB CAR CARE SERVICES (ACCS)

BY: SUPREME AUTOZONE PHILIPPINES INC.

Sitio Buroi Cabrera Road, Brgy. San Juan, Taytay, Rizal

Tel. No.: (632) 533-6398

VAT REG. TIN: 236-978-189-00006

## BILLING STATEMENT

No: **06182**

CUSTOMER No.	CUSTOMER NAME AND ADDRESS			ADVISOR	COLOR	TEAM
DOC. DATE	TIN: MOTOITALIA PHILS. INC.			YEAR/MAKE/MODEL	480% WHITE	NEW GENER
REG. No.	#234 ORTIGAS AVENUE			22/NEXTHUB/SPRINT		TAG No.
STOCK No.	NORTH GREENHILLS			MODEL No.	CARLINE	ENG/TRANS.
	SAN JUAN CITY MMN 000			UNREG	VESPA	
PURCHASE ORDER No.	DRIVER	CONTACT No.	CONTACT NAME	CHASSIS No.	KILOMETERS	PROD. DATE
						EXP. DATE
CA	RC	CH	HOME PHONE	BUSINESS PHONE	TERMS	SELLING DEALER
C/C	WAR	INT	VEHICLE ID	ENGINE No.	DATE AND TIME PROMISED	DELIVERY KMS
			REARMA2221NU079418 5185550		22/12/22 09:00pm	DELIVERY DATE
					01:56pm	QUOTE PRICE
						AIR PWR TURBO

Labour  
J# 1 76NAZZZZZ002

PDI CLEAN  
\* PDI UNIT  
\* BRAND NEW UNIT  
\* CHECK AND EVALUATED CONCERN  
PERFORMED PDI INSPECTION

Tech(s) : 48051 3125.00

Total - Labour 3125.00

Totals=====

Total Labour.	3125.00
Total Parts..	0.00
Total Other..	0.00
Total P.O.L..	0.00
Total Misc...	0.00
VAT	375.00
Total Invoice	3500.00

*[Signature]*  
12/20/22

ROAD TESTED		ACKNOWLEDGMENT	
ORDER NO.	SUBLET REPAIRS	RECEIVED above vehicle from AUTOHUB CAR CARE SERVICES (ACCS) in good condition and with all repair work enumerated completed to my satisfaction.	
		All works carried out at these premises are subject to a warranty of _____ days or _____ whichever comes first on all labor and materials.	
		SIGNATURE OF OWNER _____	

## CHECKLIST

10482

PAGE 1

Client :

Vespa

Chassis # :

NV1079414

Color :

White

Make/Model :

Sprint

Engine # :

518 5550

Date :

10-22-2012

### EMBLEMS

- ☐ Piaggio Emblem ( Front )
- ☐ PVG Emblem ( Crankcase )

### SIDE MIRROR

- ☐ LH Side View Mirror
- ☐ RH Side View Mirror

### ELECTRICAL BUTTONS

- ☐ Start Button
- ☐ Horn Button
- ☐ High&Low Button
- ☐ Passing Button ( Optional )
- ☐ Left Signal Button
- ☐ Right Signal Button
- ☐ Cut Off Engine Button ( Optional )
- ☐ Start & Stop Button
- ☐ ASR Button
- ☐ Mode
- ☐ Saddle Button
- ☐ Toggle Switch

### LIGHTS

- ☐ Park Light
- ☐ High & Low Beam
- ☐ Front Right Signal
- ☐ Rear Right Signal
- ☐ Front Left Signal
- ☐ Rear Left Signal
- ☐ Backlight
- ☐ Brakelights
- ☐ Instrumental Panel Gauges
- ☐ Plate Light

### FLUID LEVELS

- ☐ Engine Oil
- ☐ Gear Oil
- ☐ Brake Fluid
- ☐ Coolant

### SCRATCHES

- ☐ No Scratches
- ☐ W/ Scratches

\*Encircle parts that has/have scratches

### COLOR

- ☐ Evenly Painted
- ☐ Not Evenly Painted

### BATTERY/ HORN

- ☐ Battery
- Brand: \_\_\_\_\_ Battery Voltage: \_\_\_\_\_
- ☐ Horn

### TIRES

- ☐ Good Quality
- ☐ Bad Quality
- Brand: \_\_\_\_\_
- Tire Pressure: \_\_\_\_\_ Front \_\_\_\_\_ Rear \_\_\_\_\_

### PADS DIAGNOSTIC TOOL

- ☐ PADS Checkup
- Fault: \_\_\_\_\_
- Remarks: \_\_\_\_\_

### SADDLE

- ☐ Good Quality
- ☐ Bad Quality

### KEYS/ MANUAL/ TOOLS

- ☐ Master Key
- ☐ Duplicate Key
- ☐ Service Manual
- ☐ Warranty Booklet
- ☐ Set of Screw
- ☐ Battery Holder
- ☐ Plate Holder
- ☐ reflectors ( Optional )
- ☐ Under Body Caps ( Optional )
- ☐ 1 Set of Tools
- ☐ Rear Shock Adjuster
- ☐ Screw Driver
- ☐ Fuse Removal Tool
- ☐ Screw driver ( FLOWER KEY )
- ☐ Sparkplug Wrench

Remarks :

Complete 1/23

I understand all the above items as explained to me by the releasing Officer/ Manager. I also agree that any failure on my part to adhere to any of the instructions given that may result in damages on the above mentioned parts will not be covered by warranty.

Inspected by :

Technician/PDI Personnel

Approved by :

Service Manager

Approved by :

Sales Department



CHECKLIST

Client:

Vespa

Chassis #:

MG79418

Color:

10482

PAGE 2

White

Make/Model:


Sprint

Engine #:

5185850

Date:

10-22-22



LEGEND

S- Scratched

L- Loose

D- Dented

M- Missing

DD-Damaged

F-Faded

Remarks:

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_



# AUTOHUB CAR CARE SERVICES (ACCS)

BY: SUPREME AUTOZONE PHILIPPINES INC.

Sitio Buroi Cabrera Road, Brgy. San Juan, Taytay, Rizal

Tel. No.: (632) 533-6398

VAT REG. TIN: 236-978-189-00006

## BILLING STATEMENT

No: **06183**

CUSTOMER No.	CUSTOMER NAME AND ADDRESS			ADVISOR	COLOR	TEAM
DOC. DATE	TIN: MOTOITALIA PHILS. INC.			YEAR/MAKE/MODEL	48051 BLUE/	NH GENER
REG. No.	#234 ORTIGAS AVENUE			MODEL No.	22/NEXTHUB/SPRINT	TAG No.
STOCK No.	NORTH GREENHILLS			CHASSIS No.	UNREG	ENG/TRANS.
PURCHASE ORDER No.	DRIVER	CONTACT No.	CONTACT NAME	CONTRACT EXP. KMS	EXP. DATE	
CA <input type="checkbox"/>	RC <input type="checkbox"/>	CH <input type="checkbox"/>	HOME PHONE	SELLING DEALER	DELIVERY KMS	DELIVERY DATE
QC <input type="checkbox"/>	VAR <input type="checkbox"/>	INT <input type="checkbox"/>	BUSINESS PHONE	DATE AND TIME PROMISED	TIME RECEIVED	QUOTE PRICE
	VEHICLE ID	ENGINE No.				AIR PWR TURBO
	RP8M82221NU079404	5185564		22/12/22 09:00pm	01:57pm	

Labour-----  
J# 1 76NAZZZZZ002

Tech(s) : 48051

3125.00

\* PDI CLEAN  
\* PDI UNIT  
\* BRAND NEW UNIT  
\* CHECK AND EVALUATED CONCERN  
\* PERFORMED PDI INSPECTION

Total - Labour 3125.00

Totals=====

Total Labour..	3125.00
Total Parts..	0.00
Total Other..	0.00
Total P.O.L..	0.00
Total Misc...	0.00
VAT	375.00
<b>Total Invoice</b>	<b>3500.00</b>

JHR  
bpe/ps

End of Invoice 1

ROAD TESTED		<b>ACKNOWLEDGMENT</b>	
ORDER NO.	SUBLET REPAIRS	RECEIVED above vehicle from AUTOHUB CAR CARE SERVICES (ACCS) in good condition and with all repair work enumerated completed to my satisfaction	
		All works carried out at these premises are subject to a warranty of _____ days or _____ whichever comes first on all labor and materials.	
		SIGNATURE OF OWNER _____	
		I AGREE TO PAY for all works required for all the above described repair at your retail charge. It is understood that any estimate given is provisional and all repairs are undertaken on a cash basis unless prior arrangements for credit have been approved.	
		I have READ AND ACCEPTED your terms and conditions	



## CHECKLIST

10487

PAGE 1

Client :

Vespa

Chassis # :

NV 079414

Color :

Blue

Make/Model :

Spring

Engine # :

5185564

Date :

10-22-20

### EMBLEMS

- ( ) Piaggio Emblem ( Front )  
( ) PVG Emblem ( Crankcase )

### SIDE MIRROR

- ( ) LH Side View Mirror  
( ) RH Side View Mirror

### ELECTRICAL BUTTONS

- ( ) Start Button  
( ) Horn Button  
( ) High&Low Button  
( ) Passing Button ( Optional )  
( ) Left Signal Button  
( ) Right Signal Button  
( ) Cut Off Engine Button ( Optional )  
( ) Start & Stop Button  
( ) ASR Button  
( ) Mode  
( ) Saddle Button  
( ) Toggle Switch

### LIGHTS

- ( ) Park Light  
( ) High & Low Beam  
( ) Front Right Signal  
( ) Rear Right Signal  
( ) Front Left Signal  
( ) Rear Left Signal  
( ) Backlight  
( ) Brakelights  
( ) Instrumental Panel Gauges  
( ) Plate Light

### FLUID LEVELS

- ( ) Engine Oil  
( ) Gear Oil  
( ) Brake Fluid  
( ) Coolant

### SCRATCHES

- ( ) No Scratches  
( ) W/ Scratches  
\*Encircle parts that has/have scratches

### COLOR

- ( ) Evenly Painted  
( ) Not Evenly Painted

### BATTERY/ HORN

- ( ) Battery  
Brand: \_\_\_\_\_ Battery Voltage: \_\_\_\_\_  
( ) Horn

### TIRES

- ( ) Good Quality  
( ) Bad Quality  
Brand: \_\_\_\_\_  
Tire Pressure: \_\_\_\_\_ Front \_\_\_\_\_ Rear \_\_\_\_\_

### PADS DIAGNOSTIC TOOL

- ( ) PADS Checkup  
Fault : \_\_\_\_\_  
Remarks: \_\_\_\_\_

### SADDLE

- ( ) Good Quality  
( ) Bad Quality  
**KEYS/ MANUAL/ TOOLS**  
( ) Master Key  
( ) Duplicate Key  
( ) Service Manual  
( ) Warranty Booklet  
( ) Set of Screw  
( ) Battery Holder  
( ) Plate Holder  
( ) reflectors ( Optional )  
( ) Under Body Caps ( Optional )  
( ) 1 Set of Tools  
( ) Rear Shock Adjuster  
( ) Screw Driver  
( ) Fuse Removal Tool  
( ) Screw driver ( FLOWER KEY )  
( ) Sparkplug Wrench

Remarks :

Complete Acc. 2 tools w/ Brackets

I understand all the above items as explained to me by the releasing Officer/ Manager. I also agree that any failure on my part to adhere to any of the instructions given that may result in damages on the above mentioned parts will not be covered by warranty.

Inspected by :

Technician/PDI Personnel

Approved by :

Service Manager

Approved by :

Sales Department

CHECKLIST

Client :

Vespa

Chassis # :

NV079414

Color:

10487  
Blue

PAGE 2

Make/Model :


Sprint

Engine # :

5185564

Date :

10-22-22



LEGEND

S- Scratched

L- Loose

D- Dented

M- Missing

DD- Damaged

F- Faded

Remarks:






# AUTOHUB CAR CARE SERVICES (ACCS)

BY: SUPREME AUTOZONE PHILIPPINES INC.

Sitio Buroi Cabrera Road, Brgy. San Juan, Taytay, Rizal

Tel. No.: (632) 533-8398

VAT REG. TIN: 236-978-189-00006

## BILLING STATEMENT

No: **06184**

CUSTOMER No. 211A06	CUSTOMER NAME AND ADDRESS TIN: MOTOITALIA PHILS. INC. #234 ORTIGAS AVENUE NORTH GREENHILLS SAN JUAN CITY MMN 000	ADVISOR Aldrin Fadilla	COLOR 4A076 BLUE	TEAM NH GENER
DOC. DATE 22/12/22		YEAR/MAKE/MODEL 22/NEXTHUB/SPRINT		TAG No.
REG. No. UNREG		MODEL No. UNREG	CAR LINE VESPA	ENG./TRANS.
STOCK No.		CHASSIS No.	KILOMETERS	PROD. DATE
PURCHASE ORDER No.	DRIVER	CONTACT No.	CONTACT NAME	CONTRACT EXP. KMS
CA <input type="checkbox"/>	HOME PHONE	BUSINESS PHONE	TERMS	EXP. DATE
C/C <input type="checkbox"/>	VEHICLE ID	ENGINE No.	SELLING DEALER	DELIVERY KMS
			DATE AND TIME PROMISED	DELIVERY DATE
			TIME RECEIVED	QUOTE PRICE
				AIR PWR TURBO

Labour  
J# 1 76NAZZZZ002

Tech(s) : 48051 3125.00

PDI CLEAN

- \* PDI UNIT
- \* BRAND NEW UNIT
- \* CHECK AND EVALUATED CONCERN
- \* PERFORMED PDI INSPECTION

Total - Labour 3125.00

Totals:=====

Total Labour..	3125.00
Total Parts..	0.00
Total Other..	0.00
Total P.O.L..	0.00
Total Misc...	0.00
VAT	375.00
<b>Total Invoice</b>	<b>3500.00</b>

RJR  
12/22/22

[ End of Invoice ]

ROAD TESTED		<b>ACKNOWLEDGMENT</b>	
ORDER NO.	SUBLET REPAIRS	RECEIVED above vehicle from AUTOHUB CAR CARE SERVICES (ACCS) in good condition and with all repair work enumerated completed to my satisfaction.	
		All works carried out at these premises are subject to a warranty of _____ days or _____ whichever comes first on all labor and materials.	
		SIGNATURE OF OWNER _____	
		I AGREE TO PAY for all works required for all the above described repair at your retail charge. It is understood that any estimate given is provisional and all repairs are undertaken on a cash basis unless prior arrangements for credit have been approved.	
		I have READ AND ACCEPTED your terms and conditions.	

## CHECKLIST

10488

PAGE 1

Client :

Vespa

Chassis # :

NV079411

Color :

Blue

Make/Model :

Sprint

Engine # :

5185347

Date :

10-22-21

### EMBLEMS

- ( ) Piaggio Emblem ( Front )  
( ) PVG Emblem ( Crankcase )

### SIDE MIRROR

- ( ) LH Side View Mirror  
( ) RH Side View Mirror

### ELECTRICAL BUTTONS

- ( ) Start Button  
( ) Horn Button  
( ) High&Low Button  
( ) Passing Button ( Optional )  
( ) Left Signal Button  
( ) Right Signal Button  
( ) Cut Off Engine Button ( Optional )  
( ) Start & Stop Button  
( ) ASR Button  
( ) Mode  
( ) Saddle Button  
( ) Toggle Switch

### LIGHTS

- ( ) Park Light  
( ) High & Low Beam  
( ) Front Right Signal  
( ) Rear Right Signal  
( ) Front Left Signal  
( ) Rear Left Signal  
( ) Backlight  
( ) Brakelights  
( ) Instrumental Panel Gauges  
( ) Plate Light

### FLUID LEVELS

- ( ) Engine Oil  
( ) Gear Oil  
( ) Brake Fluid  
( ) Coolant

### SCRATCHES

- ( ) No Scratches  
( ) W/ Scratches  
\*Encircle parts that has/have scratches

### COLOR

- ( ) Evenly Painted  
( ) Not Evenly Painted

### BATTERY/ HORN

- ( ) Battery  
Brand: \_\_\_\_\_ Battery Voltage: \_\_\_\_\_  
( ) Horn

### TIRES

- ( ) Good Quality  
( ) Bad Quality  
Brand: \_\_\_\_\_  
Tire Pressure: \_\_\_\_\_ Front \_\_\_\_\_ Rear \_\_\_\_\_

### PADS DIAGNOSTIC TOOL

- ( ) PADS Checkup  
Fault : \_\_\_\_\_  
Remarks: \_\_\_\_\_

### SADDLE

- ( ) Good Quality  
( ) Bad Quality  
**KEYS/ MANUAL/ TOOLS**  
( ) Master Key  
( ) Duplicate Key  
( ) Service Manual  
( ) Warranty Booklet  
( ) Set of Screw  
( ) Battery Holder  
( ) Plate Holder  
( ) reflectors ( Optional )  
( ) Under Body Caps ( Optional )  
( ) 1 Set of Tools  
( ) Rear Shock Adjuster  
( ) Screw Driver  
( ) Fuse Removal Tool  
( ) Screw driver ( FLOWER KEY )  
( ) Sparkplug Wrench

Remarks :

Complete Acc & file w/ booklet

I understand all the above items as explained to me by the releasing Officer/ Manager. I also agree that any failure on my part to adhere to any of the instructions given that may result in damages on the above mentioned parts will not be covered by warranty.

Inspected by :

Technician/PDI Personnel

Approved by :

Service Manager

Approved by :


Sales Department



CHECKLIST

10488 PAGE 2

Client: Vespa Chassis #: N41079411 Color: Blue  
 Make/Model: Springer Engine #: 57815347 Date: 10-22-22



LEGEND

S- Scratched	L- Loose
D- Dented	M- Missing
DD-Damaged	F- Faded

Remarks:




# AUTOHUB CAR CARE SERVICES (ACCS)

BY: SUPREME AUTOZONE PHILIPPINES INC.

Sitio Buroi Cabrera Road, Brgy. San Juan, Taytay, Rizal

Tel. No. (832) 533-6398

VAT REG. TIN: 236-978-189-00006

## BILLING STATEMENT

No: **06185**

CUSTOMER No. 211806	CUSTOMER NAME AND ADDRESS TIN: MOTOITALIA PHILS. INC.		ADVISOR Aldrin Padilla	COLOR 48054 BLUE	TEAM NH GENER
DOC. DATE 22/12/22	#234 ORTIGAS AVENUE		YEAR/MAKE/MODEL 22/NEXTHUB/SPRINT	TAG No.	
REG. No. UNREG	NORTH GREENHILLS		MODEL No. UNREG	CAR LINE VESPA	ENG./TRANS.
STOCK No.	SAN JUAN CITY MMN 000		CHASSIS No.	KILOMETERS	PROD. DATE
PURCHASE ORDER No.	DRIVER	CONTACT No.	CONTACT NAME	CONTRACT EXP KMS	EXP DATE
CA <input type="checkbox"/>	RC <input type="checkbox"/>	CH <input type="checkbox"/>	HOME PHONE	BUSINESS PHONE	TERMS
OC <input type="checkbox"/>	WAR <input type="checkbox"/>	INT <input type="checkbox"/>	VEHICLE ID RP8AM82221NU079408	ENGINE No. 5185354	DATE AND TIME PROMISED 22/12/22 09:00am
			SELLING DEALER	DELIVERY KMS	DELIVERY DATE
			TIME RECEIVED 01:58pm	QUOTE PRICE	AIR PWR TURBO

Labour  
J# 1 76NAZZZZZ002

PDI CLEAN  
\* PDI UNIT  
\* BRAND NEW UNIT  
\* CHECK AND EVALUATED CONCERN  
\* PERFORMED PDI INSPECTION

Tech(s) : 48051 3125.00

Totals: Total - Labour 3125.00

Total Labour. 3125.00  
Total Parts.. 0.00  
Total Other.. 0.00  
Total P.O.L.. 0.00  
Total Misc... 0.00  
VAT 375.00

Total Invoice 3500.00

*RJR*  
12/22/22

[ End of Invoice ]

ROAD TESTED		ACKNOWLEDGMENT	
ORDER NO.	SUBLET REPAIRS	RECEIVED above vehicle from AUTOHUB CAR CARE SERVICES (ACCS) in good condition and with all repair work enumerated completed to my satisfaction.	
		All works carried out at these premises are subject to a warranty of _____ days or _____ whichever comes first on all labor and materials.	
		SIGNATURE OF OWNER _____	
		I AGREE TO PAY for all works required for all the above described repair at your retail charge. It is understood that any estimate given is provisional and all repairs are undertaken on a cash basis unless prior arrangements for credit have been approved.	
		I have READ AND ACCEPTED your terms and conditions.	



## CHECKLIST

10489

PAGE 1

Client :

Vespa

Chassis # :

N4079408

Color:

Blue

Make/Model :

Sprint

Engine # :

5185354

Date :

10-22-24

### EMBLEMS

- ( ) Piaggio Emblem ( Front )  
( ) PVG Emblem ( Crankcase )

### SIDE MIRROR

- ( ) LH Side View Mirror  
( ) RH Side View Mirror

### ELECTRICAL BUTTONS

- ( ) Start Button  
( ) Horn Button  
( ) High&Low Button  
( ) Passing Button ( Optional )  
( ) Left Signal Button  
( ) Right Signal Button  
( ) Cut Off Engine Button ( Optional )  
( ) Start & Stop Button  
( ) ASR Button  
( ) Mode  
( ) Saddle Button  
( ) Toggle Switch

### LIGHTS

- ( ) Park Light  
( ) High & Low Beam  
( ) Front Right Signal  
( ) Rear Right Signal  
( ) Front Left Signal  
( ) Rear Left Signal  
( ) Backlight  
( ) Brakelights  
( ) Instrumental Panel Gauges  
( ) Plate Light

### FLUID LEVELS

- ( ) Engine Oil  
( ) Gear Oil  
( ) Brake Fluid  
( ) Coolant

### SCRATCHES

- ( ) No Scratches  
( ) W/ Scratches  
\*Encircle parts that has/have scratches

### COLOR

- ( ) Evenly Painted  
( ) Not Evenly Painted

### BATTERY/ HORN

- ( ) Battery  
Brand: \_\_\_\_\_ Battery Voltage: \_\_\_\_\_  
( ) Horn

### TIRES

- ( ) Good Quality  
( ) Bad Quality  
Brand: \_\_\_\_\_  
Tire Pressure: \_\_\_\_\_ Front \_\_\_\_\_ Rear \_\_\_\_\_

### PADS DIAGNOSTIC TOOL

- ( ) PADS Checkup

Fault : \_\_\_\_\_

Remarks: \_\_\_\_\_

### SADDLE

- ( ) Good Quality  
( ) Bad Quality  
**KEYS/ MANUAL/ TOOLS**  
( ) Master Key  
( ) Duplicate Key  
( ) Service Manual  
( ) Warranty Booklet  
( ) Set of Screw  
( ) Battery Holder  
( ) Plate Holder  
( ) reflectors ( Optional )  
( ) Under Body Caps ( Optional )  
( ) 1 Set of Tools  
( ) Rear Shock Adjuster  
( ) Screw Driver  
( ) Fuse Removal Tool  
( ) Screw driver ( FLOWER KEY )  
( ) Sparkplug Wrench

Remarks :

Complete Acc. by tools w/ instructions

I understand all the above items as explained to me by the releasing Officer/ Manager. I also agree that any failure on my part to adhere to any of the instructions given that may result in damages on the above mentioned parts will not be covered by warranty.

Inspected by :

Technician/PDI Personnel

Approved by :

Service Manager

Approved by :

Sales Department

CHECKLIST

10489

PAGE 2

Client :

Vespa  
Sprint

Chassis # :

NV1074108

Color:

Blue


Make/Model :

Engine # :

5185354

Date :

10-22-22



LEGEND

S- Scratched

L- Loose

D- Dented

M- Missing

DD-Damaged

F- Faded

Remarks:

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_





## CHECKLIST

12439

PAGE 1

Client :

VESPA

Chassis # :

Rp8m82221

Color:

WHITE

Make/Model:

Vespa Sprint

Engine # :

11037428

Date :

9/23/22

### EMBLEMS

- ( ) Piaggio Emblem ( Front )
- ( ) PVG Emblem ( Crankcase )

### SIDE MIRROR

- ( ) LH Side View Mirror
- ( ) RH Side View Mirror

### ELECTRICAL BUTTONS

- ( ) Start Button
- ( ) Horn Button
- ( ) High&Low Button
- ( ) Passing Button ( Optional )
- ( ) Left Signal Button
- ( ) Right Signal Button
- ( ) Cut Off Engine Button ( Optional )
- ( ) Start & Stop Button
- ( ) ASR Button
- ( ) Mode
- ( ) Saddle Button
- ( ) Toggle Switch

### LIGHTS

- ( ) Park Light
- ( ) High & Low Beam
- ( ) Front Right Signal
- ( ) Rear Right Signal
- ( ) Front Left Signal
- ( ) Rear Left Signal
- ( ) Backlight
- ( ) Brakelights
- ( ) Instrumental Panel Gauges
- ( ) Plate Light

### FLUID LEVELS

- ( ) Engine Oil
- ( ) Gear Oil
- ( ) Brake Fluid
- ( ) Coolant

### SCRATCHES

- ( ) No Scratches
  - ( ) W/ Scratches
- \*Encircle parts that has/have scratches

### COLOR

- ( ) Evenly Painted
- ( ) Not Evenly Painted

### BATTERY/ HORN

- ( ) Battery
- Brand: DUKAL Battery Voltage: 12V
- ( ) Horn

### TIRES

- ( ) Good Quality
- ( ) Bad Quality
- Brand: CST
- Tire Pressure: Front Rear

### PADS DIAGNOSTIC TOOL

- ( ) PADS Checkup
- Fault :
- Remarks :

### SADDLE

- ( ) Good Quality
- ( ) Bad Quality
- KEYS/ MANUAL/ TOOLS
- ( ) Master Key
- ( ) Duplicate Key
- ( ) Service Manual
- ( ) Warranty Booklet
- ( ) Set of Screw
- ( ) Battery Holder
- ( ) Plate Holder
- ( ) reflectors ( Optional )
- ( ) Under Body Caps ( Optional )
- ( ) 1 Set of Tools
- ( ) Rear Shock Adjuster
- ( ) Screw Driver
- ( ) Fuse Removal Tool
- ( ) Screw driver ( FLOWER KEY )
- ( ) Sparkplug Wrench

Remarks :

COMPLETE ACCESSORIES w/ BATTERY

I understand all the above items as explained to me by the releasing Officer/ Manager. I also agree that any failure on my part to adhere to any of the instructions given that may result in damages on the above mentioned parts will not be covered by warranty.

Inspected by :

Technician/PDI Personnel

Approved by :

Service Manager

Approved by :

Sales Department



CHECKLIST

Client:

VESPA  
Vespa Sprint

Chassis #:

RP882221

Color:

12439

PAGE 2

WHITE

Make/Model:


JUSTIN BIEBER 150

Engine #:

5178656

Date:

9/23/22



LEGEND

S- Scratched	L- Loose
D- Dented	M- Missing
DD-Damaged	F- Faded

Remarks:

FOR BUFFING

D. TALAMISAN



# AUTOHUB CAR CARE SERVICES (ACCS)

BY: SUPREME AUTOZONE PHILIPPINES INC.  
Sitio Buroi Cabrera Road, Brgy. San Juan, Taytay, Rizal  
Tel. No.: (632) 533-6398  
VAT REG. TIN: 236-978-189-00006

## BILLING STATEMENT

No: **06204**

Service Invoice

Page 1 of 1

Doc # : ATCJ E23233

CUSTOMER No. 211806	CUSTOMER NAME AND ADDRESS TIN: OTOTITALIA PHILS. INC.	ADVISOR Aldrin Padilla	COLOR 48054 WHITE/	TEAM NH GENER
DOC. DATE 27/12/22	#234 ORTIGAS AVENUE	YEAR/MAKE/MODEL 22/NEXTHUB/JUSTIN BIEBER 150		TAG No.
REG. No. UNREG	NORTH GREENHILLS	MODEL No. UNREG	CAR LINE VESPA	ENG./TRANS.
STOCK No.	SAN JUAN CITY MMN 000	CHASSIS No.	KILOMETERS	PROD. DATE
PURCHASE ORDER No.	DRIVER	CONTACT No.	CONTACT NAME	CONTRACT EXP KMS
CA <input type="checkbox"/>	HOME PHONE	TERMS	SELLING DEALER	DELIVERY KMS
FC <input type="checkbox"/>	BUSINESS PHONE			DELIVERY DATE
CH <input type="checkbox"/>	VEHICLE ID	ENGINE No. <i>1823m</i>	DATE AND TIME PROMISED	TIME RECEIVED
C/C <input type="checkbox"/>	RP8M82221NV0771	5178690	27/12/22 09:00pm	11:21am
WAR <input type="checkbox"/>				QUOTE PRICE
INT <input type="checkbox"/>				AIR PWR TURBO

Labour  
J# 1 76NAZZZZZ002

PDI CLEAN  
\* PDI UNIT  
\* BRAND NEW UNIT  
\* CHECKED AND EVALUATED CONCERN  
\* PERFORMED PDI INSPECTION

Tech(s) : 48055 3125.00

Total - Labour 3125.00

Totals=====

Total Labour. 3125.00  
Total Parts.. 0.00  
Total Other.. 0.00  
Total P.O.L.. 0.00  
Total Misc... 0.00  
VAT 375.00

Total Invoice 3500.00

*RJR*  
12/27/22

[ End of Invoice ]

ROAD TESTED		ACKNOWLEDGMENT	
ORDER NO.	SUBLET REPAIRS	RECEIVED above vehicle from AUTOHUB CAR CARE SERVICES (ACCS) in good condition and with all repair work enumerated completed to my satisfaction.	I AGREE TO PAY for all works required for all the above described repair at your retail charge. It is understood that any estimate given is provisional and all repairs are undertaken on a cash basis unless prior arrangements for credit have been approved.
		All works carried out at these premises are subject to a warranty of _____ days or _____ whichever comes first on all labor and materials.	I have READ AND ACCEPTED your terms and conditions.
		SIGNATURE OF OWNER _____	



## CHECKLIST

12440

PAGE 1

Client :

VESPA

Chassis # :

RP8m82221

Q

Color:

WHITE

Make/Model :

Vespa Sport

Engine # :

m820m

Q

Date :

9/27/22

### EMBLEMS

- ( ) Piaggio Emblem ( Front )
- ( ) PVG Emblem ( Crankcase )

### SIDE MIRROR

- ( ) LH Side View Mirror
- ( ) RH Side View Mirror

### ELECTRICAL BUTTONS

- ( ) Start Button
- ( ) Horn Button
- ( ) High&Low Button
- ( ) Passing Button ( Optional )
- ( ) Left Signal Button
- ( ) Right Signal Button
- ( ) Cut Off Engine Button ( Optional )
- ( ) Start & Stop Button
- ( ) ASR Button
- ( ) Mode
- ( ) Saddle Button
- ( ) Toggle Switch

### LIGHTS

- ( ) Park Light
- ( ) High & Low Beam
- ( ) Front Right Signal
- ( ) Rear Right Signal
- ( ) Front Left Signal
- ( ) Rear Left Signal
- ( ) Backlight
- ( ) Brakelights
- ( ) Instrumental Panel Gauges
- ( ) Plate Light

### FLUID LEVELS

- ( ) Engine Oil
- ( ) Gear Oil
- ( ) Brake Fluid
- ( ) Coolant

### SCRATCHES

- ( ) No Scratches
  - ( ) W/ Scratches
- \*Encircle parts that has/have scratches

### COLOR

- ( ) Evenly Painted
- ( ) Not Evenly Painted

### BATTERY/ HORN

- ( ) Battery
- Brand: DAVITA Battery Voltage: 12V
- ( ) Horn

### TIRES

- ( ) Good Quality
- ( ) Bad Quality

Brand: CS  
Tire Pressure: Front \_\_\_\_\_ Rear \_\_\_\_\_

### PADS DIAGNOSTIC TOOL

- ( ) PADS Checkup

Fault : \_\_\_\_\_

Remarks: \_\_\_\_\_

### SADDLE

- ( ) Good Quality
- ( ) Bad Quality

### KEYS/ MANUAL/ TOOLS

- ( ) Master Key
- ( ) Duplicate Key
- ( ) Service Manual
- ( ) Warranty Booklet
- ( ) Set of Screw
- ( ) Battery Holder
- ( ) Plate Holder
- ( ) reflectors ( Optional )
- ( ) Under Body Caps ( Optional )
- ( ) 1 Set of Tools
- ( ) Rear Shock Adjuster
- ( ) Screw Driver
- ( ) Fuse Removal Tool
- ( ) Screw driver ( FLOWER KEY )
- ( ) Sparkplug Wrench

Remarks :

2nd 11/23

I understand all the above items as explained to me by the releasing Officer/ Manager. I also agree that any failure on my part to adhere to any of the instructions given that may result in damages on the above mentioned parts will not be covered by warranty.

Inspected by :

Technician/PDI Personnel

Approved by :


Service Manager

Approved by :

Sales Department

CHECKLIST

Client: VESPA Chassis #: RP8m82221 Color: 12440 PAGE 2  
Vespa Sprint  
 Make/Model: JUSTIN B. 150 Engine #: NV0771921  
ms28m  
5178690 Date: 9-27-22



LEGEND

S- Scratched	L- Loose
D- Dented	M- Missing
DD-Damaged	F- Faded

Remarks:

FOR BUFFING

D. TALAMISAN





# AUTOHUB CAR CARE SERVICES (ACCS)

BY: SUPREME AUTOZONE PHILIPPINES INC.  
Sitio Buroi Cabrera Road, Brgy. San Juan, Taytay, Rizal  
Tel. No.: (632) 533-6398  
VAT REG. TIN: 238-978-189-00006

## BILLING STATEMENT

No: **06205**

Service Invoice

Page 1 of 1

Doc #: ATCJ E23234

CUSTOMER No. 211806	CUSTOMER NAME AND ADDRESS TIN: OTODITALIA PHILS. INC. #234 ORTIGAS AVENUE NORTH GREENHILLS SAN JUAN CITY MMN 000	ADVISOR Aldrin Padilla	COLOR 48054 WHITE/	TEAM NH GENER
DOC. DATE 27/12/22		YEAR/MAKE/MODEL 22/NEXTHUB/JUSTIN B 150		TAG No.
REG. No. UNREG		MODEL No. UNREG	CAR LINE VESPA	ENG./TRANS.
STOCK No.		CHASSIS No.	KILOMETERS	PROD. DATE
PURCHASE ORDER No.	DRIVER	CONTACT No.	CONTACT NAME	CONTRACT EXP KMS
	HOME PHONE	BUSINESS PHONE	SELLING DEALER	DELIVERY KMS
CA <input type="checkbox"/>	RC <input type="checkbox"/>	CH <input type="checkbox"/>	VEHICLE ID RP8M92221NV077105	DELIVERY DATE
C/C <input type="checkbox"/>	YAR <input type="checkbox"/>	INT <input type="checkbox"/>	ENGINE No. <i>1828m</i>	DATE AND TIME PROMISED 27/12/22 09:00pm
				TIME RECEIVED 11:23am
				QUOTE PRICE
				AIR
				PWR
				TURBO

Labour J# 1 76NAZZZZZ002	PDI CLEAN	Tech(s) : 48055	3125.00
	* PDI UNIT		
	* BRAND NEW UNIT		
	* CHECKED AND EVALUATED CONCERN		
	* PERFORMED PDI INSPECTION		
Total - Labour			3125.00
Totals=====			

Total Labour.	3125.00
Total Parts..	0.00
Total Other..	0.00
Total P.O.L..	0.00
Total Misc...	0.00
VAT	375.00
Total Invoice	3500.00

*[Signature]*  
12/27/22

[ End of Invoice ]

ROAD TESTED		<b>ACKNOWLEDGMENT</b>	
ORDER NO.	SUBLET REPAIRS	RECEIVED above vehicle from AUTOHUB CAR CARE SERVICES (ACCS) in good condition and with all repair work enumerated completed to my satisfaction.	
		All works carried out at these premises are subject to a warranty of _____ days or _____ whichever comes first on all labor and materials.	
		SIGNATURE OF OWNER _____	
		I AGREE TO PAY for all works required for all the above described repair at your retail charge. It is understood that any estimate given is provisional and all repairs are undertaken on a cash basis unless prior arrangements for credit have been approved.	
		I have READ AND ACCEPTED your terms and conditions	

## CHECKLIST

12442

PAGE 1

Client: VESPA Chassis #: 10808221 Color: WHITE  
 Make/Model: Vespa Sprint Engine #: 578712 Date: 9-27-12

### EMBLEMS

- ( ) Piaggio Emblem ( Front )  
 ( ) PVG Emblem ( Crankcase )

### SIDE MIRROR

- ( ) LH Side View Mirror  
 ( ) RH Side View Mirror

### ELECTRICAL BUTTONS

- ( ) Start Button  
 ( ) Horn Button  
 ( ) High&Low Button  
 ( ) Passing Button ( Optional )  
 ( ) Left Signal Button  
 ( ) Right Signal Button  
 ( ) Cut Off Engine Button ( Optional )  
 ( ) Start & Stop Button  
 ( ) ASR Button  
 ( ) Mode  
 ( ) Saddle Button  
 ( ) Toggle Switch

### LIGHTS

- ( ) Park Light  
 ( ) High & Low Beam  
 ( ) Front Right Signal  
 ( ) Rear Right Signal  
 ( ) Front Left Signal  
 ( ) Rear Left Signal  
 ( ) Backlight  
 ( ) Brakelights  
 ( ) Instrumental Panel Gauges  
 ( ) Plate Light

### FLUID LEVELS

- ( ) Engine Oil  
 ( ) Gear Oil  
 ( ) Brake Fluid  
 ( ) Coolant

### SCRATCHES

- ( ) No Scratches  
 ( ) W/ Scratches  
 \*Encircle parts that has/have scratches

### COLOR

- ( ) Evenly Painted  
 ( ) Not Evenly Painted

### BATTERY/ HORN

- ( ) Battery  
 Brand: DELTA Battery Voltage: 12V  
 ( ) Horn

### TIRES

- ( ) Good Quality  
 ( ) Bad Quality  
 Brand: CEAT  
 Tire Pressure:        Front        Rear

### PADS DIAGNOSTIC TOOL

- ( ) PADS Checkup  
 Fault:         
 Remarks:

### SADDLE

- ( ) Good Quality  
 ( ) Bad Quality  
 KEYS/ MANUAL/ TOOLS  
 ( ) Master Key  
 ( ) Duplicate Key  
 ( ) Service Manual  
 ( ) Warranty Booklet  
 ( ) Set of Screw  
 ( ) Battery Holder  
 ( ) Plate Holder  
 ( ) reflectors ( Optional )  
 ( ) Under Body Caps ( Optional )  
 ( ) 1 Set of Tools  
 ( ) Rear Shock Adjuster  
 ( ) Screw Driver  
 ( ) Fuse Removal Tool  
 ( ) Screw driver ( FLOWER KEY )  
 ( ) Sparkplug Wrench

Remarks :

I understand all the above items as explained to me by the releasing Officer/ Manager. I also agree that any failure on my part to adhere to any of the instructions given that may result in damages on the above mentioned parts will not be covered by warranty.

Inspected by :                       
 Technician/PDI Personnel


Approved by :                       
 Service Manager

Approved by :                       
 Sales Department



CHECKLIST

Client: VESPA Chassis #: ppxm8221 12442 PAGE 2  
vespa sprint Color: WHITE  
 Make/Model: JUSTIN B. 150 Engine #: 5178712 Date: 9-27-22



LEGEND

S- Scratched	L- Loose
D- Dented	M- Missing
DD-Damaged	F- Faded

Remarks:

FDP DUEING

D. TALAMISAN



# AUTOHUB CAR CARE SERVICES (ACCS)

BY: SUPREME AUTOZONE PHILIPPINES INC.

Sitio Buroi Cabrera Road, Brgy. San Juan, Taytay, Rizal

Tel. No.: (632) 533-6398

VAT REG. TIN: 236-978-189-00006

## BILLING STATEMENT

No: **06206**

Service Invoice

Page 1 of 1

Doc # : ATCJ E23235

CUSTOMER No. 211806	CUSTOMER NAME AND ADDRESS TIN: MOTOITALIA PHILS. INC.		ADVISOR Aldrin Padilla	COLOR 48054 WHITE/	TEAM NH GENER
DOC. DATE 27/12/22	#234 ORTIGAS AVENUE		YEAR/MAKE/MODEL 22/NEXTHUB/JUSTIN B 150	TAG No.	
REG. No. UNREG	NORTH GREENHILLS		MODEL No. UNREG	CAR LINE VESPA	ENG./TRANS.
STOCK No.	SAN JUAN CITY MMN 000		CHASSIS No.	KILOMETERS	PROD. DATE
PURCHASE ORDER No.	DRIVER	CONTACT No.	CONTACT NAME	CONTRACT EXP KMS	EXP. DATE
CA <input type="checkbox"/>	FC <input type="checkbox"/>	CH <input type="checkbox"/>	HOME PHONE	BUSINESS PHONE	TERMS
OC <input type="checkbox"/>	WAR <input type="checkbox"/>	INT <input type="checkbox"/>	VEHICLE ID RP8M82221NV077163	ENGINE No. M828m	DATE AND TIME PROMISED 27/12/22 09:00pm
			SELLING DEALER	DELIVERY KMS	DELIVERY DATE
				TIME RECEIVED 11:23am	QUOTE PRICE
				AIR	PWR
				TURBO	

Labour  
J# 1 76NAZZZZZ002

PDI CLEAN  
\* PDI UNIT  
\* BRAND NEW UNIT  
\* CHECKED AND EVALUATED CONCERN  
PERFORMED PDI INSPECTION

Tech(s) : 48055

3125.00

Total - Labour 3125.00

Totals=====

Total Labour.	3125.00
Total Parts..	0.00
Total Other..	0.00
Total P.O.L..	0.00
Total Misc...	0.00
VAT	375.00
Total Invoice	3500.00

*[Signature]*  
12/27/22

[ End of Invoice ]

ROAD TESTED		ACKNOWLEDGMENT	
ORDER NO.	SUBLET REPAIRS	RECEIVED above vehicle from AUTOHUB CAR CARE SERVICES (ACCS) in good condition and with all repair work enumerated completed to my satisfaction.	
		All works carried out at these premises are subject to a warranty of _____ days or _____ whichever comes first on all labor and materials.	
		SIGNATURE OF OWNER _____	
		I AGREE TO PAY for all works required for all the above described repair at your retail charge. It is understood that any estimate given is provisional and all repairs are undertaken on a cash basis unless prior arrangements for credit have been approved.	
		I have READ AND ACCEPTED your terms and conditions	



## CHECKLIST

12445

PAGE 1

Client :

Vespa Sprint Jr  
JUSTIN B. 130

Chassis # :

RP8M8221 JB  
NV077165  
misa

Color:

WHITE

Make/Model :

Engine # :

5178696 JB

Date :

9-27-22

### EMBLEMS

- ( ) Piaggio Emblem ( Front )
- ( ) PVG Emblem ( Crankcase )

### SIDE MIRROR

- ( ) LH Side View Mirror
- ( ) RH Side View Mirror

### ELECTRICAL BUTTONS

- ( ) Start Button
- ( ) Horn Button
- ( ) High&Low Button
- ( ) Passing Button ( Optional )
- ( ) Left Signal Button
- ( ) Right Signal Button
- ( ) Cut Off Engine Button ( Optional )
- ( ) Start & Stop Button
- ( ) ASR Button
- ( ) Mode
- ( ) Saddle Button
- ( ) Toggle Switch

### LIGHTS

- ( ) Park Light
- ( ) High & Low Beam
- ( ) Front Right Signal
- ( ) Rear Right Signal
- ( ) Front Left Signal
- ( ) Rear Left Signal
- ( ) Backlight
- ( ) Brakelights
- ( ) Instrumental Panel Gauges
- ( ) Plate Light

### FLUID LEVELS

- ( ) Engine Oil
- ( ) Gear Oil
- ( ) Brake Fluid
- ( ) Coolant

Remarks :

### SCRATCHES

- ( ) No Scratches
  - ( ) W/ Scratches
- \*Encircle parts that has/have scratches

### COLOR

- ( ) Evenly Painted
- ( ) Not Evenly Painted

### BATTERY/ HORN

- ( ) Battery
- Brand: DOUGAL Battery Voltage: 12V
- ( ) Horn

### TIRES

- ( ) Good Quality
- ( ) Bad Quality
- Brand: CST
- Tire Pressure: Front \_\_\_\_\_ Rear \_\_\_\_\_

### PADS DIAGNOSTIC TOOL

- ( ) PADS Checkup

Fault :

Remarks :

### SADDLE

- ( ) Good Quality
- ( ) Bad Quality

### KEYS/ MANUAL/ TOOLS

- ( ) Master Key
- ( ) Duplicate Key
- ( ) Service Manual
- ( ) Warranty Booklet
- ( ) Set of Screw
- ( ) Battery Holder
- ( ) Plate Holder
- ( ) reflectors ( Optional )
- ( ) Under Body Caps ( Optional )
- ( ) 1 Set of Tools
- ( ) Rear Shock Adjuster
- ( ) Screw Driver
- ( ) Fuse Removal Tool
- ( ) Screw driver ( FLOWER KEY )
- ( ) Sparkplug Wrench

COMPLETE ACCESSORIES w/ BATTERY

I understand all the above items as explained to me by the releasing Officer/ Manager. I also agree that any failure on my part to adhere to any of the instructions given that may result in damages on the above mentioned parts will not be covered by warranty.

Inspected by :

Technician/PDI Personnel

Approved by :

Service Manager

Approved by :

Sales Department

CHECKLIST

Client :

VESPA  
Vespa Sprint

Chassis # :

PP8M8221  
NV077165  
M028M

Color:

12445

PAGE 2

WHITE

Make/Model :


JUSTIN B. 150

Engine # :

5178696

Date :

9-27-22



LEGEND

S- Scratched

L- Loose

D- Dented

M- Missing

DD-Damaged

F- Faded

Remarks:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

D. THE AMISAN





# AUTOHUB CAR CARE SERVICES (ACCS)

BY: SUPREME AUTOZONE PHILIPPINES INC.  
Sitio Buroi Cabrera Road, Brgy. San Juan, Taytay, Rizal  
Tel. No. (632) 533-6398  
VAT REG. TIN 236-978-189-00006

## BILLING STATEMENT

No: **06207**

Service Invoice

Page 1 of 1

Doc # : ATCJ E23236

CUSTOMER No. 211806	CUSTOMER NAME AND ADDRESS TIN: OTOTOITALIA PHILS. INC. #234 ORTIGAS AVENUE NORTH GREENHILLS SAN JUAN CITY MMN 000		ADVISOR Aldrin Padilla	COLOR 48054 WHITE/	TEAM NH GENER
DOC. DATE 27/12/22	REG. No. UNREG		YEAR/MAKE/MODEL 22/NEXTHUB/JUSTIN B 150	TAG No.	
STOCK No.	PURCHASE ORDER No.		MODEL No. UNREG	CAR LINE VESPA	ENG./TRANS.
DRIVER		CONTACT No.	CHASSIS No.	KILOMETERS	PROD. DATE
HOME PHONE		BUSINESS PHONE	CONTACT NAME	CONTRACT EXP. KMS	EXP. DATE
CA <input type="checkbox"/>	PC <input type="checkbox"/>	CH <input type="checkbox"/>	SELLING DEALER	DELIVERY KMS	DELIVERY DATE
C/C <input type="checkbox"/>	WAR <input type="checkbox"/>	INT <input type="checkbox"/>	DATE AND TIME PROMISED 27/12/22 09:00pm	TIME RECEIVED 11:25am	QUOTE PRICE
VEHICLE ID RP8M62221NV077165		ENGINE No. 5178702	AIR PWR TURBO		

Labour  
J# 1 76NAZZZZZ002

PDI CLEAN  
PDI UNIT  
\* BRAND NEW UNIT  
\* CHECKED AND EVALUATED CONCERN  
PERFORMED PDI INSPECTION

Tech(s) : 48055 3125.00

Total - Labour 3125.00

Totals=====

Total Labour..	3125.00
Total Parts..	0.00
Total Other..	0.00
Total P.O.L..	0.00
Total Misc...	0.00
VAT	375.00
Total Invoice	3500.00

*RJR*  
12/27/22

[ End of Invoice ]

ROAD TESTED		ACKNOWLEDGMENT	
ORDER NO.	SUBLET REPAIRS	RECEIVED above vehicle from AUTOHUB CAR CARE SERVICES (ACCS) in good condition and with all repair work enumerated completed to my satisfaction.	
		All works carried out at these premises are subject to a warranty of _____ days or _____ whichever comes first on all labor and materials.	
		SIGNATURE OF OWNER _____	

## CHECKLIST

12447

PAGE 1

Client: VESPA  
Vespa Sprint  
 Make/Model: JUSTIN B. 150

Chassis #: RP8M82221 q  
NV077166  
ms28m  
 Engine #: 5178702 q

Color: WHITE  
 Date: 9-27-22

### EMBLEMS

- ( ) Piaggio Emblem ( Front )  
 ( ) PVG Emblem ( Crankcase )

### SIDE MIRROR

- ( ) LH Side View Mirror  
 ( ) RH Side View Mirror

### ELECTRICAL BUTTONS

- ( ) Start Button  
 ( ) Horn Button  
 ( ) High&Low Button  
 ( ) Passing Button ( Optional )  
 ( ) Left Signal Button  
 ( ) Right Signal Button  
 ( ) Cut Off Engine Button ( Optional )  
 ( ) Start & Stop Button  
 ( ) ASR Button  
 ( ) Mode  
 ( ) Saddle Button  
 ( ) Toggle Switch

### LIGHTS

- ( ) Park Light  
 ( ) High & Low Beam  
 ( ) Front Right Signal  
 ( ) Rear Right Signal  
 ( ) Front Left Signal  
 ( ) Rear Left Signal  
 ( ) Backlight  
 ( ) Brakelights  
 ( ) Instrumental Panel Gauges  
 ( ) Plate Light

### FLUID LEVELS

- ( ) Engine Oil  
 ( ) Gear Oil  
 ( ) Brake Fluid  
 ( ) Coolant

### SCRATCHES

- ( ) No Scratches  
 ( ) W/ Scratches  
 \*Encircle parts that has/have scratches

### COLOR

- ( ) Evenly Painted  
 ( ) Not Evenly Painted

### BATTERY/ HORN

- ( ) Battery  
 Brand: DONGNAI Battery Voltage: 12V  
 ( ) Horn

### TIRES

- ( ) Good Quality  
 ( ) Bad Quality  
 Brand: CS  
 Tire Pressure: Front \_\_\_\_\_ Rear \_\_\_\_\_

### PADS DIAGNOSTIC TOOL

- ( ) PADS Checkup  
 Fault: \_\_\_\_\_  
 Remarks: \_\_\_\_\_

### SADDLE

- ( ) Good Quality  
 ( ) Bad Quality  
 KEYS/ MANUAL/ TOOLS  
 ( ) Master Key  
 ( ) Duplicate Key  
 ( ) Service Manual  
 ( ) Warranty Booklet  
 ( ) Set of Screw  
 ( ) Battery Holder  
 ( ) Plate Holder  
 ( ) reflectors ( Optional )  
 ( ) Under Body Caps ( Optional )  
 ( ) 1 Set of Tools  
 ( ) Rear Shock Adjuster  
 ( ) Screw Driver  
 ( ) Fuse Removal Tool  
 ( ) Screw driver ( FLOWER KEY )  
 ( ) Sparkplug Wrench

Remarks :

COMPLETE ACCESSORIES W/ BATTERY

I understand all the above items as explained to me by the releasing Officer/ Manager. I also agree that any failure on my part to adhere to any of the instructions given that may result in damages on the above mentioned parts will not be covered by warranty.

Inspected by : D. TH. AMISAN  
 Technician/PDI Personnel


Approved by : \_\_\_\_\_  
 Service Manager

Approved by : \_\_\_\_\_  
 Sales Department



CHECKLIST

Client: VESPA Vespa Sprint Chassis #: RF8M8221 Q 12447 PAGE 2  
 Make/Model: JUSTIN B. 150 Engine #: 5178702 Q Color: WHITE  
 Date: 9-27-22



LEGEND	
S- Scratched	L- Loose
D- Dented	M- Missing
DD-Damaged	F- Faded

Remarks:

Carving head. w/ Copper paint  
just board dent  
D. TALAMISAN



# AUTOHUB CAR CARE SERVICES (ACCS)

BY: SUPREME AUTOZONE PHILIPPINES INC.

Sitio Buroi Cabrera Road, Brgy. San Juan, Taytay, Rizal

Tel. No. : (632) 533-6398

VAT REG. TIN: 236-978-189-00006

## BILLING STATEMENT

No: **06208**

Service Invoice

Page 1 of 1

Doc # : ATCJ E23237

CUSTOMER No. 211806	CUSTOMER NAME AND ADDRESS TIN: OTOITALIA PHILS. INC. #234 ORTIGAS AVENUE NORTH GREENHILLS SAN JUAN CITY MMN 000	ADVISOR Aldrin Padilla	COLOR 48054 WHITE/	TEAM NH GENER
DOC. DATE 27/12/22		YEAR/MAKE/MODEL 22/NEXTHUB/SPRINT		TAG No.
REG. No. UNREG		MODEL No. UNREG	CAR LINE VESPA	ENG./TRANS.
STOCK No.		CHASSIS No.	KILOMETERS	PROD. DATE
PURCHASE ORDER No.	DRIVER	CONTACT No.	CONTACT NAME	CONTRACT EXP. KMS
CA <input type="checkbox"/>	HOME PHONE	BUSINESS PHONE	TERMS	DELIVERY KMS
QC <input type="checkbox"/>	VEHICLE ID	ENGINE No.	DATE AND TIME PROMISED	DELIVERY DATE
WAR <input type="checkbox"/>				QUOTE PRICE
INT <input type="checkbox"/>				AIR PWR TURBO
	RP8M82221NV07699	5178393	27/12/22 09:00pm	11:26am

Labour-----  
J# 1 76NAZZZZZ002  
PDI CLEAN  
\* PDI UNIT  
\* BRAND NEW UNIT  
\* CHECKED AND EVALUATED CONCERN  
PERFORMED PDI INSPECTION  
Tech(s) : 48048  
3125.00  
Total - Labour 3125.00

Totals=====

Total Labour.	3125.00
Total Parts..	0.00
Total Other..	0.00
Total P.O.L..	0.00
Total Misc...	0.00
VAT	375.00
Total Invoice	3500.00

*[Signature]*  
12/27/22

[ End of Invoice ]

ROAD TESTED	ACKNOWLEDGMENT	I AGREE TO PAY for all works required for all the above described repair at your retail charge. It is understood that any estimate given is provisional and all repairs are undertaken on a cash basis unless prior arrangements for credit have been approved.
ORDER NO	RECEIVED above vehicle from AUTOHUB CAR CARE SERVICES (ACCS) in good condition and with all repair work enumerated completed to my satisfaction.	I have READ AND ACCEPTED your terms and conditions
SUBLET REPAIRS	All works carried out at these premises are subject to a warranty of _____ days or _____ whichever comes first on all labor and materials.	
	SIGNATURE OF OWNER _____	



## CHECKLIST

12451

PAGE 1

Client :

Chassis # :

76991

Color :

White

Make/Model :

SPRINT

Engine # :

5178393

Date :

Sept 29 2022

### EMBLEMS

- ( ) Piaggio Emblem ( Front )
- ( ) PVG Emblem ( Crankcase )

### SIDE MIRROR

- ( ) LH Side View Mirror
- ( ) RH Side View Mirror

### ELECTRICAL BUTTONS

- ( ) Start Button
- ( ) Horn Button
- ( ) High&Low Button
- ( ) Passing Button ( Optional )
- ( ) Left Signal Button
- ( ) Right Signal Button
- ( ) Cut Off Engine Button ( Optional )
- ( ) Start & Stop Button
- ( ) ASR Button
- ( ) Mode
- ( ) Saddle Button
- ( ) Toggle Switch

### LIGHTS

- ( ) Park Light
- ( ) High & Low Beam
- ( ) Front Right Signal
- ( ) Rear Right Signal
- ( ) Front Left Signal
- ( ) Rear Left Signal
- ( ) Backlight
- ( ) Brakelights
- ( ) Instrumental Panel Gauges
- ( ) Plate Light

### FLUID LEVELS

- ( ) Engine Oil
- ( ) Gear Oil
- ( ) Brake Fluid
- ( ) Coolant

### SCRATCHES

- ( ) No Scratches
  - ( ) W/ Scratches
- \*Encircle parts that has/have scratches

### COLOR

- ( ) Evenly Painted
- ( ) Not Evenly Painted

### BATTERY/ HORN

- ( ) Battery
- Brand: Dynalene Battery Voltage: \_\_\_\_\_
- ( ) Horn

### TIRES

- ( ) Good Quality
- ( ) Bad Quality
- Brand: \_\_\_\_\_
- Tire Pressure: Front \_\_\_\_\_ Rear \_\_\_\_\_

### PADS DIAGNOSTIC TOOL

- ( ) PADS Checkup
- Fault : \_\_\_\_\_
- Remarks: \_\_\_\_\_

### SADDLE

- ( ) Good Quality
- ( ) Bad Quality
- KEYS/ MANUAL/ TOOLS
- ( ) Master Key
- ( ) Duplicate Key
- ( ) Service Manual
- ( ) Warranty Booklet
- ( ) Set of Screw
- ( ) Battery Holder
- ( ) Plate Holder
- ( ) reflectors ( Optional )
- ( ) Under Body Caps ( Optional )
- ( ) 1 Set of Tools
- ( ) Rear Shock Adjuster
- ( ) Screw Driver
- ( ) Fuse Removal Tool
- ( ) Screw driver ( FLOWER KEY )
- ( ) Sparkplug Wrench

Remarks :

Complete tools

I understand all the above items as explained to me by the releasing Officer/ Manager. I also agree that any failure on my part to adhere to any of the instructions given that may result in damages on the above mentioned parts will not be covered by warranty.

Inspected by :

Technician/PDI Personnel

Approved by :

Service Manager

Approved by :

Sales Department

CHECKLIST

12451

PAGE 2

Client :


Chassis # : 76991

Color: White

Make/Model : Sprint

Engine # : 5178393

Date : Sept 29 2022



LEGEND

S- Scratched	L- Loose
D- Dented	M- Missing
DD-Damaged	F- Faded

Remarks:

Complete fails  
Battery  
Chassis





# AUTOHUB CAR CARE SERVICES (ACCS)

BY: SUPREME AUTOZONE PHILIPPINES INC.

Sitio Buroi Cabrera Road, Brgy. San Juan, Taytay, Rizal

Tel No. (632) 533-8398

VAT REG. TIN: 236-978-189-00006

## BILLING STATEMENT

No: **06209**

Service Invoice		Page 1 of 1		Doc # : ATCJ E23238	
CUSTOMER No. 211806	CUSTOMER NAME AND ADDRESS TIN: MOTOITALIA PHILS. INC. #234 ORTIGAS AVENUE NORTH GREENHILLS SAN JUAN CITY MMN 000			ADVISOR Aldrin Padilla 48054	COLOR WHITE/
DOC. DATE 27/12/22	REG. No. UNREG	STOCK No.	YEAR/MAKE/MODEL 22/NEXTHUB/SPRINT	MODEL No. UNREG	CAR LINE VESPA
PURCHASE ORDER No.			DRIVER	CONTACT No.	CONTACT NAME
CA <input type="checkbox"/>	RIC <input type="checkbox"/>	CH <input type="checkbox"/>	HOME PHONE	BUSINESS PHONE	TERMS
QC <input type="checkbox"/>	WAR <input type="checkbox"/>	INT <input type="checkbox"/>	VEHICLE ID RP8M82221NV077003	ENGINE No. 5178186	DATE AND TIME PROMISED 27/12/22 09:00pm
			CHASSIS No.	KILOMETERS	PROD. DATE
			SELLING DEALER	DELIVERY KMS	DELIVERY DATE
				CONTRACT EXP. KMS	EXP. DATE
				TIME RECEIVED 11:29am	QUOTE PRICE
				AIR	PWR
				TURBO	

Labour  
J# 1 76NAZZZZZ002

\* PDI CLEAN  
\* PDI UNIT  
\* BRAND NEW UNIT  
\* CHECKED AND EVALUATED CONCERN  
\* PERFORMED PDI INSPECTION

Tech(s) : 48048

3125.00

Totals: Total - Labour 3125.00

Total Labour. 3125.00  
Total Parts.. 0.00  
Total Other.. 0.00  
Total P.O.L.. 0.00  
Total Misc... 0.00  
VAT 375.00

Total Invoice 3500.00

*[Signature]*  
R/27/22

[ End of Invoice ]

ROAD TESTED		ACKNOWLEDGMENT	
ORDER NO.	SUBLET REPAIRS	RECEIVED above vehicle from AUTOHUB CAR CARE SERVICES (ACCS) in good condition and with all repair work enumerated completed to my satisfaction.	
		All works carried out at these premises are subject to a warranty of _____ days or _____ whichever comes first on all labor and materials.	
		SIGNATURE OF OWNER _____	
		I AGREE TO PAY for all works required for all the above described repair at your retail charge. It is understood that any estimate given is provisional and all repairs are undertaken on a cash basis unless prior arrangements for credit have been approved.	
		I have READ AND ACCEPTED your terms and conditions.	

## CHECKLIST

12457

PAGE 1

Client :

Chassis # :

77003

Color:

white

Make/Model :

Sprint

Engine # :

5178186

Date :

Oct 1 2021

### EMBLEMS

- ( ) Piaggio Emblem ( Front )  
( ) PVG Emblem ( Crankcase )

### SIDE MIRROR

- ( ) LH Side View Mirror  
( ) RH Side View Mirror

### ELECTRICAL BUTTONS

- ( ) Start Button  
( ) Horn Button  
( ) High&Low Button  
( ) Passing Button ( Optional )  
( ) Left Signal Button  
( ) Right Signal Button  
( ) Cut Off Engine Button ( Optional )  
( ) Start & Stop Button  
( ) ASR Button  
( ) Mode  
( ) Saddle Button  
( ) Toggle Switch

### LIGHTS

- ( ) Park Light  
( ) High & Low Beam  
( ) Front Right Signal  
( ) Rear Right Signal  
( ) Front Left Signal  
( ) Rear Left Signal  
( ) Backlight  
( ) Brakelights  
( ) Instrumental Panel Gauges  
( ) Plate Light

### FLUID LEVELS

- ( ) Engine Oil  
( ) Gear Oil  
( ) Brake Fluid  
( ) Coolant

Remarks :

Complete tools

Battery  
accessories

### SCRATCHES

- ( ) No Scratches  
( ) W/ Scratches  
\*Encircle parts that has/have scratches

### COLOR

- ( ) Evenly Painted  
( ) Not Evenly Painted

### BATTERY/ HORN

- ( ) Battery  
Brand: Durocell Battery Voltage: \_\_\_\_\_  
( ) Horn

### TIRES

- ( ) Good Quality  
( ) Bad Quality  
Brand: \_\_\_\_\_  
Tire Pressure: Front \_\_\_\_\_ Rear \_\_\_\_\_

### PADS DIAGNOSTIC TOOL

- ( ) PADS Checkup  
Fault : \_\_\_\_\_  
Remarks: \_\_\_\_\_

### SADDLE

- ( ) Good Quality  
( ) Bad Quality  
KEYS/ MANUAL/ TOOLS  
( ) Master Key  
( ) Duplicate Key  
( ) Service Manual  
( ) Warranty Booklet  
( ) Set of Screw  
( ) Battery Holder  
( ) Plate Holder  
( ) reflectors ( Optional )  
( ) Under Body Caps ( Optional )  
( ) 1 Set of Tools  
( ) Rear Shock Adjuster  
( ) Screw Driver  
( ) Fuse Removal Tool  
( ) Screw driver ( FLOWER KEY )  
( ) Sparkplug Wrench

I understand all the above items as explained to me by the releasing Officer/ Manager. I also agree that any failure on my part to adhere to any of the instructions given that may result in damages on the above mentioned parts will not be covered by warranty.

Inspected by :

J. Ely

Approved by :

Approved by :

Technician/PDI Personnel

Service Manager

Sales Department



CHECKLIST

12457

PAGE 2

Client :

Chassis # :

77003

Color:

white

Make/Model :


SPRINT

Engine # :

5178186

Date :

Oct. 1 2021



LEGEND

S- Scratched

L- Loose

D- Dented

M- Missing

DD-Damaged

F- Faded

Remarks:

Complete fault



# AUTOHUB CAR CARE SERVICES (ACCS)

BY: SUPREME AUTOZONE PHILIPPINES INC.

Sitio Buroi Cabrera Road, Brgy. San Juan, Taytay Rizal

Tel No (632) 533-8398

VAT REG TIN 236-978-189-00006

## BILLING STATEMENT

No: **06210**

Service Invoice		Page 1 of 1		Doc # : ATCJ E23239	
CUSTOMER No. 211806	CUSTOMER NAME AND ADDRESS TINOTOTALIA PHILS. INC. #234 ORTIGAS AVENUE NORTH GREENHILLS SAN JUAN CITY MMN 000			ADVISOR Aldrin Padilla	COLOR 48054 WHITE/
DOC. DATE 27/12/22				YEAR/MAKE/MODEL 22/NEXTHUB/SPRINT	TEAM NH GENER
REG. No. UNREG				MODEL No. UNREG	TAG No.
STOCK No.				CHASSIS No.	ENG./TRANS.
PURCHASE ORDER No.	DRIVER	CONTACT No.	CONTACT NAME	CONTRACT EXR KMS	EXP. DATE
CA <input type="checkbox"/>	R/C <input type="checkbox"/>	CH <input type="checkbox"/>	HOME PHONE	BUSINESS PHONE	TERMS
C/C <input type="checkbox"/>	WAR <input type="checkbox"/>	INT <input type="checkbox"/>	VEHICLE ID RP8M82221NV07699	ENGINE No. 5178175	Charge
			DATE AND TIME PROMISED 27/12/22 09:00pm	TIME RECEIVED 11:29am	QUOTE PRICE
			AIR PWR TURBO		

Labour  
J# 1 76NAZZZZ002

PDI CLEAN  
\* PDI UNIT  
\* BRAND NEW UNIT  
\* CHECKED AND EVALUATED CONCERN  
\* PERFORMED PDI INSPECTION

Tech(s) : 011 3125.00

Total - Labour 3125.00

Totals=====

Total Labour.	3125.00
Total Parts..	0.00
Total Other..	0.00
Total P.O.L..	0.00
Total Misc...	0.00
VAT	375.00
Total Invoice	3500.00

*RJR*  
12/27/22

[ End of Invoice ]

ROAD TESTED		<b>ACKNOWLEDGMENT</b>	
ORDER NO.	SUBLET REPAIRS	RECEIVED above vehicle from AUTOHUB CAR CARE SERVICES (ACCS) in good condition and with all repair work enumerated completed to my satisfaction.	
		All works carried out at these premises are subject to a warranty of _____ days or _____ whichever comes first on all labor and materials.	
		SIGNATURE OF OWNER _____	
		I AGREE TO PAY for all works required for all the above described repair at your retail charge. It is understood that any estimate given is provisional and all repairs are undertaken on a cash basis unless prior arrangements for credit have been approved.	
		I have READ AND ACCEPTED your terms and conditions.	



## CHECKLIST

12470

PAGE 1

Client : VESPA

Chassis # : 076994

Color: white

Make/Model : Sprint

Engine # : 5178175

Date : 10/1/2011

### EMBLEMS

- ( ) Piaggio Emblem ( Front )  
( ) PVG Emblem ( Crankcase )

### SIDE MIRROR

- ( ) LH Side View Mirror  
( ) RH Side View Mirror

### ELECTRICAL BUTTONS

- ( ) Start Button  
( ) Horn Button  
( ) High&Low Button  
( ) Passing Button ( Optional )  
( ) Left Signal Button  
( ) Right Signal Button  
( ) Cut Off Engine Button ( Optional )  
( ) Start & Stop Button  
( ) ASR Button  
( ) Mode  
( ) Saddle Button  
( ) Toggle Switch

### LIGHTS

- ( ) Park Light  
( ) High & Low Beam  
( ) Front Right Signal  
( ) Rear Right Signal  
( ) Front Left Signal  
( ) Rear Left Signal  
( ) Backlight  
( ) Brakelights  
( ) Instrumental Panel Gauges  
( ) Plate Light

### FLUID LEVELS

- ( ) Engine Oil  
( ) Gear Oil  
( ) Brake Fluid  
( ) Coolant

### SCRATCHES

- ( ) No Scratches  
( ) W/ Scratches  
\*Encircle parts that has/have scratches

### COLOR

- ( ) Evenly Painted  
( ) Not Evenly Painted

### BATTERY/ HORN

- ( ) Battery  
Brand: \_\_\_\_\_ Battery Voltage: \_\_\_\_\_  
( ) Horn

### TIRES

- ( ) Good Quality  
( ) Bad Quality  
Brand: \_\_\_\_\_  
Tire Pressure: \_\_\_\_\_ Front \_\_\_\_\_ Rear \_\_\_\_\_

### PADS DIAGNOSTIC TOOL

- ( ) PADS Checkup  
Fault : \_\_\_\_\_  
Remarks: \_\_\_\_\_

### SADDLE

- ( ) Good Quality  
( ) Bad Quality  
KEYS/ MANUAL/ TOOLS  
( ) Master Key  
( ) Duplicate Key  
( ) Service Manual  
( ) Warranty Booklet  
( ) Set of Screw  
( ) Battery Holder  
( ) Plate Holder  
( ) reflectors ( Optional )  
( ) Under Body Caps ( Optional )  
( ) 1 Set of Tools  
( ) Rear Shock Adjuster  
( ) Screw Driver  
( ) Fuse Removal Tool  
( ) Screw driver ( FLOWER KEY )  
( ) Sparkplug Wrench

Remarks :

I understand all the above items as explained to me by the releasing Officer/ Manager. I also agree that any failure on my part to adhere to any of the instructions given that may result in damages on the above mentioned parts will not be covered by warranty.

Inspected by : Arcebes  
Technician/PDI Personnel

Approved by : \_\_\_\_\_  
Service Manager

Approved by : \_\_\_\_\_  
Sales Department



CHECKLIST

Client: VESPA

Chassis #: 076994


12470  
Color: white

PAGE 2

Make/Model: SPRINT

Engine #: 3178175

Date: 10/1/22



LEGEND

S- Scratched	L- Loose
D- Dented	M- Missing
DD-Damaged	F- Faded

Remarks:

complete tools, Accessories, battery, side mirror