



AUTOHUB CAR CARE SERVICES (ACCS)

BY: SUPREME AUTOZONE PHILIPPINES INC.

Sitio Buroi Cabrera Road, Brgy. San Juan, Taytay, Rizal

Tel. No.: (632) 533-6398

VAT REG. TIN: 236-978-189-00006

BILLING STATEMENT

No: **06768**

Service Invoice		Page 1 of 1		Doc # : ATCJ E23979		
CUSTOMER No. 211806	CUSTOMER NAME AND ADDRESS TIN: AUTOITALIA PHILS. INC. #234 ORTIGAS AVENUE NORTH GREENHILLS SAN JUAN CITY MMN 000			ADVISOR Hidrin Padilla	COLOR 480 4 BLACK/	TEAM NA GENER
DOC. DATE 27/02/23				YEAR/MAKE/MODEL 22/NEXTHUB/VESPA	TAG No.	
REG. No. UNREG				MODEL No. 5125	CAR LINE VESPA	ENG./TRANS.
STOCK No.				CHASSIS No.	KILOMETERS	PROD. DATE
PURCHASE ORDER No.	DRIVER	CONTACT No.		CONTACT NAME	CONTRACT EXP. KMS	EXP. DATE
CA <input type="checkbox"/>	P/C <input type="checkbox"/>	CH <input type="checkbox"/>	HOME PHONE	BUSINESS PHONE	TERMS	SELLING DEALER
O/C <input type="checkbox"/>	WAR <input type="checkbox"/>	INT <input type="checkbox"/>	VEHICLE ID RP8M6670INV0391	ENGINE No. 1 M66BM5103684	DATE AND TIME PROMISED 25/02/23 09:00pm	DELIVERY KMS
				TIME RECEIVED 10:06am	QUOTE PRICE	AIR PWR TURBO

Labour
J# 1 76NAZZZZZ002

* PDI CLEAN
* PDI INSPECTION
* BRAND NEW UNIT
* CHECKED AND EVALUATED CONCERN:
PERFORMED PDI INSPECTION

Tech(s) : 48055

3125.00

Total - Labour 3125.00

Totals=====

Total Labour. 3125.00
Total Parts.. 0.00
Total Other.. 0.00
Total P.O.L.. 0.00
Total Misc... 0.00
VAT 375.00

Total Invoice 3500.00

Handwritten signature
02/23/23

[End of Invoice]

ROAD TESTED		ACKNOWLEDGMENT	
ORDER NO.	SUBLET REPAIRS	RECEIVED above vehicle from AUTOHUB CAR CARE SERVICES (ACCS) in good condition and with all repair work enumerated completed to my satisfaction.	
		All works carried out at these premises are subject to a warranty of _____ days or _____ whichever comes first on all labor and materials.	
		SIGNATURE OF OWNER _____	

CHECKLIST

10921

PAGE 1

RRKMEBNO1M4

Client : VESPA

Chassis # : 039131

Color : BLK.

Make/Model : SI25

Engine # : 510 3684

Date : 10-12-22

EMBLEMS

- (☒) Piaggio Emblem (Front)
- (☒) PVG Emblem (Crankcase)

SIDE MIRROR

- (☒) LH Side View Mirror
- (☒) RH Side View Mirror

ELECTRICAL BUTTONS

- (☒) Start Button
- (☒) Horn Button
- (☒) High&Low Button
- (☐) Passing Button (Optional)
- (☒) Left Signal Button
- (☒) Right Signal Button
- (☐) Cut Off Engine Button (Optional)
- (☐) Start & Stop Button
- (☐) ASR Button
- (☒) Mode
- (☐) Saddle Button
- (☐) Toggle Switch

LIGHTS

- (☒) Park Light
- (☒) High & Low Beam
- (☒) Front Right Signal
- (☒) Rear Right Signal
- (☒) Front Left Signal
- (☒) Rear Left Signal
- (☒) Backlight
- (☒) Brakelights
- (☒) Instrumental Panel Gauges
- (☒) Plate Light

FLUID LEVELS

- (☒) Engine Oil
- (☒) Gear Oil
- (☒) Brake Fluid
- (☐) Coolant

SCRATCHES

- (☐) No Scratches
 - (☒) W/ Scratches
- *Encircle parts that has/have scratches

COLOR

- (☐) Evenly Painted
- (☒) Not Evenly Painted

BATTERY/ HORN

- (☒) Battery
- Brand : ORIGINAL Battery Voltage : 12V
- (☒) Horn

TIRES

- (☒) Good Quality
- (☐) Bad Quality
- Brand : MAXXIS
- Tire Pressure : Front _____ Rear _____

PADS DIAGNOSTIC TOOL

- (☐) PADS Checkup
- Fault : _____
- Remarks : _____

SADDLE

- (☒) Good Quality
- (☐) Bad Quality
- KEYS/ MANUAL/ TOOLS**
- (☒) Master Key
- (☒) Duplicate Key
- (☒) Service Manual
- (☒) Warranty Booklet
- (☐) Set of Screw
- (☒) Battery Holder
- (☐) Plate Holder
- (☒) reflectors (Optional)
- (☒) Under Body Caps (Optional)
- (☐) 1 Set of Tools
- (☒) Rear Shock Adjuster
- (☒) Screw Driver
- (☐) Fuse Removal Tool
- (☐) Screw driver (FLOWER KEY)
- (☒) Sparkplug Wrench

Remarks :

COMPLETE ACCESSORIES W/ BATTERY

I understand all the above items as explained to me by the releasing Officer/ Manager. I also agree that any failure on my part to adhere to any of the instructions given that may result in damages on the above mentioned parts will not be covered by warranty.

Inspected by : D. HANAN
Technician/PDI Personnel

Approved by : _____
Service Manager

Approved by : _____
Sales Department

CHECKLIST

PAGE 2

Client :

VESPA

Chassis # :

039131

Color:

BK.

Make/Model :


S125

Engine # :

5103084

Date :

10-12-22



LEGEND

S- Scratched

D- Dented

DD-Damaged

L- Loose

M- Missing

F- Faded

Remarks:

D. TALAMISAN



AUTOHUB CAR CARE SERVICES (ACCS)

BY: SUPREME AUTOZONE PHILIPPINES INC.

Sitio Buroi Cabrera Road, Brgy. San Juan, Taytay, Rizal

Tel. No.: (632) 533-6398

VAT REG. TIN: 236-978-189-00006

BILLING STATEMENT

No: **06769**

Service Invoice		Page 1 of 1		Doc # : ATCJ E23980	
CUSTOMER No. 211806	CUSTOMER NAME AND ADDRESS MOTOTITALIA PHILS. INC.		ADVISOR Aldrin Padilla	COLOR 480 GREY/	TEAM NH GENER
DOC. DATE 27/02/23	#234 ORTIGAS AVENUE		YEAR/MAKE/MODEL 22/NEXTHUB/5125	TAG No.	
REG. No. UNREG	NORTH GREENHILLS		MODEL No. 5125	CAR LINE VESPA	ENG./TRANS.
STOCK No.	SAN JUAN CITY MMN 000		CHASSIS No.	KILOMETERS	PROD. DATE
PURCHASE ORDER No.	DRIVER	CONTACT No.	CONTACT NAME	CONTRACT EXP. KMS	EXP. DATE
CA <input type="checkbox"/>	F/C <input type="checkbox"/>	CH <input type="checkbox"/>	HOME PHONE	BUSINESS PHONE	TERMS
O/C <input type="checkbox"/>	WAR <input type="checkbox"/>	INT <input type="checkbox"/>	VEHICLE ID RP8M66701NV039058	ENGINE No. M668M5102619	DATE AND TIME PROMISED 25/02/23 09:00pm
			SELLING DEALER	DELIVERY KMS	DELIVERY DATE
			TIME RECEIVED 10:06am	QUOTE PRICE	AIR PWR TURBO

Labour
J# 1 76NAZZZZ7002

* PDI CLEAN
* PDI INSPECTION
* BRAND NEW UNIT
* CHECKED AND EVALUATED CONCERN:
PERFORMED PDI INSPECTION

Tech(s) : 48057

3125.00

Total - Labour 3125.00

Totals=====

Total Labour. 3125.00
Total Parts.. 0.00
Total Other.. 0.00
Total P.O.L.. 0.00
Total Misc... 0.00
VAT 375.00

Total Invoice 3500.00

[Signature]
02/27/23

[End of Invoice]

ROAD TESTED		ACKNOWLEDGMENT	
ORDER NO.	SUBLET REPAIRS	RECEIVED above vehicle from AUTOHUB CAR CARE SERVICES (ACCS) in good condition and with all repair work enumerated completed to my satisfaction.	
		All works carried out at these premises are subject to a warranty of _____ days or _____ whichever comes first on all labor and materials.	
		SIGNATURE OF OWNER _____	
		I AGREE TO PAY for all works required for all the above described repair at your retail charge. It is understood that any estimate given is provisional and all repairs are undertaken on a cash basis unless prior arrangements for credit have been approved.	
		I have READ AND ACCEPTED your terms and conditions	

CHECKLIST

10894

PAGE 1

Client :

Chassis # :

Color :

Make/Model :

Engine # :

Date :

EMBLEMS

- () Piaggio Emblem (Front)
() PVG Emblem (Crankcase)

SIDE MIRROR

- () LH Side View Mirror
() RH Side View Mirror

ELECTRICAL BUTTONS

- () Start Button
() Horn Button
() High&Low Button
() Passing Button (Optional)
() Left Signal Button
() Right Signal Button
() Cut Off Engine Button (Optional)
() Start & Stop Button
() ASR Button
() Mode
() Saddle Button
() Toggle Switch

LIGHTS

- () Park Light
() High & Low Beam
() Front Right Signal
() Rear Right Signal
() Front Left Signal
() Rear Left Signal
() Backlight
() Brakelights
() Instrumental Panel Gauges
() Plate Light

FLUID LEVELS

- () Engine Oil
() Gear Oil
() Brake Fluid
() Coolant

SCRATCHES

- () No Scratches
() W/ Scratches
*Encircle parts that has/have scratches

COLOR

- () Evenly Painted
() Not Evenly Painted

BATTERY/ HORN

- () Battery
Brand: PYRUS Battery Voltage: 12V 20AH (bnc)
() Horn

TIRES

- () Good Quality
() Bad Quality
Brand: _____
Tire Pressure: Front _____ Rear _____

PADS DIAGNOSTIC TOOL

- () PADS Checkup
Fault : _____
Remarks: _____

SADDLE

- () Good Quality
() Bad Quality
KEYS/ MANUAL/ TOOLS
() Master Key
() Duplicate Key
() Service Manual
() Warranty Booklet
() Set of Screw
() Battery Holder
() Plate Holder
() reflectors (Optional)
() Under Body Caps (Optional)
() 1 Set of Tools
() Rear Shock Adjuster
() Screw Driver
() Fuse Removal Tool
() Screw driver (FLOWER KEY)
() Sparkplug Wrench

Remarks :

I understand all the above items as explained to me by the releasing Officer/ Manager. I also agree that any failure on my part to adhere to any of the instructions given that may result in damages on the above mentioned parts will not be covered by warranty.

Inspected by :

Approved by :

Approved by :

Technician/PDI Personnel

Service Manager

Sales Department

CHECKLIST

PAGE 2

Client :

Chassis # :

Color:

Make/Model :

Engine # :

Date :

RD6MB60114

10894


039058

GRAY

S125

5102619

10/10/22



LEGEND

S- Scratched

L- Loose

D- Dented

M- Missing

DD-Damaged

F- Faded

Remarks:

CHECKLIST

Client :

Chassis # :

Color :

10893

PAGE 1

Make/Model :

Engine # :

Date :

EMBLEMS

- () Piaggio Emblem (Front)
() PVG Emblem (Crankcase)

SIDE MIRROR

- () LH Side View Mirror
() RH Side View Mirror

ELECTRICAL BUTTONS

- () Start Button
() Horn Button
() High&Low Button
() Passing Button (Optional)
() Left Signal Button
() Right Signal Button
() Cut Off Engine Button (Optional)
() Start & Stop Button
() ASR Button
() Mode
() Saddle Button
() Toggle Switch

LIGHTS

- () Park Light
() High & Low Beam
() Front Right Signal
() Rear Right Signal
() Front Left Signal
() Rear Left Signal
() Backlight
() Brakelights
() Instrumental Panel Gauges
() Plate Light

FLUID LEVELS

- () Engine Oil
() Gear Oil
() Brake Fluid
() Coolant

SCRATCHES

- () No Scratches
() W/ Scratches
*Encircle parts that has/have scratches

COLOR

- () Evenly Painted
() Not Evenly Painted

BATTERY/ HORN

- () Battery
Brand: Donghai Battery Voltage: _____
() Horn

TIRES

- () Good Quality
() Bad Quality
Brand: _____
Tire Pressure: _____ Front _____ Rear _____

PADS DIAGNOSTIC TOOL

- () PADS Checkup
Fault : _____
Remarks: _____

SADDLE

- () Good Quality
() Bad Quality
KEYS/ MANUAL/ TOOLS
() Master Key
() Duplicate Key
() Service Manual
() Warranty Booklet
() Set of Screw
() Battery Holder
() Plate Holder
() reflectors (Optional)
() Under Body Caps (Optional)
() 1 Set of Tools
() Rear Shock Adjuster
() Screw Driver
() Fuse Removal Tool
() Screw driver (FLOWER KEY)
() Sparkplug Wrench

Remarks :

Complete fault

Battery

Accessories

I understand all the above items as explained to me by the releasing Officer/ Manager. I also agree that any failure on my part to adhere to any of the instructions given that may result in damages on the above mentioned parts will not be covered by warranty.

Inspected by :

Approved by :

Approved by :

Technician/PDI Personnel

Service Manager

Sales Department

CHECKLIST

RR8Mde701RV

10893

PAGE 2

Client :

Chassis # :

039040

Color:

Gray

Make/Model :


S125

Engine # :

5101485

Date :

10-10-22



LEGEND

S- Scratched

D- Dented

DD-Damaged

L- Loose

M- Missing

F- Faded

Remarks:

Complete full
Battery
Accessories



AUTOHUB CAR CARE SERVICES (ACCS)

BY: SUPREME AUTOZONE PHILIPPINES INC.

Sitio Buroi Cabrera Road, Brgy. San Juan, Taytay, Rizal

Tel. No.: (632) 533-6398

VAT REG. TIN: 236-978-189-00006

BILLING STATEMENT

No: **06771**

Service Invoice		Page 1 of 1		Doc # : ATCJ E23982	
CUSTOMER No. 211806	CUSTOMER NAME AND ADDRESS TIN: TOTOTALIA PHILS. INC. #234 ORTIGAS AVENUE NORTH GREENHILLS SAN JUAN CITY MMN 000			ADVISOR Aldrin Padilla	COLOR 4804 GREEN/
DOC. DATE 27/02/23	REG. No. UNREG			YEAR/MAKE/MODEL 22/NEXTHUB/VESPA S125	TEAM NH GENER
STOCK No.	PURCHASE ORDER No.			MODEL No. S125	TAG No.
DRIVER		CONTACT No.		CHASSIS No.	ENG./TRANS.
HOME PHONE		BUSINESS PHONE		CONTACT NAME	KILOMETERS
VEHICLE ID RP8M66701NV040206		ENGINE No. M66BM5109379		CONTRACT EXP. KMS	PROD. DATE
CA <input type="checkbox"/>		F/C <input type="checkbox"/>		SELLING DEALER	EXP. DATE
C/C <input type="checkbox"/>		WAR <input type="checkbox"/>		DELIVERY KMS	DELIVERY DATE
CH <input type="checkbox"/>		INT <input type="checkbox"/>		DATE AND TIME PROMISED 25/02/23 09:00pm	QUOTE PRICE
				TIME RECEIVED 10:07am	AIR PWR TURBO

Labour
JH 1 76NAZZZZZ002

* PDI CLEAN
* PDI INSPECTION
* BRAND NEW UNIT
* CHECKED AND EVALUATED CONCERN:
PERFORMED PDI INSPECTION

Tech(s) : 48057

3125.00

Totals=====

Total - Labour 3125.00

Total Labour. 3125.00
Total Parts.. 0.00
Total Other.. 0.00
Total P.O.L.. 0.00
Total Misc... 0.00
VAT 375.00

Total Invoice 3500.00

[Signature]
02/27/23

[End of Invoice]

ROAD TESTED		ACKNOWLEDGMENT	
ORDER NO.	SUBLET REPAIRS	RECEIVED above vehicle from AUTOHUB CAR CARE SERVICES (ACCS) in good condition and with all repair work enumerated completed to my satisfaction	I AGREE TO PAY for all works required for all the above described repair at your retail charge. It is understood that any estimate given is provisional and all repairs are undertaken on a cash basis unless prior arrangements for credit have been approved.
		All works carried out at these premises are subject to a warranty of _____ days or _____ whichever comes first on all labor and materials.	I have READ AND ACCEPTED your terms and conditions.
		SIGNATURE OF OWNER _____	

CHECKLIST

10187

PAGE 1

Client :

Chassis # :

Color :

Make/Model :

Engine # :

Date :

EMBLEMS

- ☒ Piaggio Emblem (Front)
- ☒ PVG Emblem (Crankcase)

SIDE MIRROR

- ☒ LH Side View Mirror
- ☒ RH Side View Mirror

ELECTRICAL BUTTONS

- ☒ Start Button
- ☒ Horn Button
- ☒ High&Low Button
- ☒ Passing Button (Optional)
- ☒ Left Signal Button
- ☒ Right Signal Button
- ☒ Cut Off Engine Button (Optional)
- ☒ Start & Stop Button
- ☒ ASR Button
- ☒ Mode
- ☒ Saddle Button
- ☒ Toggle Switch

LIGHTS

- ☒ Park Light
- ☒ High & Low Beam
- ☒ Front Right Signal
- ☒ Rear Right Signal
- ☒ Front Left Signal
- ☒ Rear Left Signal
- ☒ Backlight
- ☒ Brakelights
- ☒ Instrumental Panel Gauges
- ☒ Plate Light

FLUID LEVELS

- ☒ Engine Oil
- ☒ Gear Oil
- ☒ Brake Fluid
- ☒ Coolant

SCRATCHES

- ☐ No Scratches
- ☐ W/ Scratches

*Encircle parts that has/have scratches

COLOR

- ☐ Evenly Painted
- ☐ Not Evenly Painted

BATTERY/ HORN

- ☒ Battery
- Brand: Dongrai Battery Voltage: _____
- ☒ Horn

TIRES

- ☐ Good Quality
- ☐ Bad Quality
- Brand: _____
- Tire Pressure: Front _____ Rear _____

PADS DIAGNOSTIC TOOL

- ☐ PADS Checkup
- Fault : _____
- Remarks: _____

SADDLE

- ☐ Good Quality
- ☐ Bad Quality
- KEYS/MANUAL/ TOOLS**
- ☒ Master Key
- ☒ Duplicate Key
- ☒ Service Manual
- ☒ Warranty Booklet
- ☒ Set of Screw
- ☒ Battery Holder
- ☒ Plate Holder
- ☒ reflectors (Optional)
- ☒ Under Body Caps (Optional)
- ☒ 1 Set of Tools
- ☒ Rear Shock Adjuster
- ☒ Screw Driver
- ☒ Fuse Removal Tool
- ☒ Screw driver (FLOWER KEY)
- ☒ Sparkplug Wrench

Remarks :

complete tools. accs. got by

I understand all the above items as explained to me by the releasing Officer/ Manager. I also agree that any failure on my part to adhere to any of the instructions given that may result in damages on the above mentioned parts will not be covered by warranty.

Inspected by :

Approved by :

Approved by :

Technician/PDI Personnel

Service Manager

Sales Department

CHECKLIST

Client :

Chassis # :

Color:

10187

PAGE 2

Make/Model :

Engine # :


Date :

5125

7017V
RPM 1000
040206

5109379

10/21/22



LEGEND

S- Scratched

D- Dented

DD-Damaged

L- Loose

M- Missing

F- Faded

Remarks:



AUTOHUB CAR CARE SERVICES (ACCS)

BY: SUPREME AUTOZONE PHILIPPINES INC.

Sitio Buroi Cabrera Road, Brgy. San Juan, Taytay, Rizal

Tel. No. (632) 533-6398

VAT REG TIN 236-978-189-00006

BILLING STATEMENT

No: **06772**

Service Invoice		Page 1 of 1		Doc # : ATCJ E23983	
CUSTOMER No. 211806	CUSTOMER NAME AND ADDRESS MOTOITALIA PHILS. INC. #234 ORTIGAS AVENUE NORTH GREENHILLS SAN JUAN CITY MMN 000			ADVISOR Aldrin Padilla	COLOR 48034 WHITE/
DOC. DATE 27/02/23				YEAR/MAKE/MODEL 22/NEXTHUB/VESPA S125 3V	TEAM NH GENER
REG. No. UNREG				MODEL No. S125 3V	TAG No.
STOCK No.				CHASSIS No.	ENG./TRANS.
PURCHASE ORDER No.	DRIVER	CONTACT No.	CONTACT NAME	CONTRACT EXP. KMS	EXP. DATE
CA <input type="checkbox"/>	F/C <input type="checkbox"/>	CH <input type="checkbox"/>	HOME PHONE	BUSINESS PHONE	TERMS
C/C <input type="checkbox"/>	WAR <input type="checkbox"/>	INT <input type="checkbox"/>	VEHICLE ID RP8M66701NV039608	ENGINE No. M66BM5106350	Charge
			DATE AND TIME PROMISED 25/02/23 09:00pm	TIME RECEIVED 10:08am	QUOTE PRICE
					AIR PWR TURBO

Labour
J# 1 76NAZZZZZ002

PDI CLEAN
* PDI INSPECTION
* BRAND NEW UNIT
* CHECKED AND EVALUATED CONCERN
PERFORMED PDI INSPECTION

Tech(s) : 48063

3125.00

Totals=====

Total - Labour 3125.00

Total Labour. 3125.00
Total Parts.. 0.00
Total Other.. 0.00
Total P.O.L.. 0.00
Total Misc... 0.00
VAT 375.00

Total Invoice 3500.00

RJR
02/07/23

[End of Invoice]

ROAD TESTED		ACKNOWLEDGMENT	
ORDER NO.	SUBLET REPAIRS	RECEIVED above vehicle from AUTOHUB CAR CARE SERVICES (ACCS) in good condition and with all repair work enumerated completed to my satisfaction.	
		All works carried out at these premises are subject to a warranty of _____ days or _____ whichever comes first on all labor and materials.	
		SIGNATURE OF OWNER _____	
		I AGREE TO PAY for all works required for all the above described repair at your retail charge. It is understood that any estimate given is provisional and all repairs are undertaken on a cash basis unless prior arrangements for credit have been approved.	
		I have READ AND ACCEPTED your terms and conditions.	

CHECKLIST

10724

PAGE 1

Client: VESPA

Chassis #: RP8M66701NV039608

Color: WHITE

Make/Model: VESPA S125 3V

Engine #: M66BM S106350

Date: 10-26-22

EMBLEMS

- ☒ Piaggio Emblem (Front)
- ☒ PVG Emblem (Crankcase)

SIDE MIRROR

- ☒ LH Side View Mirror
- ☒ RH Side View Mirror

ELECTRICAL BUTTONS

- ☒ Start Button
- ☒ Horn Button
- ☒ High&Low Button
- ☒ Passing Button (Optional)
- ☒ Left Signal Button
- ☒ Right Signal Button
- ☒ Cut Off Engine Button (Optional)
- ☒ Start & Stop Button
- ☐ ASR Button
- ☐ Mode
- ☐ Saddle Button
- ☐ Toggle Switch

LIGHTS

- ☒ Park Light
- ☒ High & Low Beam
- ☒ Front Right Signal
- ☒ Rear Right Signal
- ☒ Front Left Signal
- ☒ Rear Left Signal
- ☒ Backlight
- ☒ Brakelights
- ☒ Instrumental Panel Gauges
- ☒ Plate Light

FLUID LEVELS

- ☒ Engine Oil
- ☒ Gear Oil
- ☒ Brake Fluid
- ☒ Coolant

SCRATCHES

- ☒ No Scratches
 - ☐ W/ Scratches
- *Encircle parts that has/have scratches

COLOR

- ☐ Evenly Painted
- ☐ Not Evenly Painted

BATTERY/ HORN

- ☐ Battery
- Brand: _____ Battery Voltage: _____
- ☐ Horn

TIRES

- ☒ Good Quality
- ☐ Bad Quality
- Brand: _____
- Tire Pressure: _____ Front _____ Rear _____

PADS DIAGNOSTIC TOOL

- ☐ PADS Checkup
- Fault: _____
- Remarks: _____

SADDLE

- ☒ Good Quality
- ☐ Bad Quality
- KEYS/ MANUAL/ TOOLS**
- ☒ Master Key
- ☒ Duplicate Key
- ☒ Service Manual
- ☒ Warranty Booklet
- ☒ Set of Screw
- ☒ Battery Holder
- ☐ Plate Holder
- ☒ reflectors (Optional)
- ☐ Under Body Caps (Optional)
- ☒ 1 Set of Tools
- ☒ Rear Shock Adjuster
- ☒ Screw Driver
- ☐ Fuse Removal Tool
- ☒ Screw driver (FLOWER KEY)
- ☐ Sparkplug Wrench

Remarks: BUFFING ALL PANEL

I understand all the above items as explained to me by the releasing Officer/ Manager. I also agree that any failure on my part to adhere to any of the instructions given that may result in damages on the above mentioned parts will not be covered by warranty.

Inspected by: Nestor Acut

Approved by: _____

Approved by: _____

Technician/PDI Personnel

Service Manager

Sales Department

CHECKLIST

10724

PAGE 2


Client: VESPA

Chassis #: RP6M66701NV03998 Color: WHITE

Make/Model: VESPA 8 125 3V

Engine #: M66BM 5106350

Date: 10-26-22



LEGEND

S- Scratched	L- Loose
D- Dented	M- Missing
DD- Damaged	F- Faded

Remarks:

BUFFING ALL PANEL



AUTOHUB CAR CARE SERVICES (ACCS)

BY: SUPREME AUTOZONE PHILIPPINES INC.

Sitio Buroi Cabrera Road, Brgy. San Juan, Taytay, Rizal

Tel No (632) 533-6398

VAT REG TIN 236-978-189-00006

BILLING STATEMENT

No: **06773**

Service Invoice		Page 1 of 1		Doc # : ATCJ E23984	
CUSTOMER No. 211806	CUSTOMER NAME AND ADDRESS TIN: MOTOITALIA PHILS. INC. #234 ORTIGAS AVENUE NORTH GREENHILLS SAN JUAN CITY MMN 000			ADVISOR Aldrin Padilla	COLOR 48054 WHITE/
DOC. DATE 27/02/23	REG. No. UNREG			YEAR/MAKE/MODEL 22/NEXTHUB/VESPA S125	TEAM NH GENER
STOCK No.	PURCHASE ORDER No.			MODEL No. S125	TAG No.
DRIVER		CONTACT No.		CAR LINE VESPA	ENG./TRANS.
HOME PHONE		BUSINESS PHONE		CHASSIS No.	KILOMETERS
TERMS		CONTACT NAME		PROD. DATE	EXP. DATE
VEHICLE ID RP8M66701NV039536		ENGINE No. M66BM5105832		SELLING DEALER	CONTRACT EXP. KMS
DATE AND TIME PROMISED 25/02/23 09:00pm		TIME RECEIVED 10:09am		DELIVERY KMS	EXP. DATE
QUOTE PRICE		AIR		PWR	TURBO

Labour
J# 1 76NAZZZZZ002

* PDI CLEAN
* PDI INSPECTION
* BRAND NEW UNIT
* CHECKED AND EVALUATED CONCERN
* PERFORMED PDI INSPECTION

Tech(s) : 48063

3125.00

Totals=====

Total - Labour 3125.00

Total Labour. 3125.00
Total Parts.. 0.00
Total Other.. 0.00
Total P.O.L.. 0.00
Total Misc... 0.00
VAT 375.00

Total Invoice 3500.00

RAB
12/27/23

[End. of Invoice]

ROAD TESTED		ACKNOWLEDGMENT	
ORDER NO.	SUBLET REPAIRS	RECEIVED above vehicle from AUTOHUB CAR CARE SERVICES (ACCS) in good condition and with all repair work enumerated completed to my satisfaction.	
		All works carried out at these premises are subject to a warranty of _____ days or _____ whichever comes first on all labor and materials.	
		SIGNATURE OF OWNER _____	
		I AGREE TO PAY for all works required for all the above described repair at your retail charge. It is understood that any estimate given is provisional and all repairs are undertaken on a cash basis unless prior arrangements for credit have been approved.	
		I have READ AND ACCEPTED your terms and conditions.	

CHECKLIST

10725

PAGE 1

Client : VESPA

Chassis # : RP8M6670 INV03826 Color: WHITE

Make/Model : VESPA S 125 3V

Engine # : M66BM S105832

Date : 6-24-2022

EMBLEMS

- (/) Piaggio Emblem (Front)
- (/) PVG Emblem (Crankcase)

SIDE MIRROR

- (/) LH Side View Mirror
- (/) RH Side View Mirror

ELECTRICAL BUTTONS

- (/) Start Button
- (/) Horn Button
- (/) High&Low Button
- (/) Passing Button (Optional)
- (/) Left Signal Button
- (/) Right Signal Button
- (/) Cut Off Engine Button (Optional)
- (/) Start & Stop Button
- () ASR Button
- (/) Mode
- () Saddle Button
- () Toggle Switch

LIGHTS

- (/) Park Light
- (/) High & Low Beam
- (/) Front Right Signal
- (/) Rear Right Signal
- (/) Front Left Signal
- (/) Rear Left Signal
- (/) Backlight
- (/) Brakelights
- (/) Instrumental Panel Gauges
- (/) Plate Light

FLUID LEVELS

- () Engine Oil
- (/) Gear Oil
- (/) Brake Fluid
- (/) Coolant

SCRATCHES

- (/) No Scratches
 - () W/ Scratches
- *Encircle parts that has/have scratches

COLOR

- () Evenly Painted
- () Not Evenly Painted

BATTERY/ HORN

- () Battery
- Brand: _____ Battery Voltage: _____
- () Horn

TIRES

- (/) Good Quality
- () Bad Quality
- Brand: _____
- Tire Pressure: _____ Front _____ Rear _____

PADS DIAGNOSTIC TOOL

- () PADS Checkup
- Fault : _____
- Remarks: _____

SADDLE

- (/) Good Quality
- () Bad Quality
- KEYS/ MANUAL/ TOOLS
- (/) Master Key
- (/) Duplicate Key
- (/) Service Manual
- (/) Warranty Booklet
- (/) Set of Screw
- (/) Battery Holder
- (/) Plate Holder
- (/) reflectors (Optional)
- (/) Under Body Caps (Optional)
- (/) 1 Set of Tools
- (/) Rear Shock Adjuster
- (/) Screw Driver
- (/) Fuse Removal Tool
- (/) Screw driver (FLOWER KEY)
- () Sparkplug Wrench

Remarks :

BUFFING ALL PANEL

I understand all the above items as explained to me by the releasing Officer/ Manager. I also agree that any failure on my part to adhere to any of the instructions given that may result in damages on the above mentioned parts will not be covered by warranty.

Inspected by :

Technician/PDI Personnel

Approved by :

Service Manager

Approved by :

Sales Department

CHECKLIST

10725

PAGE 2

Client: _____


Chassis #: RP8M66701N4039526

Color: WHITE

Make/Model: G125

Engine #: M66BM 5105836

Date: 10-24-22



LEGEND

S- Scratched	L- Loose
D- Dented	M- Missing
DD-Damaged	F- Faded

Remarks:



AUTOHUB CAR CARE SERVICES (ACCS)

BY: SUPREME AUTOZONE PHILIPPINES INC.

Sitio Buroi Cabrera Road, Brgy. San Juan, Taytay, Rizal

Tel. No. (632) 533-6398

VAT REG TIN: 236-978-189-00006

BILLING STATEMENT

No: **06774**

Service Invoice		Page 1 of 1		Doc # : ATCJ E23985	
CUSTOMER No. 211806	CUSTOMER NAME AND ADDRESS TIN: MOTOITALIA PHILS. INC. #234 ORTIGAS AVENUE NORTH GREENHILLS SAN JUAN CITY MMN 000			ADVISOR Aldrin Padilla	COLOR 48054 BLACK/
DOC. DATE 27/02/23	REG. No. UNREG			YEAR/MAKE/MODEL 23/NEXTHUB/VESPA 125	TEAM NH GENER
STOCK No.	PURCHASE ORDER No.			MODEL No. 5125	TAG No.
DRIVER			CONTACT No.	CHASSIS No.	ENG./TRANS.
HOME PHONE			BUSINESS PHONE	CONTACT NAME	PROD. DATE
VEHICLE ID RP8M66701NV039632			ENGINE No. M66BM5106361	CONTACT EXP. KMS	EXP. DATE
CA <input type="checkbox"/> F/C <input type="checkbox"/> CH <input type="checkbox"/>			TERMS	SELLING DEALER	DELIVERY KMS
C/C <input type="checkbox"/> WAR <input type="checkbox"/> INT <input type="checkbox"/>			Charge	DELIVERY DATE	DELIVERY DATE
DATE AND TIME PROMISED 25/02/23 09:00pm			TIME RECEIVED 10:10am	QUOTE PRICE	AIR <input type="checkbox"/> PWR <input type="checkbox"/> TURBO <input type="checkbox"/>

Labour
J# 1 76NAZZZZZ002

- * PDI CLEAN
- * PDI INSPECTION
- * BRAND NEW UNIT
- * CHECKED AND EVALUATED CONCERN
- * PERFORMED PDI INSPECTION

Tech(s) : 48055

3125.00

Total - Labour 3125.00

Totals=====

Total Labour.	3125.00
Total Parts..	0.00
Total Other..	0.00
Total P.O.L..	0.00
Total Misc...	0.00
VAT	375.00
Total Invoice	3500.00

RAR
02/27/23

[End of Invoice]

ROAD TESTED		ACKNOWLEDGMENT	
ORDER NO.	SUBLET REPAIRS	RECEIVED above vehicle from AUTOHUB CAR CARE SERVICES (ACCS) in good condition and with all repair work enumerated completed to my satisfaction.	
		All works carried out at these premises are subject to a warranty of _____ days or _____ whichever comes first on all labor and materials.	
		SIGNATURE OF OWNER _____	
		I AGREE TO PAY for all works required for all the above described repair at your retail charge. It is understood that any estimate given is provisional and all repairs are undertaken on a cash basis unless prior arrangements for credit have been approved.	
		I have READ AND ACCEPTED your terms and conditions.	

CHECKLIST

PAGE 1

Client :

Vespa

Chassis # :

ROK Model 701

39622

10749

Color:

Black

Make/Model :

S125

Engine # :

5106361

Date :

10-26-22

EMBLEMS

- ☒ Piaggio Emblem (Front)
- ☒ PVG Emblem (Crankcase)

SIDE MIRROR

- ☒ LH Side View Mirror
- ☒ RH Side View Mirror

ELECTRICAL BUTTONS

- ☒ Start Button
- ☒ Horn Button
- ☒ High&Low Button
- ☐ Passing Button (Optional)
- ☒ Left Signal Button
- ☒ Right Signal Button
- ☐ Cut Off Engine Button (Optional)
- ☐ Start & Stop Button
- ☐ ASR Button
- ☒ Mode
- ☐ Saddle Button
- ☐ Toggle Switch

LIGHTS

- ☐ Park Light
- ☒ High & Low Beam
- ☒ Front Right Signal
- ☒ Rear Right Signal
- ☒ Front Left Signal
- ☒ Rear Left Signal
- ☒ Backlight
- ☒ Brakelights
- ☒ Instrumental Panel Gauges
- ☒ Plate Light

FLUID LEVELS

- ☒ Engine Oil
- ☒ Gear Oil
- ☒ Brake Fluid
- ☐ Coolant

SCRATCHES

- ☐ No Scratches
 - ☐ W/ Scratches
- *Encircle parts that has/have scratches

COLOR

- ☐ Evenly Painted
- ☐ Not Evenly Painted

BATTERY/ HORN

- ☒ Battery
- Brand: _____ Battery Voltage: _____
- ☒ Horn

TIRES

- ☒ Good Quality
- ☐ Bad Quality
- Brand: _____
- Tire Pressure: _____ Front _____ Rear _____

PADS DIAGNOSTIC TOOL

- ☐ PADS Checkup

Fault : _____

Remarks: _____

SADDLE

- ☒ Good Quality
- ☐ Bad Quality
- KEYS/ MANUAL/ TOOLS**
- ☒ Master Key
- ☒ Duplicate Key
- ☒ Service Manual
- ☒ Warranty Booklet
- ☒ Set of Screw
- ☒ Battery Holder
- ☒ Plate Holder
- ☒ reflectors (Optional)
- ☐ Under Body Caps (Optional)
- ☐ 1 Set of Tools
- ☒ Rear Shock Adjuster
- ☒ Screw Driver
- ☐ Fuse Removal Tool
- ☐ Screw driver (FLOWER KEY)
- ☒ Sparkplug Wrench

Remarks :

Complete Acc. 3 tools w/ battery

I understand all the above items as explained to me by the releasing Officer/ Manager. I also agree that any failure on my part to adhere to any of the instructions given that may result in damages on the above mentioned parts will not be covered by warranty.

Inspected by :

Technician/PDI Personnel

Approved by :

Service Manager

Approved by :

Sales Department

CHECKLIST

PAGE 2

Client :

Vespa

Chassis # :

RP8M66761

NV1039622

Color:

10749

Black

Make/Model :


S125

Engine # :

5106361

Date :

10-26-22



LEGEND

S- Scratched

D- Dented

DD-Damaged

L- Loose

M- Missing

F- Faded

Remarks:

CHECKLIST

RP6M66761

10751

PAGE 1

Client :

VESPA

Chassis # :

NV039560

Color :

GREY

Make/Model :

S 125

Engine # :

5105890

Date :

10-29-77

EMBLEMS

- () Piaggio Emblem (Front)
() PVG Emblem (Crankcase)

SIDE MIRROR

- () LH Side View Mirror
() RH Side View Mirror

ELECTRICAL BUTTONS

- () Start Button
() Horn Button
() High&Low Button
() Passing Button (Optional)
() Left Signal Button
() Right Signal Button
() Cut Off Engine Button (Optional)
() Start & Stop Button
() ASR Button
() Mode
() Saddle Button
() Toggle Switch

LIGHTS

- () Park Light
() High & Low Beam
() Front Right Signal
() Rear Right Signal
() Front Left Signal
() Rear Left Signal
() Backlight
() Brakelights
() Instrumental Panel Gauges
() Plate Light

FLUID LEVELS

- () Engine Oil
() Gear Oil
() Brake Fluid
() Coolant

SCRATCHES

- () No Scratches
() W/ Scratches
*Encircle parts that has/have scratches

COLOR

- () Evenly Painted
() Not Evenly Painted

BATTERY/ HORN

- () Battery
Brand: SAFARI Battery Voltage: 12V
() Horn

TIRES

- () Good Quality
() Bad Quality
Brand: _____
Tire Pressure: _____ Front _____ Rear _____

PADS DIAGNOSTIC TOOL

- () PADS Checkup
Fault : _____
Remarks: _____

SADDLE

- () Good Quality
() Bad Quality
KEYS/ MANUAL/ TOOLS
() Master Key
() Duplicate Key
() Service Manual
() Warranty Booklet
() Set of Screw
() Battery Holder
() Plate Holder
() reflectors (Optional)
() Under Body Caps (Optional)
() 1 Set of Tools
() Rear Shock Adjuster
() Screw Driver
() Fuse Removal Tool
() Screw driver (FLOWER KEY)
() Sparkplug Wrench

Remarks :

COMPLETE TOOLS & ACCESSORIES W/ BATTERY

I understand all the above items as explained to me by the releasing Officer/ Manager. I also agree that any failure on my part to adhere to any of the instructions given that may result in damages on the above mentioned parts will not be covered by warranty.

Inspected by :

Technician/PDI Personnel

Approved by :

Service Manager

Approved by :

Sales Department

CHECKLIST

RPM6601

10751

PAGE 2

Client : VESPA


Chassis # : NV039560

Color: GREY

Make/Model : 5125

Engine # : 5105840

Date: 10-24-22



LEGEND

S- Scratched	L- Loose
D- Dented	M- Missing
DD-Damaged	F- Faded

Remarks:

D. TAPASAN



AUTOHUB CAR CARE SERVICES (ACCS)

BY: SUPREME AUTOZONE PHILIPPINES INC.

Sitio Buroi Cabrera Road, Brgy. San Juan, Taytay, Rizal

Tel. No.: (632) 533-6398

VAT REG. TIN: 236-978-189-00006

BILLING STATEMENT

No: **06776**

Service Invoice		Page 1 of 1		Doc # : ATCJ E23987	
CUSTOMER No. 271806	CUSTOMER NAME AND ADDRESS TIN: MOTOITALIA PHILS. INC. #234 ORTIGAS AVENUE NORTH GREENHILLS SAN JUAN CITY MMN 000			ADVISOR Aldrin Padilla	Doc # : ATCJ E23987
DOC. DATE 27/02/23				YEAR/MAKE/MODEL 22/NEXTHUB/S125	COLOR 4 BLACK/
REG. No. UNREG				MODEL No. S125	TEAM NH GENER
STOCK No.				CHASSIS No.	TAG No.
PURCHASE ORDER No.	DRIVER			CONTACT No.	ENG./TRANS.
CA <input type="checkbox"/>	F/C <input type="checkbox"/>	CH <input type="checkbox"/>	HOME PHONE	BUSINESS PHONE	TERMS
C/C <input type="checkbox"/>	WAR <input type="checkbox"/>	INT <input type="checkbox"/>	VEHICLE ID RP8M66701NV039635	ENGINE No. M66BM5106370	Charge
			DATE AND TIME PROMISED 25/02/23 09:00pm		
			TIME RECEIVED 10:10am		
			QUOTE PRICE		
			AIR PWR TURBO		

Labour
J# 1 76NAZZZZZ002

* PDI CLEAN
* PDI INSPECTION
* BRAND NEW UNIT
* CHECKED AND EVALUATED CONCERN:
PERFORMED PDI INSPECTION

Tech(s) : 48055

3125.00

Totals=====

Total - Labour 3125.00

Total Labour. 3125.00
Total Parts.. 0.00
Total Other.. 0.00
Total P.O.L.. 0.00
Total Misc... 0.00
VAT 375.00

Total Invoice 3500.00

RJP
02/27/23

[End of Invoice]

ROAD TESTED		ACKNOWLEDGMENT	
ORDER NO.	SUBLET REPAIRS	RECEIVED above vehicle from AUTOHUB CAR CARE SERVICES (ACCS) in good condition and with all repair work enumerated completed to my satisfaction.	
		All works carried out at these premises are subject to a warranty of _____ days or _____ whichever comes first on all labor and materials.	
		SIGNATURE OF OWNER _____	
		I AGREE TO PAY for all works required for all the above described repair at your retail charge. It is understood that any estimate given is provisional and all repairs are undertaken on a cash basis unless prior arrangements for credit have been approved.	
		I have READ AND ACCEPTED your terms and conditions.	

CHECKLIST

10752

PAGE 1

Client : VESPA

Chassis # : RV6M6761
NV039625

Color : BLK.

Make/Model : 5125

Engine # : 5106370

Date : 10-24-22

EMBLEMS

- (☒) Piaggio Emblem (Front)
() PVG Emblem (Crankcase)

SIDE MIRROR

- (☒) LH Side View Mirror
() RH Side View Mirror

ELECTRICAL BUTTONS

- (☒) Start Button
(☒) Horn Button
(☒) High&Low Button
() Passing Button (Optional)
(☒) Left Signal Button
(☒) Right Signal Button
() Cut Off Engine Button (Optional)
() Start & Stop Button
() ASR Button
(☒) Mode
() Saddle Button
() Toggle Switch

LIGHTS

- (☒) Park Light
(☒) High & Low Beam
(☒) Front Right Signal
(☒) Rear Right Signal
(☒) Front Left Signal
(☒) Rear Left Signal
(☒) Backlight
(☒) Brakelights
(☒) Instrumental Panel Gauges
(☒) Plate Light

FLUID LEVELS

- (☒) Engine Oil
(☒) Gear Oil
() Brake Fluid
() Coolant

SCRATCHES

- () No Scratches
(☒) W/ Scratches
*Encircle parts that has/have scratches

COLOR

- () Evenly Painted
(☒) Not Evenly Painted

BATTERY/ HORN

- (☒) Battery
Brand : ORIGINAL Battery Voltage : 12V
() Horn

TIRES

- (☒) Good Quality
() Bad Quality
Brand : MAXXIS
Tire Pressure : Front _____ Rear _____

PADS DIAGNOSTIC TOOL

- () PADS Checkup

Fault : _____

Remarks : _____

SADDLE

- (☒) Good Quality
() Bad Quality

KEYS/ MANUAL/ TOOLS

- (☒) Master Key
(☒) Duplicate Key
(☒) Service Manual
(☒) Warranty Booklet
(☒) Set of Screw
(☒) Battery Holder
() Plate Holder
(☒) reflectors (Optional)
(☒) Under Body Caps (Optional)
(☒) 1 Set of Tools
(☒) Rear Shock Adjuster
(☒) Screw Driver
() Fuse Removal Tool
() Screw driver (FLOWER KEY)
(☒) Sparkplug Wrench

Remarks :

COMPLETE TOOLS & ACCESSORIES W/ BATTERY

I understand all the above items as explained to me by the releasing Officer/ Manager. I also agree that any failure on my part to adhere to any of the instructions given that may result in damages on the above mentioned parts will not be covered by warranty.

Inspected by :

Approved by :

Approved by :

Technician/PDI Personnel

Service Manager

Sales Department

CHECKLIST

RP8M66701

10752

PAGE 2

Client: VESPA


Chassis #: NV039625

Color: BLK.

Make/Model: S125

Engine #: 5106370

Date: 10-21-22



LEGEND

S- Scratched	L- Loose
D- Dented	M- Missing
DD-Damaged	F- Faded

Remarks:

O. TRAMISAN



AUTOHUB CAR CARE SERVICES (ACCS)

BY: SUPREME AUTOZONE PHILIPPINES INC.

Sitio Buroi Cabrera Road, Brgy. San Juan, Taytay, Rizal

Tel. No.: (632) 533-6398

VAT REG. TIN: 236-978-189-00006

BILLING STATEMENT

No: **06777**

Service Invoice		Page 1 of 1		Doc # : ATCJ E23988		
CUSTOMER No. 211806	CUSTOMER NAME AND ADDRESS TIN: POTOITALIA PHILS. INC. #234 ORTIGAS AVENUE NORTH GREENHILLS SAN JUAN CITY MMN 000			ADVISOR Aldrin Padilla	COLOR 480 34 BLACK/	TEAM NH GENER
DOC. DATE 27/02/23				YEAR/MAKE/MODEL 22/NEXTHUB/VESPA S125	TAG No.	
REG. No. UNREG				MODEL No. S125	CAR LINE VESPA	ENG./TRANS.
STOCK No.				CHASSIS No.	KILOMETERS 2	PROD. DATE
PURCHASE ORDER No.	DRIVER	CONTACT No.	CONTACT NAME	CONTRACT EXP. KMS	EXP. DATE	
CA <input type="checkbox"/>	F/C <input type="checkbox"/>	CH <input type="checkbox"/>	HOME PHONE	BUSINESS PHONE	TERMS	SELLING DEALER
C/C <input type="checkbox"/>	WAR <input type="checkbox"/>	INT <input type="checkbox"/>	VEHICLE ID RP8M66701NV0396	ENGINE No. M66BM5106344	DATE AND TIME PROMISED 25/02/23 09:00pm	TIME RECEIVED 10:11am
				QUOTE PRICE	AIR	FWR TURBO

Labour
JW 1 76NAZZZZZ002

* PDI CLEAN
* PDI INSPECTION
* BRAND NEW UNIT
* CHECKED AND EVALUATED CONCERN:
PERFORMED PDI INSPECTION

Tech(s) : 48055

3125.00

Totals=====

Total - Labour 3125.00

Total Labour. 3125.00
Total Parts.. 0.00
Total Other.. 0.00
Total P.O.L.. 0.00
Total Misc... 0.00
VAT 375.00

Total Invoice 3500.00

RAR
02/23/23

[End of Invoice]

ROAD TESTED		ACKNOWLEDGMENT	
ORDER NO.	SUBLET REPAIRS	RECEIVED above vehicle from AUTOHUB CAR CARE SERVICES (ACCS) in good condition and with all repair work enumerated completed to my satisfaction.	
		All works carried out at these premises are subject to a warranty of _____ days or _____ whichever comes first on all labor and materials.	
		SIGNATURE OF OWNER _____	
		I AGREE TO PAY for all works required for all the above described repair at your retail charge. It is understood that any estimate given is provisional and all repairs are undertaken on a cash basis unless prior arrangements for credit have been approved.	
		I have READ AND ACCEPTED your terms and conditions.	

CHECKLIST

RP8M16701

10753

PAGE 1

Client : VESPA

Chassis # : NV039616

Color : BLK

Make/Model : S125

Engine # : 5106341

Date : 10-24-22

EMBLEMS

- (☒) Piaggio Emblem (Front)
(☒) PVG Emblem (Crankcase)

SIDE MIRROR

- (☒) LH Side View Mirror
(☒) RH Side View Mirror

ELECTRICAL BUTTONS

- (☒) Start Button
(☒) Horn Button
(☒) High&Low Button
(☒) Passing Button (Optional)
(☒) Left Signal Button
(☒) Right Signal Button
(☒) Cut Off Engine Button (Optional)
(☒) Start & Stop Button
(☒) ASR Button
(☒) Mode
(☒) Saddle Button
(☒) Toggle Switch

LIGHTS

- (☒) Park Light
(☒) High & Low Beam
(☒) Front Right Signal
(☒) Rear Right Signal
(☒) Front Left Signal
(☒) Rear Left Signal
(☒) Backlight
(☒) Brakelights
(☒) Instrumental Panel Gauges
(☒) Plate Light

FLUID LEVELS

- (☒) Engine Oil
(☒) Gear Oil
(☒) Brake Fluid
(☒) Coolant

Remarks :

SCRATCHES

- (☒) No Scratches
(☒) W/ Scratches
*Encircle parts that has/have scratches

COLOR

- (☒) Evenly Painted
(☒) Not Evenly Painted

BATTERY/ HORN

- (☒) Battery
Brand : DONGHA Battery Voltage : 12V
(☒) Horn

TIRES

- (☒) Good Quality
(☒) Bad Quality
Brand : MAXXIS
Tire Pressure : Front _____ Rear _____

PADS DIAGNOSTIC TOOL

- (☒) PADS Checkup
Fault : _____
Remarks : _____

SADDLE

- (☒) Good Quality
(☒) Bad Quality
KEYS/ MANUAL/ TOOLS
(☒) Master Key
(☒) Duplicate Key
(☒) Service Manual
(☒) Warranty Booklet
(☒) Set of Screw
(☒) Battery Holder
(☒) Plate Holder
(☒) reflectors (Optional)
(☒) Under Body Caps (Optional)
(☒) 1 Set of Tools
(☒) Rear Shock Adjuster
(☒) Screw Driver
(☒) Fuse Removal Tool
(☒) Screw driver (FLOWER KEY)
(☒) Sparkplug Wrench

COMPLETE TOOLS & ACCESSORIES W/ BATTERY

I understand all the above items as explained to me by the releasing Officer/ Manager. I also agree that any failure on my part to adhere to any of the instructions given that may result in damages on the above mentioned parts will not be covered by warranty.


Inspected by : D. TAMISAN
Technician/PDI Personnel

Approved by : _____
Service Manager

Approved by : _____
Sales Department

CHECKLIST

Client: VESPA Chassis #: NV039616 Color: ELK 10753 PAGE 2
Make/Model: S 125 Engine #: 5106341 Date: 10-24-22



LEGEND

S- Scratched L- Loose
D- Dented M- Missing
DD-Damaged F- Faded

Remarks:

D. TAZAMISAN

CHECKLIST

10768

PAGE 1

Client: VESPA

Chassis #: P18M66701NV039552

Color: ORANGE

Make/Model: S125

Engine #: M66BM 5105847

Date: 10-25-22

EMBLEMS

- (☒) Piaggio Emblem (Front)
- (☒) PVG Emblem (Crankcase)

SIDE MIRROR

- (☒) LH Side View Mirror
- (☒) RH Side View Mirror

ELECTRICAL BUTTONS

- (☒) Start Button
- (☒) Horn Button
- (☒) High&Low Button
- (☐) Passing Button (Optional)
- (☒) Left Signal Button
- (☒) Right Signal Button
- (☐) Cut Off Engine Button (Optional)
- (☐) Start & Stop Button
- (☐) ASR Button
- (☒) Mode
- (☐) Saddle Button
- (☐) Toggle Switch

LIGHTS

- (☒) Park Light
- (☒) High & Low Beam
- (☒) Front Right Signal
- (☒) Rear Right Signal
- (☒) Front Left Signal
- (☒) Rear Left Signal
- (☒) Backlight
- (☒) Brakelights
- (☒) Instrumental Panel Gauges
- (☒) Plate Light

FLUID LEVELS

- (☒) Engine Oil
- (☒) Gear Oil
- (☒) Brake Fluid
- (☐) Coolant

SCRATCHES

- (☐) No Scratches
 - (☒) W/ Scratches
- *Encircle parts that has/have scratches

COLOR

- (☐) Evenly Painted
- (☒) Not Evenly Painted

BATTERY/ HORN

- (☒) Battery
- Brand: SONENAI Battery Voltage: 12V
- (☒) Horn

TIRES

- (☒) Good Quality
- (☐) Bad Quality
- Brand: MAXXIS
- Tire Pressure: Front _____ Rear _____

PADS DIAGNOSTIC TOOL

- (☐) PADS Checkup

Fault: _____

Remarks: _____

SADDLE

- (☒) Good Quality
- (☐) Bad Quality
- KEYS/ MANUAL/ TOOLS**
- (☒) Master Key
- (☒) Duplicate Key
- (☒) Service Manual
- (☒) Warranty Booklet
- (☒) Set of Screw
- (☒) Battery Holder
- (☐) Plate Holder
- (☒) reflectors (Optional)
- (☒) Under Body Caps (Optional)
- (☐) 1 Set of Tools
- (☒) Rear Shock Adjuster
- (☒) Screw Driver
- (☐) Fuse Removal Tool
- (☐) Screw driver (FLOWER KEY)
- (☒) Sparkplug Wrench

Remarks :

COMPLETE TOOLS & ACCESSORIES W/ BATTERY

I understand all the above items as explained to me by the releasing Officer/ Manager. I also agree that any failure on my part to adhere to any of the instructions given that may result in damages on the above mentioned parts will not be covered by warranty.

Inspected by :

D. TANIGAN
Technician/PDI Personnel

Approved by :

Service Manager

Approved by :

Sales Department

CHECKLIST

Client : VESPA

Chassis # : RP8M66701 NV039552

10768


PAGE 2

Make/Model : S 125

Engine # : M66BM 5105847

Color: ORANGE

Date : 10-25-22



LEGEND

S- Scratched	L- Loose
D- Dented	M- Missing
DD-Damaged	F- Faded

Remarks:

D. TALAMISAN

CHECKLIST

Client :

VESPA

Chassis # :

R88M66701NV097699

Color:

BLK.

10766

PAGE 1

Make/Model :

S125

Engine # :

M66BM 5106355

Date :

10-25-22

EMBLEMS

- () Piaggio Emblem (Front)
() PVG Emblem (Crankcase)

SIDE MIRROR

- () LH Side View Mirror
() RH Side View Mirror

ELECTRICAL BUTTONS

- () Start Button
() Horn Button
() High&Low Button
() Passing Button (Optional)
() Left Signal Button
() Right Signal Button
() Cut Off Engine Button (Optional)
() Start & Stop Button
() ASR Button
() Mode
() Saddle Button
() Toggle Switch

LIGHTS

- () Park Light
() High & Low Beam
() Front Right Signal
() Rear Right Signal
() Front Left Signal
() Rear Left Signal
() Backlight
() Brakelights
() Instrumental Panel Gauges
() Plate Light

FLUID LEVELS

- () Engine Oil
() Gear Oil
() Brake Fluid
() Coolant

SCRATCHES

- () No Scratches
() W/ Scratches
*Encircle parts that has/have scratches

COLOR

- () Evenly Painted
() Not Evenly Painted

BATTERY/ HORN

- () Battery
Brand: ORIGINA Battery Voltage: 12V
() Horn

TIRES

- () Good Quality
() Bad Quality
Brand: MAXXIS
Tire Pressure: Front _____ Rear _____

PADS DIAGNOSTIC TOOL

- () PADS Checkup
Fault : _____
Remarks: _____

SADDLE

- () Good Quality
() Bad Quality
KEYS/ MANUAL/ TOOLS
() Master Key
() Duplicate Key
() Service Manual
() Warranty Booklet
() Set of Screw
() Battery Holder
() Plate Holder
() reflectors (Optional)
() Under Body Caps (Optional)
() 1 Set of Tools
() Rear Shock Adjuster
() Screw Driver
() Fuse Removal Tool
() Screw driver (FLOWER KEY)
() Sparkplug Wrench

Remarks :

COMPLETE TOOLS & ACCESSORIES W/ BATTERY

I understand all the above items as explained to me by the releasing Officer/ Manager. I also agree that any failure on my part to adhere to any of the instructions given that may result in damages on the above mentioned parts will not be covered by warranty.

Inspected by :

W. RAMISAN
Technician/PDI Personnel

Approved by :

Service Manager

Approved by :

Sales Department

CHECKLIST

10766


PAGE 2

Client : VESPA

Chassis # : PP8M66701NV039633 Color: BLK.

Make/Model : S125

Engine # : M66BM 5106355 Date : 10-25-22



LEGEND

S- Scratched L- Loose
D- Dented M- Missing
DD-Damaged F- Faded

Remarks:

D. TAYAMISAN

THIS BILLING STATEMENT SHALL BE VALID FOR FIVE (5) YEARS FROM THE DATE OF ATP.
THIS DOCUMENT IS NOT VALID FOR CLAIMING INPUT TAXES.

CHECKLIST

10767

PAGE 1

Client : YESA

Chassis # : RP8MG6701NV039534

Color : ORANGE

Make/Model : S 125

Engine # : M66BM 5105856

Date : 10-25-22

EMBLEMS

- (☒) Piaggio Emblem (Front)
(☒) PVG Emblem (Crankcase)

SIDE MIRROR

- (☒) LH Side View Mirror
(☒) RH Side View Mirror

ELECTRICAL BUTTONS

- (☒) Start Button
(☒) Horn Button
(☒) High&Low Button
(☐) Passing Button (Optional)
(☒) Left Signal Button
(☒) Right Signal Button
(☐) Cut Off Engine Button (Optional)
(☐) Start & Stop Button
(☐) ASR Button
(☒) Mode
(☐) Saddle Button
(☐) Toggle Switch

LIGHTS

- (☒) Park Light
(☒) High & Low Beam
(☒) Front Right Signal
(☒) Rear Right Signal
(☒) Front Left Signal
(☒) Rear Left Signal
(☒) Backlight
(☒) Brakelights
(☒) Instrumental Panel Gauges
(☒) Plate Light

FLUID LEVELS

- (☒) Engine Oil
(☒) Gear Oil
(☒) Brake Fluid
(☐) Coolant

SCRATCHES

- (☐) No Scratches
(☒) W/ Scratches
*Encircle parts that has/have scratches

COLOR

- (☐) Evenly Painted
(☒) Not Evenly Painted

BATTERY/ HORN

- (☒) Battery
Brand: YUASA Battery Voltage: 12V
(☒) Horn

TIRES

- (☒) Good Quality
(☐) Bad Quality
Brand: MAXXIS
Tire Pressure: Front _____ Rear _____

PADS DIAGNOSTIC TOOL

- (☐) PADS Checkup
Fault : _____
Remarks: _____

SADDLE

- (☒) Good Quality
(☐) Bad Quality
KEYS/ MANUAL/ TOOLS
(☒) Master Key
(☒) Duplicate Key
(☒) Service Manual
(☒) Warranty Booklet
(☒) Set of Screw
(☒) Battery Holder
(☐) Plate Holder
(☒) reflectors (Optional)
(☒) Under Body Caps (Optional)
(☐) 1 Set of Tools
(☒) Rear Shock Adjuster
(☒) Screw Driver
(☐) Fuse Removal Tool
(☐) Screw driver (FLOWER KEY)
(☒) Sparkplug Wrench

Remarks :

COMPLETE TOOLS & ACCESSORIES W/ BATTERY

I understand all the above items as explained to me by the releasing Officer/ Manager. I also agree that any failure on my part to adhere to any of the instructions given that may result in damages on the above mentioned parts will not be covered by warranty.

Inspected by :

Technician/PDI Personnel

Approved by :

Service Manager

Approved by :

Sales Department

CHECKLIST

Client: VESPA

Chassis #: RP8M6670INN039531

10767


PAGE 2

Make/Model: 5125

Engine #: M66BM 5105856

Color: ORANGE

Date: 10-25-22



LEGEND

S- Scratched	L- Loose
D- Dented	M- Missing
DD-Damaged	F- Faded

Remarks:

CHECKLIST

10769

PAGE 1

Client :

VESPA

Chassis # :

R18M1670INV039598

Color :

ORANGE

Make/Model :

S125

Engine # :

M166MB 51058169

Date :

10-25-22

EMBLEMS

- (☒) Piaggio Emblem (Front)
(☒) PVG Emblem (Crankcase)

SIDE MIRROR

- (☒) LH Side View Mirror
(☒) RH Side View Mirror

ELECTRICAL BUTTONS

- (☒) Start Button
(☒) Horn Button
(☒) High&Low Button
(☐) Passing Button (Optional)
(☒) Left Signal Button
(☒) Right Signal Button
(☐) Cut Off Engine Button (Optional)
(☐) Start & Stop Button
(☐) ASR Button
(☒) Mode
(☐) Saddle Button
(☐) Toggle Switch

LIGHTS

- (☒) Park Light
(☐) High & Low Beam
(☒) Front Right Signal
(☒) Rear Right Signal
(☒) Front Left Signal
(☒) Rear Left Signal
(☒) Backlight
(☒) Brakelights
(☒) Instrumental Panel Gauges
(☒) Plate Light

FLUID LEVELS

- (☒) Engine Oil
(☒) Gear Oil
(☒) Brake Fluid
(☐) Coolant

SCRATCHES

- (☐) No Scratches
(☒) W/ Scratches
*Encircle parts that has/have scratches

COLOR

- (☐) Evenly Painted
(☒) Not Evenly Painted

BATTERY/ HORN

- (☒) Battery
Brand: DONKAP Battery Voltage: 12V
(☒) Horn

TIRES

- (☒) Good Quality
(☐) Bad Quality
Brand: MAXXIS
Tire Pressure: Front _____ Rear _____

PADS DIAGNOSTIC TOOL

- (☐) PADS Checkup
Fault : _____
Remarks: _____

SADDLE

- (☒) Good Quality
(☐) Bad Quality
KEYS/ MANUAL/ TOOLS
(☒) Master Key
(☒) Duplicate Key
(☒) Service Manual
(☒) Warranty Booklet
(☒) Set of Screw
(☒) Battery Holder
(☐) Plate Holder
(☒) reflectors (Optional)
(☒) Under Body Caps (Optional)
(☐) 1 Set of Tools
(☒) Rear Shock Adjuster
(☒) Screw Driver
(☐) Fuse Removal Tool
(☐) Screw driver (FLOWER KEY)
(☒) Sparkplug Wrench

Remarks :

COMPLETE TOOLS & ACCESSORIES W/ BATTERY

I understand all the above items as explained to me by the releasing Officer/ Manager. I also agree that any failure on my part to adhere to any of the instructions given that may result in damages on the above mentioned parts will not be covered by warranty.

Inspected by :

Technician/PDI Personnel

Approved by :

Service Manager

Approved by :

Sales Department

CHECKLIST

Client: VESPA


Chassis #: RP8ML66701NV039518 Color: ORANGE

10769

PAGE 2

Make/Model: S125

Engine #: ML66MB 5105869 Date: 10-25-22



LEGEND

S- Scratched	L- Loose
D- Dented	M- Missing
DD-Damaged	F- Faded

Remarks:

D. TALPISAN



AUTOHUB CAR CARE SERVICES (ACCS)

BY: SUPREME AUTOZONE PHILIPPINES INC.

Sitio Buroi Cabrera Road, Brgy. San Juan, Taytay, Rizal

Tel. No.: (632) 533-6398

VAT REG. TIN: 236-978-189-00006

BILLING STATEMENT

No: **06782**

Service Invoice		Page 1 of 1		Doc # : ATCJ E23993	
CUSTOMER No. 211806	CUSTOMER NAME AND ADDRESS TIN: MOTOITALIA PHILS. INC.		ADVISOR Aldrin Padilla	COLOR 48054 BLACK/	TEAM NH GENER
DOC. DATE 27/02/23	#234 ORTIGAS AVENUE		YEAR/MAKE/MODEL 22/NEXTHUB/SPRINT 125S	TAG No.	
REG. No. UNREG	NORTH GREENHILLS		MODEL No. SPRINT 125S	CAR LINE VESPA	ENG./TRANS.
STOCK No.	SAN JUAN CITY MMN 000		CHASSIS No.	KILOMETERS	PROD. DATE
PURCHASE ORDER No.	DRIVER	CONTACT No.	CONTACT NAME	CONTRACT EXP KMS	EXP. DATE
CA <input type="checkbox"/>	F/C <input type="checkbox"/>	OH <input type="checkbox"/>	HOME PHONE	BUSINESS PHONE	TERMS
C/C <input type="checkbox"/>	WAR <input type="checkbox"/>	INT <input type="checkbox"/>	VEHICLE ID RP8M66701NV03963	ENGINE No. M66BM5106369	DATE AND TIME PROMISED 25/02/23 09:00pm
			SELLING DEALER	DELIVERY KMS	DELIVERY DATE
			TIME RECEIVED 10:14am	QUOTE PRICE	AIR PWR TURBO

Labour-----
J# 1 76NAZZZZZ002
PDI CLEAN
* PDI INSPECTION
* BRAND NEW UNIT
* CHECKED AND EVALUATED CONCERN:
PERFORMED PDI INSPECTION
Tech(s) : 48055 3125.00
Total - Labour 3125.00
Totals=====

Total Labour..	3125.00
Total Parts..	0.00
Total Other..	0.00
Total P.O.L..	0.00
Total Misc...	0.00
VAT	375.00
Total Invoice	3500.00

RJR
02/27/23

[End of Invoice]

ROAD TESTED		ACKNOWLEDGMENT	
ORDER NO.	SUBLET REPAIRS	RECEIVED above vehicle from AUTOHUB CAR CARE SERVICES (ACCS) in good condition and with all repair work enumerated completed to my satisfaction.	
		All works carried out at these premises are subject to a warranty of _____ days or _____ whichever comes first on all labor and materials.	
		SIGNATURE OF OWNER _____	
		I AGREE TO PAY for all works required for all the above described repair at your retail charge. It is understood that any estimate given is provisional and all repairs are undertaken on a cash basis unless prior arrangements for credit have been approved.	
		I have READ AND ACCEPTED your terms and conditions	

CHECKLIST

10799

PAGE 1

Client : VESPA

Chassis # : PP8ML670M/V039623

Color: BLK.

Make/Model : S 125

Engine # : M660M 5106369

Date : 10-26-22

EMBLEMS

- (☒) Piaggio Emblem (Front)
- (☐) PVG Emblem (Crankcase)

SIDE MIRROR

- (☒) LH Side View Mirror
- (☒) RH Side View Mirror

ELECTRICAL BUTTONS

- (☒) Start Button
- (☒) Horn Button
- (☒) High&Low Button
- (☐) Passing Button (Optional)
- (☒) Left Signal Button
- (☒) Right Signal Button
- (☐) Cut Off Engine Button (Optional)
- (☐) Start & Stop Button
- (☐) ASR Button
- (☒) Mode
- (☐) Saddle Button
- (☐) Toggle Switch

LIGHTS

- (☒) Park Light
- (☒) High & Low Beam
- (☒) Front Right Signal
- (☒) Rear Right Signal
- (☒) Front Left Signal
- (☒) Rear Left Signal
- (☒) Backlight
- (☒) Brakelights
- (☒) Instrumental Panel Gauges
- (☒) Plate Light

FLUID LEVELS

- (☒) Engine Oil
- (☒) Gear Oil
- (☒) Brake Fluid
- (☐) Coolant

SCRATCHES

- (☐) No Scratches
 - (☒) W/ Scratches
- *Encircle parts that has/have scratches

COLOR

- (☐) Evenly Painted
- (☒) Not Evenly Painted

BATTERY/ HORN

- (☒) Battery
- Brand: DONGNA Battery Voltage: 12V
- (☒) Horn

TIRES

- (☒) Good Quality
- (☐) Bad Quality
- Brand: MAXXIS
- Tire Pressure: Front _____ Rear _____

PADS DIAGNOSTIC TOOL

- (☐) PADS Checkup
- Fault : _____
- Remarks: _____

SADDLE

- (☒) Good Quality
- (☐) Bad Quality
- KEYS/ MANUAL/ TOOLS**
- (☒) Master Key
- (☒) Duplicate Key
- (☒) Service Manual
- (☒) Warranty Booklet
- (☒) Set of Screw
- (☒) Battery Holder
- (☐) Plate Holder
- (☒) reflectors (Optional)
- (☒) Under Body Caps (Optional)
- (☐) 1 Set of Tools
- (☒) Rear Shock Adjuster
- (☒) Screw Driver
- (☐) Fuse Removal Tool
- (☐) Screw driver (FLOWER KEY)
- (☒) Sparkplug Wrench

Remarks :

COMPLETE ACCESSORIES W/ BATTERY

I understand all the above items as explained to me by the releasing Officer/ Manager. I also agree that any failure on my part to adhere to any of the instructions given that may result in damages on the above mentioned parts will not be covered by warranty.

Inspected by : B. TALAMISAN
Technician/PDI Personnel

Approved by : _____
Service Manager

Approved by : _____
Sales Department

CHECKLIST

10799

PAGE 2

Client :

VESPA

Chassis # :

RP8M166701 NV039623

Color:

BLK.

Make/Model :


S125

Engine # :

M166BM 5106369

Date :

10-26-22



LEGEND

S- Scratched

L- Loose

D- Dented

M- Missing

DD-Damaged

F- Faded

Remarks:

D. TALAMISAN



AUTOHUB CAR CARE SERVICES (ACCS)

BY: SUPREME AUTOZONE PHILIPPINES INC.

Sitio Buroi Cabrera Road, Brgy. San Juan, Taytay, Rizal

Tel. No. (632) 533-6398

VAT REG. TIN: 236-978-189-00006

BILLING STATEMENT

No: **06783**

Service Invoice		Page 1 of 1		Doc # : ATCJ E23994	
CUSTOMER No. 211806	CUSTOMER NAME AND ADDRESS TIN: MOTOITALIA PHILS. INC.			ADVISOR Aldrin Padilla	COLOR 48054 BLACK/
DOC. DATE 27/02/23	#234 ORTIGAS AVENUE			YEAR/MAKE/MODEL 22/NEXTHUB/VESPA 5125	TEAM NH GENER
REG. No. UNREG	NORTH GREENHILLS			MODEL No. 5125	TAG No.
STOCK No.	SAN JUAN CITY MMN 000			CAR LINE VESPA	ENG./TRANS.
PURCHASE ORDER No.	DRIVER	CONTACT No.	CONTACT NAME	CHASSIS No.	KILOMETERS
				PROD. DATE	
CA <input type="checkbox"/>	F/C <input type="checkbox"/>	CH <input type="checkbox"/>	HOME PHONE	BUSINESS PHONE	TERMS
C/C <input type="checkbox"/>	WAR <input type="checkbox"/>	INT <input type="checkbox"/>	VEHICLE ID RPQM66701NV039600	ENGINE No. M66BM5106362	DATE AND TIME PROMISED 25/02/23 09:00pm
			SELLING DEALER	DELIVERY KMS	DELIVERY DATE
			TIME RECEIVED 10:15am	QUOTE PRICE	AIR PWR TURBO

Labour
J# 1 76NAZZZZZ002

PDI CLEAN
* PDI INSPECTION
* BRAND NEW UNIT
* CHECKED AND EVALUATED CONCERN:
PERFORMED PDI INSPECTION

Tech(s) : 48048 3125.00

Total - Labour 3125.00

Totals=====

Total Labour. 3125.00
Total Parts.. 0.00
Total Other.. 0.00
Total P.O.L.. 0.00
Total Misc... 0.00
VAT 375.00
Total Invoice 3500.00

[Handwritten Signature]
02/03/23

ROAD TESTED		ACKNOWLEDGMENT	
ORDER NO.	SUBLET REPAIRS	RECEIVED above vehicle from AUTOHUB CAR CARE SERVICES (ACCS) in good condition and with all repair work enumerated completed to my satisfaction.	
		All works carried out at these premises are subject to a warranty of _____ days or _____ whichever comes first on all labor and materials.	
		SIGNATURE OF OWNER _____	
		I AGREE TO PAY for all works required for all the above described repair at your retail charge. It is understood that any estimate given is provisional and all repairs are undertaken on a cash basis unless prior arrangements for credit have been approved.	
		I have READ AND ACCEPTED your terms and conditions	

CHECKLIST

Client :

Vespa

Chassis # :

RPSM60701

NV039420

Color :

10750

PAGE 2

Black

Make/Model :


S125

Motor
Engine # :

51003671

Date :

10-26-22



LEGEND

S- Scratched

D- Dented

DD-Damaged

L- Loose

M- Missing

F- Faded

Remarks:



AUTOHUB CAR CARE SERVICES (ACCS)

BY: SUPREME AUTOZONE PHILIPPINES INC.

Sitio Buroi Cabrera Road, Brgy. San Juan, Taytay, Rizal

Tel. No. (632) 533-6398

VAT REG TIN 236-978-189-00006

BILLING STATEMENT

No: **06784**

Service Invoice		Page 1 of 1		Doc # : ATCJ E23995	
CUSTOMER No. 211806	CUSTOMER NAME AND ADDRESS TIN: MOYOTALIA PHILS. INC.			ADVISOR Aldrin Padilla	48055
DOC. DATE 27/02/23	1234 ORTIGAS AVENUE			COLOR ORANGE/	TEAM NH GENER
REG. No. UNREG	NORTH GREENHILLS			YEAR/MAKE/MODEL 22/NEXTHUB/VESPA 5125	TAG No.
STOCK No.	SAN JUAN CITY MMN 000			MODEL No. 5125	CAR LINE VESPA
PURCHASE ORDER No.	DRIVER	CONTACT No.	CONTACT NAME	CHASSIS No.	ENG./TRANS.
CA <input type="checkbox"/>	HOME PHONE	BUSINESS PHONE	TERMS	CONTRACT EXP KMS	PROD. DATE
FC <input type="checkbox"/>	1	1	Charge	EXP. DATE	
CH <input type="checkbox"/>	VEHICLE ID	ENGINE No.	SELLING DEALER	DELIVERY KMS	DELIVERY DATE
C/C <input type="checkbox"/>	RP8M66701NV039553	M66BM5105839	DATE AND TIME PROMISED	TIME RECEIVED	QUOTE PRICE
WAR <input type="checkbox"/>			25/02/23 09:00pm	10:15am	AIR PWR TURBO
INT <input type="checkbox"/>					

Labour
JH 1 76NAZZZZ002

* PDI CLEAN
* PDI INSPECTION
* BRAND NEW UNIT
* CHECKED AND EVALUATED CONCERN:
PERFORMED PDI INSPECTION

Tech(s) : 48055

3125.00

Totals-----

Total - Labour 3125.00

Total Labour. 3125.00
Total Parts.. 0.00
Total Other.. 0.00
Total P.O.L.. 0.00
Total Misc... 0.00
VAT 375.00

Total Invoice 3500.00

[Handwritten Signature]
02/03/23

[End of Invoice]

ROAD TESTED		ACKNOWLEDGMENT		<p>I AGREE TO PAY for all works required for all the above described repair at your retail charge. It is understood that any estimate given is provisional and all repairs are undertaken on a cash basis unless prior arrangements for credit have been approved.</p> <p>I have READ AND ACCEPTED your terms and conditions.</p>
ORDER NO.	SUBLET REPAIRS	RECEIVED above vehicle from AUTOHUB CAR CARE SERVICES (ACCS) in good condition and with all repair work enumerated completed to my satisfaction.		
		All works carried out at these premises are subject to a warranty of _____ days or _____ whichever comes first on all labor and materials.		
		SIGNATURE OF OWNER _____		

CHECKLIST

10835

PAGE 1

Client : VESPA

Chassis # : RPM66701NN039553

Color : ORANGE

Make/Model : S125

Engine # : M66BM 5105839

Date : 10-26-22

EMBLEMS

- (☒) Piaggio Emblem (Front)
- (☒) PVG Emblem (Crankcase)

SIDE MIRROR

- (☒) LH Side View Mirror
- (☒) RH Side View Mirror

ELECTRICAL BUTTONS

- (☒) Start Button
- (☒) Horn Button
- (☒) High&Low Button
- (☒) Passing Button (Optional)
- (☒) Left Signal Button
- (☒) Right Signal Button
- (☒) Cut Off Engine Button (Optional)
- (☒) Start & Stop Button
- (☒) ASR Button
- (☒) Mode
- (☒) Saddle Button
- (☒) Toggle Switch

LIGHTS

- (☒) Park Light
- (☒) High & Low Beam
- (☒) Front Right Signal
- (☒) Rear Right Signal
- (☒) Front Left Signal
- (☒) Rear Left Signal
- (☒) Backlight
- (☒) Brakelights
- (☒) Instrumental Panel Gauges
- (☒) Plate Light

FLUID LEVELS

- (☒) Engine Oil
- (☒) Gear Oil
- (☒) Brake Fluid
- (☒) Coolant

SCRATCHES

- (☐) No Scratches
 - (☐) W/ Scratches
- *Encircle parts that has/have scratches

COLOR

- (☐) Evenly Painted
- (☐) Not Evenly Painted

BATTERY/ HORN

- (☒) Battery
- Brand : DEGNADA Battery Voltage : 12V
- (☒) Horn

TIRES

- (☒) Good Quality
- (☐) Bad Quality
- Brand : MAXXIS
- Tire Pressure : Front _____ Rear _____

PADS DIAGNOSTIC TOOL

- (☐) PADS Checkup
- Fault : _____
- Remarks : _____

SADDLE

- (☒) Good Quality
- (☐) Bad Quality
- KEYS/ MANUAL/ TOOLS**
- (☒) Master Key
- (☒) Duplicate Key
- (☒) Service Manual
- (☒) Warranty Booklet
- (☒) Set of Screw
- (☒) Battery Holder
- (☐) Plate Holder
- (☒) reflectors (Optional)
- (☒) Under Body Caps (Optional)
- (☐) 1 Set of Tools
- (☒) Rear Shock Adjuster
- (☒) Screw Driver
- (☐) Fuse Removal Tool
- (☐) Screw driver (FLOWER KEY)
- (☒) Sparkplug Wrench

Remarks :

COMPLETE ACCESSORIES w/ BATTERY

I understand all the above items as explained to me by the releasing Officer/ Manager. I also agree that any failure on my part to adhere to any of the instructions given that may result in damages on the above mentioned parts will not be covered by warranty.

Inspected by : D. PALANISAN
Technician/PDI Personnel

Approved by : _____
Service Manager

Approved by : _____
Sales Department

CHECKLIST

10835

PAGE 2

Client: VESPA


Chassis #: RP8MCG70INV039553

Color: ORANGE

Make/Model: S 125

Engine #: M166BM 5105839

Date: 10-26-22



LEGEND

S- Scratched	L- Loose
D- Dented	M- Missing
DD-Damaged	F- Faded

Remarks:

O. TANMISAN



AUTOHUB CAR CARE SERVICES (ACCS)

BY: SUPREME AUTOZONE PHILIPPINES INC.

Sitio Buroi Cabrera Road, Brgy San Juan, Taytay, Rizal

Tel No (632) 533-6398

VAT REG. TIN 236-978-189-00006

BILLING STATEMENT

No: 06785

Service Invoice		Page 1 of 1		Doc # : ATCJ E23996	
CUSTOMER No. 211806	CUSTOMER NAME AND ADDRESS TIN: MOTOITALIA PHILS. INC. #234 ORTIGAS AVENUE NORTH GREENHILLS SAN JUAN CITY MMN 000			ADVISOR Aldrin Padilla	COLOR 48054 ORANGE/
DOC. DATE 27/02/23				YEAR/MAKE/MODEL 22/NEXTHUB/VESPA S125	TEAM NH GENER
REG. No. UNREG				MODEL No. S125	TAG No.
STOCK No.				CHASSIS No.	ENG./TRANS.
PURCHASE ORDER No.	DRIVER	CONTACT No.	CONTACT NAME	KILOMETERS	PROD. DATE
CA <input type="checkbox"/>	HOME PHONE	BUSINESS PHONE	SELLING DEALER	CONTRACT EXP. KMS	EXP. DATE
F/C <input type="checkbox"/>	1	1	Charge	DELIVERY KMS	DELIVERY DATE
CH <input type="checkbox"/>	VEHICLE ID	ENGINE No.	DATE AND TIME PROMISED	TIME RECEIVED	QUOTE PRICE
C/C <input type="checkbox"/>	WAR <input type="checkbox"/>	INT <input type="checkbox"/>	25/02/23 09:00pm	10:15am	AIR PWR TURBO
	RP8M66701NV039514	M66BM5105830			

Labour
J# 1 76NAZZZZZ002

- * PDI CLEAN
- * PDI INSPECTION
- * BRAND NEW UNIT
- * CHECKE AND EVALUATED CONCER:
PERFORMED PDI INSPECTION

Tech(s) : 48055

3125.00

Totals=====

Total - Labour 3125.00

Total Labour. 3125.00
Total Parts.. 0.00
Total Other.. 0.00
Total P.O.L.. 0.00
Total Misc... 0.00
VAT 375.00

Total Invoice 3500.00

RMP
02/27/23

[End of Invoice]

ROAD TESTED		ACKNOWLEDGMENT	
ORDER NO.	SUBLET REPAIRS	RECEIVED above vehicle from AUTOHUB CAR CARE SERVICES (ACCS) in good condition and with all repair work enumerated completed to my satisfaction.	
		All works carried out at these premises are subject to a warranty of _____ days or _____ whichever comes first on all labor and materials.	
		SIGNATURE OF OWNER _____	

CHECKLIST

10836

PAGE 1

Client : VESPA

Chassis # : RP8M66701NN1039554 Color: ORANGE

Make/Model : 5125

Engine # : M66BM 5105838 Date : 10-26-22

EMBLEMS

- (☒) Piaggio Emblem (Front)
- (☒) PVG Emblem (Crankcase)

SIDE MIRROR

- (☒) LH Side View Mirror
- (☒) RH Side View Mirror

ELECTRICAL BUTTONS

- (☒) Start Button
- (☒) Horn Button
- (☒) High&Low Button
- (☒) Passing Button (Optional)
- (☒) Left Signal Button
- (☒) Right Signal Button
- (☒) Cut Off Engine Button (Optional)
- (☒) Start & Stop Button
- (☒) ASR Button
- (☒) Mode
- (☒) Saddle Button
- (☒) Toggle Switch

LIGHTS

- (☒) Park Light
- (☒) High & Low Beam
- (☒) Front Right Signal
- (☒) Rear Right Signal
- (☒) Front Left Signal
- (☒) Rear Left Signal
- (☒) Backlight
- (☒) Brakelights
- (☒) Instrumental Panel Gauges
- (☒) Plate Light

FLUID LEVELS

- (☒) Engine Oil
- (☒) Gear Oil
- (☒) Brake Fluid
- (☒) Coolant

SCRATCHES

- (☐) No Scratches
 - (☐) W/ Scratches
- *Encircle parts that has/have scratches

COLOR

- (☐) Evenly Painted
- (☐) Not Evenly Painted

BATTERY/ HORN

- (☒) Battery
- Brand: DONGFENG Battery Voltage: 12V
- (☒) Horn

TIRES

- (☒) Good Quality
- (☐) Bad Quality
- Brand: MAXXIS
- Tire Pressure: Front _____ Rear _____

PADS DIAGNOSTIC TOOL

- (☐) PADS Checkup
- Fault : _____
- Remarks: _____

SADDLE

- (☒) Good Quality
- (☐) Bad Quality
- KEYS/ MANUAL/ TOOLS**
- (☒) Master Key
- (☒) Duplicate Key
- (☒) Service Manual
- (☒) Warranty Booklet
- (☒) Set of Screw
- (☒) Battery Holder
- (☒) Plate Holder
- (☒) reflectors (Optional)
- (☒) Under Body Caps (Optional)
- (☒) 1 Set of Tools
- (☒) Rear Shock Adjuster
- (☒) Screw Driver
- (☒) Fuse Removal Tool
- (☒) Screw driver (FLOWER KEY)
- (☒) Sparkplug Wrench

Remarks :

COMPLETE ACCESSORIES W/ BATTERY

I understand all the above items as explained to me by the releasing Officer/ Manager. I also agree that any failure on my part to adhere to any of the instructions given that may result in damages on the above mentioned parts will not be covered by warranty.

Inspected by : B. RAMOSAN
Technician/PDI Personnel

Approved by : _____
Service Manager

Approved by : _____
Sales Department

CHECKLIST

Client :

VESPA

Chassis # :

RP6M66701NV039554

Color:

10836

PAGE 2

ORANGE

Make/Model :


S125

Engine # :

ML66BM 5105838

Date :

10-26-22



LEGEND

S- Scratched

L- Loose

D- Dented

M- Missing

DD-Damaged

F- Faded

Remarks:

D. TARAMISAN



AUTOHUB CAR CARE SERVICES (ACCS)

BY SUPREME AUTOZONE PHILIPPINES INC.
Site: Buroi Cabrera Road, Brgy. San Juan, Taytay, Rizal
Tel No. (032) 533-8388
VAT REG TIN: 236-978-189-00005

BILLING STATEMENT

No: 06786

Service Invoice		Page 1 of 1		Doc # : 4253 E23997	
CUSTOMER NO. 27.08.20	CUSTOMER NAME AND ADDRESS TINOTY TALIA PHILE, INC. NO. 34 ORTIGAS AVENUE NORTH GREENHILLS SAN JUAN CITY MMN Q20	ADVISOR Aldren Padilla	COLOR WHITE	TEAM NIT GENER	
DOB DATE 27.08.20	REG. NO. UNREG	YEAR/MAKE/MODEL 22/NEATHUB VESPA 125	MODEL NO. 125	CARLINE VESPA	TAG NO.
STOCK NO.	PURCHASE ORDER NO.	CHASSIS NO.	KILOMETERS	PROB. DATE	ENG/TRANS.
DRIVER	CONTACT NO.	CONTACT NAME	CONTRACT EXP. KMS	EXP. DATE	
HOME PHONE	BUSINESS PHONE	SELLING DEALER	DELIVERY KMS	DELIVERY DATE	
VEHICLE ID	ENGINE NO.	DATE AND TIME PROMISED	TIME RECEIVED	QUOTE PRICE	AIR FWA TURBO
RF 3M66701NV0395	5 M66BM5106395	25/02/23 09:00pm	10:16am		

JA 1 70NAZZZZZ000

- * PDI CLEAN
- * PDI INSPECTION
- * BRAND NEW UNIT
- * CHECKED AND EVALUATED CONCERN:
- * PERFORMED PDI INSPECTION

Technician: 43

3125.00

Total - Labour 3125.00

Total Labour 3125.00
Total Parts 0.00
Total Other 0.00
Total P.O.L. 0.00
Total Misc. 0.00
VAT 175.00

Total Invoice

3500.00

RHP
02/27/23

ROAD TESTED

ORDER NO.	SUBJECT REPAIRS

ACKNOWLEDGMENT

RECEIVED above vehicle from AUTOHUB CAR CARE SERVICES (ACCS) in good condition and with all repair work enumerated completed to my satisfaction.
All works carried out at these premises are subject to a warranty of materials, whichever comes first on all labor and materials.

SIGNATURE OF OWNER

I AGREE TO PAY for all works required for all the above described repair at your retail charge. It is understood that any estimate given is provisional and all repairs are undertaken on a cash basis unless prior arrangements for credit have been approved.

I have READ AND ACCEPTED your terms and conditions.

5 BKS (1000 sets/box) 2 ply SH: 05001-10000 * BIR Permit No. OGH: 016AU20210020003181
Date of ATP: November 28, 2021 * Expiry Date: November 25, 2025
L0009-1008 Permit No., LUMAR-044-0820-00372 * Date: Sept 18, 2020

Printed by: supripta@supripta.com - W-3 Lot 1 A, Mercedes Avenue, Alay
(Street) Brgy. San Andres Calabang, BSM * VAT REG TIN: 101-838-883-000000

THIS BILLING STATEMENT SHALL BE VALID FOR FIVE (5) YEARS FROM THE DATE OF ATP.

CHECKLIST

10837

PAGE 1

Client : VESPA

Chassis # : RP8MG6701NV039525

Color : WHITE

Make/Model : S125

Engine # : M66BM 5105831

Date : 10-24-22

EMBLEMS

- (☒) Piaggio Emblem (Front)
(☒) PVG Emblem (Crankcase)

SIDE MIRROR

- (☒) LH Side View Mirror
(☒) RH Side View Mirror

ELECTRICAL BUTTONS

- (☒) Start Button
(☒) Horn Button
(☒) High&Low Button
(☐) Passing Button (Optional)
(☒) Left Signal Button
(☒) Right Signal Button
(☐) Cut Off Engine Button (Optional)
(☐) Start & Stop Button
(☐) ASR Button
(☒) Mode
(☐) Saddle Button
(☐) Toggle Switch

LIGHTS

- (☒) Park Light
(☒) High & Low Beam
(☒) Front Right Signal
(☒) Rear Right Signal
(☒) Front Left Signal
(☒) Rear Left Signal
(☒) Backlight
(☒) Brakelights
(☒) Instrumental Panel Gauges
(☒) Plate Light

FLUID LEVELS

- (☒) Engine Oil
(☐) Gear Oil
(☒) Brake Fluid
(☐) Coolant

SCRATCHES

- (☐) No Scratches
(☐) W/ Scratches
*Encircle parts that has/have scratches

COLOR

- (☐) Evenly Painted
(☐) Not Evenly Painted

BATTERY/ HORN

- (☒) Battery
Brand: DODGNAI Battery Voltage: 12V
(☐) Horn

TIRES

- (☒) Good Quality
(☐) Bad Quality
Brand: MAXXIS
Tire Pressure: Front _____ Rear _____

PADS DIAGNOSTIC TOOL

- (☐) PADS Checkup

Fault : _____

Remarks: _____

SADDLE

- (☒) Good Quality
(☐) Bad Quality
KEYS/ MANUAL/ TOOLS
(☒) Master Key
(☒) Duplicate Key
(☒) Service Manual
(☒) Warranty Booklet
(☒) Set of Screw
(☒) Battery Holder
(☐) Plate Holder
(☒) reflectors (Optional)
(☒) Under Body Caps (Optional)
(☐) 1 Set of Tools
(☒) Rear Shock Adjuster
(☒) Screw Driver
(☐) Fuse Removal Tool
(☐) Screw driver (FLOWER KEY)
(☒) Sparkplug Wrench

Remarks :

COMPLETE ACCESSORIES w/ BATTERY

I understand all the above items as explained to me by the releasing Officer/ Manager. I also agree that any failure on my part to adhere to any of the instructions given that may result in damages on the above mentioned parts will not be covered by warranty.

Inspected by : D. TALAMISAN
Technician/PDI Personnel

Approved by : _____
Service Manager

Approved by : _____
Sales Department

CHECKLIST

10837

PAGE 2


Client: VESPA

Chassis #: RP8M66701 NV039525 Color: WHITE

Make/Model: S 125

Engine #: M66BM 5105831

Date: 10-26-22



LEGEND

S- Scratched	L- Loose
D- Dented	M- Missing
DD-Damaged	F- Faded

Remarks:

D. THAMISA



AUTOHUB CAR CARE SERVICES (ACCS)

BY: SUPREME AUTOZONE PHILIPPINES INC.

Sitio Buroi Cabrera Road, Brgy. San Juan, Taytay, Rizal

Tel. No. : (632) 533-6398

VAT REG. TIN: 236-978-189-00006

BILLING STATEMENT

No: **06787**

Service Invoice		Page 1 of 1		Doc # : ATCJ E23998	
CUSTOMER No. 271886	CUSTOMER NAME AND ADDRESS TIN: MOTOITALIA PHILS. INC.		ADVISOR Aldrin Padilla	COLOR 48054 WHITE/	TEAM NA GENER
DOC. DATE 27/02/23	#234 ORTIGAS AVENUE		YEAR/MAKE/MODEL 22/NEXTHUB/VESPA 5125	TAG No.	
REG. No. UNREG	NORTH GREENHILLS		MODEL No. 5125	CAR LINE VESPA	ENG./TRANS.
STOCK No.	SAN JUAN CITY MMN 000		CHASSIS No.	KILOMETERS	PROD. DATE
PURCHASE ORDER No.	DRIVER	CONTACT No.	CONTACT NAME	CONTRACT EXP. KMS	EXP. DATE
CA <input type="checkbox"/>	F/C <input type="checkbox"/>	CH <input type="checkbox"/>	HOME PHONE	BUSINESS PHONE	TERMS
C/C <input type="checkbox"/>	WAR <input type="checkbox"/>	INT <input type="checkbox"/>	VEHICLE ID	ENGINE No.	Charge
RPBM66701NV039587			M66BM5106379		
DATE AND TIME PROMISED 25/02/23 09:00pm			TIME RECEIVED 10:16am		
QUOTE PRICE			AIR	PWR	TURBO

Labour
J# 1 76NAZZZZZ002

* PDI CLEAN
* PDI INSPECTION
* BRAND NEW UNIT
* CHECKED AND EVALUATED CONCERN:
PERFORMED PDI INSPECTION

Tech(s) : 48063

3125.00

Totals===== Total - Labour 3125.00

Total Labour. 3125.00
Total Parts.. 0.00
Total Other.. 0.00
Total P.O.L.. 0.00
Total Misc... 0.00
VAT 375.00

Total Invoice 3500.00

RJR
02/27/23

[End of Invoice]

ROAD TESTED		ACKNOWLEDGMENT	
ORDER NO.	SUBLET REPAIRS	RECEIVED above vehicle from AUTOHUB CAR CARE SERVICES (ACCS) in good condition and with all repair work enumerated completed to my satisfaction.	
		All works carried out at these premises are subject to a warranty of _____ days or _____ whichever comes first on all labor and materials.	
		SIGNATURE OF OWNER _____	

CHECKLIST

10838

PAGE 1

Client : VESPA Chassis # : RPM66101NV030587 Color : WHITE
 Make/Model : VESPA SRS 3V Engine # : M66BM 510379 Date : 10-24-22

EMBLEMS

- () Piaggio Emblem (Front)
 (/) PVG Emblem (Crankcase)

SIDE MIRROR

- () LH Side View Mirror
 (/) RH Side View Mirror

ELECTRICAL BUTTONS

- () Start Button
 (/) Horn Button
 (/) High & Low Button
 (/) Passing Button (Optional)
 (/) Left Signal Button
 (/) Right Signal Button
 (/) Cut Off Engine Button (Optional)
 (/) Start & Stop Button
 (/) ASR Button
 () Mode
 (/) Saddle Button
 (/) Toggle Switch

LIGHTS

- () Park Light
 (/) High & Low Beam
 (/) Front Right Signal
 (/) Rear Right Signal
 (/) Front Left Signal
 (/) Rear Left Signal
 (/) Backlight
 (/) Brakelights
 (/) Instrumental Panel Gauges
 (/) Plate Light

FLUID LEVELS

- () Engine Oil
 (/) Gear Oil
 (/) Brake Fluid
 (/) Coolant

SCRATCHES

- () No Scratches
 (/) W/ Scratches
 *Encircle parts that has/have scratches

COLOR

- () Evenly Painted
 () Not Evenly Painted

BATTERY/ HORN

- () Battery
 Brand : _____ Battery Voltage : _____
 () Horn

TIRES

- () Good Quality
 (/) Bad Quality
 Brand : _____
 Tire Pressure : _____ Front _____ Rear _____

PADS DIAGNOSTIC TOOL

- () PADS Checkup
 Fault : _____
 Remarks : _____

SADDLE

- (/) Good Quality
 (/) Bad Quality
KEYS/ MANUAL/ TOOLS
 () Master Key
 (/) Duplicate Key
 (/) Service Manual
 (/) Warranty Booklet
 (/) Set of Screw
 (/) Battery Holder
 (/) Plate Holder
 () reflectors (Optional)
 (/) Under Body Caps (Optional)
 (/) 1 Set of Tools
 (/) Rear Shock Adjuster
 (/) Screw Driver
 (/) Fuse Removal Tool
 () Screw driver (FLOWER KEY)
 (/) Sparkplug Wrench

Remarks :

BUFFING ALL PANEL

I understand all the above items as explained to me by the releasing Officer/ Manager. I also agree that any failure on my part to adhere to any of the instructions given that may result in damages on the above mentioned parts will not be covered by warranty.

Inspected by :

Technician/PDI Personnel

Approved by :

Service Manager

Approved by :

Sales Department

CHECKLIST

Client :

VESPA

Chassis # :

RPS MCG 701N V0391581
(MCG 5m 5106370)

Color:

10838

PAGE 2

WHITE

Make/Model :


VESPA 5125 3V

Engine # :

16m

Date :

10-26-72



LEGEND

S- Scratched

L- Loose

D- Dented

M- Missing

DD-Damaged

F- Faded

Remarks:

BUFFING ALL PANEL

CHECKLIST

10301 PAGE 1

Client : _____ Chassis # : 040162 Color: White
 Make/Model : S125 Engine # : 5109365 Date : 10-20-20

EMBLEMS

- ☒ Piaggio Emblem (Front)
☒ PVG Emblem (Crankcase)

SIDE MIRROR

- ☒ LH Side View Mirror
☒ RH Side View Mirror

ELECTRICAL BUTTONS

- ☒ Start Button
☒ Horn Button
☒ High&Low Button
☒ Passing Button (Optional)
☒ Left Signal Button
☒ Right Signal Button
☒ Cut Off Engine Button (Optional)
☒ Start & Stop Button
☒ ASR Button
☒ Mode
☒ Saddle Button
☒ Toggle Switch

LIGHTS

- ☒ Park Light
☒ High & Low Beam
☒ Front Right Signal
☒ Rear Right Signal
☒ Front Left Signal
☒ Rear Left Signal
☒ Backlight
☒ Brakelights
☒ Instrumental Panel Gauges
☒ Plate Light

FLUID LEVELS

- ☒ Engine Oil
☒ Gear Oil
☒ Brake Fluid
☒ Coolant

SCRATCHES

- ☒ No Scratches
☒ W/ Scratches
 *Encircle parts that has/have scratches

COLOR

- ☒ Evenly Painted
☒ Not Evenly Painted

BATTERY/ HORN

- ☒ Battery
 Brand: Ducati Battery Voltage: _____
☒ Horn

TIRES

- ☒ Good Quality
☒ Bad Quality
 Brand: _____
 Tire Pressure: _____ Front _____ Rear _____

PADS DIAGNOSTIC TOOL

- ☒ PADS Checkup
 Fault : _____
 Remarks: _____

SADDLE

- ☒ Good Quality
☒ Bad Quality
KEYS/ MANUAL/ TOOLS
☒ Master Key
☒ Duplicate Key
☒ Service Manual
☒ Warranty Booklet
☒ Set of Screw
☒ Battery Holder
☒ Plate Holder
☒ reflectors (Optional)
☒ Under Body Caps (Optional)
☒ 1 Set of Tools
☒ Rear Shock Adjuster
☒ Screw Driver
☒ Fuse Removal Tool
☒ Screw driver (FLOWER KEY)
☒ Sparkplug Wrench

Remarks :

I understand all the above items as explained to me by the releasing Officer/ Manager. I also agree that any failure on my part to adhere to any of the instructions given that may result in damages on the above mentioned parts will not be covered by warranty.

Inspected by : _____
 Technician/PDI Personnel

Approved by : _____
 Service Manager

Approved by : _____
 Sales Department

CHECKLIST

10301

PAGE 2

Client :

Chassis # :

Color:

Make/Model :

Engine # :

Date :

ROSMEDONIN V


040162

white

S125

5109365

10-20-11



LEGEND

S- Scratched L- Loose
D- Dented M- Missing
DD-Damaged F- Faded

Remarks:

Complete
tools
battery
oil, etc.



AUTOHUB CAR CARE SERVICES (ACCS)

BY: SUPREME AUTOZONE PHILIPPINES INC.

Sitio Buroi Cabrera Road, Brgy. San Juan, Taytay, Rizal

Tel. No.: (632) 533-6398

VAT REG. TIN: 236-978-189-00006

BILLING STATEMENT

No: **06789**

Service Invoice

Page 1 of 1

Doc # : ATCJ E24000

CUSTOMER No. 211806	CUSTOMER NAME AND ADDRESS TIN: MOTOITALIA PHILS. INC. #234 ORTIGAS AVENUE NORTH GREENHILLS SAN JUAN CITY MMN 000			ADVISOR Aldrin Padilla	COLOR 480 4 RED/	TEAM NA GENER
DOC. DATE 27/02/23				YEAR/MAKE/MODEL 22/NEXTHUB/VESPA S125	TAG No.	
REG. No. UNREG				MODEL No. S125	CAR LINE VESPA	ENG./TRANS.
STOCK No.				CHASSIS No.	KILOMETERS 2	PROD. DATE
PURCHASE ORDER No.	DRIVER	CONTACT No.	CONTACT NAME	CONTRACT EXP KMS	EXP. DATE	
CA <input type="checkbox"/>	PC <input type="checkbox"/>	CH <input type="checkbox"/>	HOME PHONE	BUSINESS PHONE	TERMS	SELLING DEALER
C/C <input type="checkbox"/>	WAR <input type="checkbox"/>	INT <input type="checkbox"/>	VEHICLE ID RP8M66701NV039139	ENGINE No. M66BM5103695	DATE AND TIME PROMISED 25/02/23 09:00pm	DELIVERY KMS
					TIME RECEIVED 10:17am	DELIVERY DATE
					QUOTE PRICE	AIR PWR TURBO

Labour
J# 1 76NAZZZZZ002

Tech(s) : 48048

3125.00

- * PDI CLEAN
- * PDI INSPECTION
- * BRAND NEW UNIT
- * CHECKED AND EVALUATED CONCERN:
PERFORMED PDI INSPECTION

Total - Labour 3125.00

Totals:=====

Total Labour. 3125.00

Total Parts.. 0.00

Total Other.. 0.00

Total P.O.L.. 0.00

Total Misc... 0.00

VAT 375.00

Total Invoice 3500.00

[Signature]
02/27/23

[End of Invoice]

ROAD TESTED		ACKNOWLEDGMENT	
ORDER NO.	SUBLET REPAIRS	RECEIVED above vehicle from AUTOHUB CAR CARE SERVICES (ACCS) in good condition and with all repair work enumerated completed to my satisfaction.	
		All works carried out at these premises are subject to a warranty of _____ days or _____ whichever comes first on all labor and materials.	
		SIGNATURE OF OWNER _____	
		I AGREE TO PAY for all works required for all the above described repair at your retail charge. It is understood that any estimate given is provisional and all repairs are undertaken on a cash basis unless prior arrangements for credit have been approved.	
		I have READ AND ACCEPTED your terms and conditions.	

CHECKLIST

10997

PAGE 1

RP8M66701

Client: Vespa

Chassis #: NV1039139

Color: Red

Make/Model: 5125

Engine #: 5103695

Date: 10-8-22

EMBLEMS

- ☒ Piaggio Emblem (Front)
- ☒ PVG Emblem (Crankcase)

SIDE MIRROR

- ☒ LH Side View Mirror
- ☒ RH Side View Mirror

ELECTRICAL BUTTONS

- ☒ Start Button
- ☒ Horn Button
- ☒ High&Low Button
- ☒ Passing Button (Optional)
- ☒ Left Signal Button
- ☒ Right Signal Button
- ☒ Cut Off Engine Button (Optional)
- ☒ Start & Stop Button
- ☒ ASR Button
- ☒ Mode
- ☒ Saddle Button
- ☒ Toggle Switch

LIGHTS

- ☒ Park Light
- ☒ High & Low Beam
- ☒ Front Right Signal
- ☒ Rear Right Signal
- ☒ Front Left Signal
- ☒ Rear Left Signal
- ☒ Backlight
- ☒ Brakelights
- ☒ Instrumental Panel Gauges
- ☒ Plate Light

FLUID LEVELS

- ☒ Engine Oil
- ☒ Gear Oil
- ☒ Brake Fluid
- ☒ Coolant

SCRATCHES

- ☒ No Scratches
 - ☒ W/ Scratches
- *Encircle parts that has/have scratches

COLOR

- ☒ Evenly Painted
- ☒ Not Evenly Painted

BATTERY/ HORN

- ☒ Battery
- Brand: _____ Battery Voltage: _____
- ☒ Horn

TIRES

- ☒ Good Quality
- ☒ Bad Quality
- Brand: _____
- Tire Pressure: _____ Front _____ Rear _____

PADS DIAGNOSTIC TOOL

- ☒ PADS Checkup
- Fault : _____
- Remarks: _____

SADDLE

- ☒ Good Quality
- ☒ Bad Quality
- KEYS/ MANUAL/ TOOLS**
- ☒ Master Key
- ☒ Duplicate Key
- ☒ Service Manual
- ☒ Warranty Booklet
- ☒ Set of Screw
- ☒ Battery Holder
- ☒ Plate Holder
- ☒ reflectors (Optional)
- ☒ Under Body Caps (Optional)
- ☒ 1 Set of Tools
- ☒ Rear Shock Adjuster
- ☒ Screw Driver
- ☒ Fuse Removal Tool
- ☒ Screw driver (FLOWER KEY)
- ☒ Sparkplug Wrench

Remarks :

Missing Handle Screw

I understand all the above items as explained to me by the releasing Officer/ Manager. I also agree that any failure on my part to adhere to any of the instructions given that may result in damages on the above mentioned parts will not be covered by warranty.


Inspected by: J. Beyer
Technician/PDI Personnel

Approved by: _____
Service Manager

Approved by: _____
Sales Department

CHECKLIST

Client: Vespa Chassis #: RP8mb6701 Color: 10997 red PAGE 2
Make/Model: S125 Engine #: 5103695 Date: 10-8-22



LEGEND

S- Scratched L- Loose
D- Dented M- Missing
DD-Damaged F- Faded

Remarks:



AUTOHUB CAR CARE SERVICES (ACCS)

BY: SUPREME AUTOZONE PHILIPPINES INC.

Sitio Buroi Cabrera Road, Brgy. San Juan, Taytay, Rizal

Tel. No.: (632) 533-6398

VAT REG. TIN: 236-978-189-00006

BILLING STATEMENT

No: **06790**

Service Invoice		Page 1 of 1		Doc # : ATCJ E24004	
CUSTOMER No. 211806	CUSTOMER NAME AND ADDRESS TIN: MOTOITALIA PHILS. INC. #234 ORTIGAS AVENUE NORTH GREENHILLS SAN JUAN CITY MMN 000		ADVISOR Aldrin Padilla	COLOR 48004 ORANGE/	TEAM NH GENER
DOC. DATE 27/02/23			YEAR/MAKE/MODEL 22/NEXTHUB/VESPA S125	TAG No.	
REG. No. UNREG			MODEL No. S125	CAR LINE VESPA	ENG./TRANS.
STOCK No.			CHASSIS No.	KILOMETERS	PROD. DATE
PURCHASE ORDER No.	DRIVER	CONTACT No.	CONTACT NAME	CONTRACT EXP. KMS	EXP. DATE
GA <input type="checkbox"/>	FC <input type="checkbox"/>	CH <input type="checkbox"/>	HOME PHONE	BUSINESS PHONE	TERMS
C/C <input type="checkbox"/>	WAR <input type="checkbox"/>	INT <input type="checkbox"/>	Charge		SELLING DEALER
VEHICLE ID RP8M66701NV039109		ENGINE No. M66BM5103683	DATE AND TIME PROMISED 25/02/23 09:00pm	TIME RECEIVED 10:18am	QUOTE PRICE
			AIR	PWR	TURBO

Labour-----
J# 1 76NAZZZZZ002
PDI CLEAN
PDI INSPECTION
BRAND NEW UNIT
CHECKED AND EVALUATED CONCERN:
PERFORMED PDI INSPECTION
Tech(s) : 48048 3125.00
Total - Labour 3125.00
Totals-----
Total Labour. 3125.00
Total Parts.. 0.00
Total Other.. 0.00
Total P.O.L.. 0.00
Total Misc... 0.00
VAT 375.00
Total Invoice 3500.00
RJP
02/27/23

[End of Invoice]

ROAD TESTED		ACKNOWLEDGMENT RECEIVED above vehicle from AUTOHUB CAR CARE SERVICES (ACCS) in good condition and with all repair work enumerated completed to my satisfaction. All works carried out at these premises are subject to a warranty of _____ days or _____ whichever comes first on all labor and materials. SIGNATURE OF OWNER _____		I AGREE TO PAY for all works required for all the above described repair at your retail charge. It is understood that any estimate given is provisional and all repairs are undertaken on a cash basis unless prior arrangements for credit have been approved. I have READ AND ACCEPTED your terms and conditions.	
ORDER NO.	SUBLET REPAIRS				

CHECKLIST

10883

PAGE 1

RP6M66701

Client :

Vespa

Chassis # :

NV1030109

Color:

Orange

Make/Model :

S125

Engine # :

5103683

Date :

10-10-22

EMBLEMS

- ☒ Piaggio Emblem (Front)
- ☒ PVG Emblem (Crankcase)

SIDE MIRROR

- ☒ LH Side View Mirror
- ☒ RH Side View Mirror

ELECTRICAL BUTTONS

- ☒ Start Button
- ☒ Horn Button
- ☒ High&Low Button
- ☐ Passing Button (Optional)
- ☒ Left Signal Button
- ☒ Right Signal Button
- ☐ Cut Off Engine Button (Optional)
- ☐ Start & Stop Button
- ☐ ASR Button
- ☒ Mode
- ☐ Saddle Button
- ☐ Toggle Switch

LIGHTS

- ☐ Park Light
- ☒ High & Low Beam
- ☒ Front Right Signal
- ☒ Rear Right Signal
- ☒ Front Left Signal
- ☒ Rear Left Signal
- ☒ Backlight
- ☒ Brakelights
- ☒ Instrumental Panel Gauges
- ☒ Plate Light

FLUID LEVELS

- ☒ Engine Oil
- ☒ Gear Oil
- ☒ Brake Fluid
- ☐ Coolant

SCRATCHES

- ☐ No Scratches
 - ☐ W/ Scratches
- *Encircle parts that has/have scratches

COLOR

- ☐ Evenly Painted
- ☐ Not Evenly Painted

BATTERY/ HORN

- ☒ Battery
- Brand: _____ Battery Voltage: _____
- ☒ Horn

TIRES

- ☒ Good Quality
- ☐ Bad Quality
- Brand: _____
- Tire Pressure: _____ Front _____ Rear _____

PADS DIAGNOSTIC TOOL

- ☐ PADS Checkup
- Fault : _____
- Remarks: _____

SADDLE

- ☒ Good Quality
- ☐ Bad Quality
- KEYS/ MANUAL/ TOOLS**
- ☒ Master Key
- ☒ Duplicate Key
- ☒ Service Manual
- ☒ Warranty Booklet
- ☐ Set of Screw
- ☒ Battery Holder
- ☐ Plate Holder
- ☐ reflectors (Optional)
- ☐ Under Body Caps (Optional)
- ☐ 1 Set of Tools
- ☒ Rear Shock Adjuster
- ☒ Screw Driver
- ☒ Fuse Removal Tool
- ☐ Screw driver (FLOWER KEY)
- ☒ Sparkplug Wrench

Remarks :

Complete Accessories by tools w/ battery

I understand all the above items as explained to me by the releasing Officer/ Manager. I also agree that any failure on my part to adhere to any of the instructions given that may result in damages on the above mentioned parts will not be covered by warranty.

Inspected by :

Technician/PDI Personnel

Approved by :


Service Manager

Approved by :

Sales Department

CHECKLIST

Client: Vespa Chassis #: N-103909 Color: Orange
Make/Model: S125 Engine #: 5703683 Date: 10-10-22



LEGEND

S- Scratched	L- Loose
D- Dented	M- Missing
DD-Damaged	F- Faded

Remarks:



AUTOHUB CAR CARE SERVICES (ACCS)

BY: SUPREME AUTOZONE PHILIPPINES INC.

Sitio Buroi Cabrera Road, Brgy. San Juan, Taytay, Rizal

Tel. No.: (632) 533-6398

VAT REG. TIN: 236-978-189-00006

BILLING STATEMENT

No: **06791**

Service Invoice

Page 1 of 1

Doc # : ATCJ E24005

CUSTOMER No. 211806	CUSTOMER NAME AND ADDRESS TIN: MOTORIALIA PHILS. INC. #234 ORTIGAS AVENUE NORTH GREENHILLS SAN JUAN CITY MMN 000	ADVISOR Aldrin Padilla	COLOR 48004 GREY/	TEAM NA GENER
DOC. DATE 27/02/23		YEAR/MAKE/MODEL 22/NEXTHUB/VESPA 5125		TAG No.
REG. No. UNREG		MODEL No. 5125	CAR LINE VESPA	ENG./TRANS.
STOCK No.		CHASSIS No.	KILOMETERS	PROD. DATE
PURCHASE ORDER No.	DRIVER	CONTACT No.	CONTACT NAME	CONTRACT EXP KMS
	HOME PHONE	BUSINESS PHONE	SELLING DEALER	DELIVERY KMS
CA <input type="checkbox"/>	F/C <input type="checkbox"/>	CH <input type="checkbox"/>	VEHICLE ID RP8M66701NV0390	ENGINE No. M66BM5102637
C/C <input type="checkbox"/>	WAR <input type="checkbox"/>	INT <input type="checkbox"/>	DATE AND TIME PROMISED 25/02/23 09:00pm	TIME RECEIVED 10:19am
			QUOTE PRICE	AIR PWR TURBO

Labour
J# 1 76NAZZZZZ002

PDI CLEAN
* PDI INSPECTION
* BRAND NEW UNIT
* CHECKED AND EVALUATED CONCERN:
PERFORMED PDI INSPECTION

Tech(s) : 48048 3125.00

Total - Labour 3125.00

Totals

Total Labour. 3125.00
Total Parts.. 0.00
Total Other.. 0.00
Total P.O.L.. 0.00
Total Misc... 0.00
VAT 375.00
Total Invoice 3500.00

[Signature]
02/27/23

End of Invoice 1

ROAD TESTED		ACKNOWLEDGMENT	
		RECEIVED above vehicle from AUTOHUB CAR CARE SERVICES (ACCS) in good condition and with all repair work enumerated completed to my satisfaction.	
		All works carried out at these premises are subject to a warranty of _____ days or _____ whichever comes first on all labor and materials.	
		SIGNATURE OF OWNER _____	
ORDER NO.	SUBLET REPAIRS	I AGREE TO PAY for all works required for all the above described repair at your retail charge. It is understood that any estimate given is provisional and all repairs are undertaken on a cash basis unless prior arrangements for credit have been approved.	
		I have READ AND ACCEPTED your terms and conditions.	

CHECKLIST

12493

PAGE 1

Client : VEDA Chassis # : 0391048 Color : Gray
 Make/Model : 5125 Engine # : 512637 Date : 10/3/22

EMBLEMS

- () Piaggio Emblem (Front)
 () PVG Emblem (Crankcase)

SIDE MIRROR

- () LH Side View Mirror
 () RH Side View Mirror

ELECTRICAL BUTTONS

- () Start Button
 () Horn Button
 () High&Low Button
 () Passing Button (Optional)
 () Left Signal Button
 () Right Signal Button
 () Cut Off Engine Button (Optional)
 () Start & Stop Button
 () ASR Button
 () Mode
 () Saddle Button
 () Toggle Switch

LIGHTS

- () Park Light
 () High & Low Beam
 () Front Right Signal
 () Rear Right Signal
 () Front Left Signal
 () Rear Left Signal
 () Backlight
 () Brakelights
 () Instrumental Panel Gauges
 () Plate Light

FLUID LEVELS

- () Engine Oil
 () Gear Oil
 () Brake Fluid
 () Coolant

SCRATCHES

- () No Scratches
 () W/ Scratches
 *Encircle parts that has/have scratches

COLOR

- () Evenly Painted
 () Not Evenly Painted

BATTERY/ HORN

- () Battery
 Brand: _____ Battery Voltage: _____
 () Horn

TIRES

- () Good Quality
 () Bad Quality
 Brand: _____
 Tire Pressure: _____ Front _____ Rear _____

PADS DIAGNOSTIC TOOL

- () PADS Checkup
 Fault : _____
 Remarks: _____

SADDLE

- () Good Quality
 () Bad Quality
KEYS/ MANUAL/ TOOLS
 () Master Key
 () Duplicate Key
 () Service Manual
 () Warranty Booklet
 () Set of Screw
 () Battery Holder
 () Plate Holder
 () reflectors (Optional)
 () Under Body Caps (Optional)
 () 1 Set of Tools
 () Rear Shock Adjuster
 () Screw Driver
 () Fuse Removal Tool
 () Screw driver (FLOWER KEY)
 () Sparkplug Wrench

Remarks :

I understand all the above items as explained to me by the releasing Officer/ Manager. I also agree that any failure on my part to adhere to any of the instructions given that may result in damages on the above mentioned parts will not be covered by warranty.

Inspected by : JOEL ACEBES
 Technician/PDI Personnel

Approved by : _____
 Service Manager

Approved by : _____
 Sales Department

CHECKLIST

PAGE 2

Client:

VESPA
5125

Chassis #:

039048
510237

Color:

12492
GRAY


Make/Model:

Engine #:

5102637

Date:

10/3/22



LEGEND

S- Scratched L- Loose
D- Dented M- Missing
DD-Damaged F- Faded

Remarks:

complete tools, side mirror, battery



AUTOHUB CAR CARE SERVICES (ACCS)

BY: SUPREME AUTOZONE PHILIPPINES INC.

Sitio Buroi Cabrera Road, Brgy. San Juan, Taytay, Rizal

Tel. No.: (632) 533-6398

VAT REG. TIN: 236-978-189-00006

BILLING STATEMENT

No: **06792**

Service Invoice		Page 1 of 1		Doc # : ATCJ E24006	
CUSTOMER No. 211806	CUSTOMER NAME AND ADDRESS TIN: MOTOITALIA PHILS. INC.		ADVISOR Aldrin Padilla	COLOR 480 4 RED/	TEAM NH GENER
DOC. DATE 27/02/23	#234 ORTIGAS AVENUE		YEAR/MAKE/MODEL 22/NEXTHUB/VESPA 5125	TAG No.	
REG. No. UNREG	NORTH GREENHILLS		MODEL No. 5125	CAR LINE VESPA	ENG./TRANS.
STOCK No.	SAN JUAN CITY MMN 000		CHASSIS No.	KILOMETERS	PROD. DATE
PURCHASE ORDER No.	DRIVER	CONTACT No.	CONTACT NAME	CONTRACT EXP. KMS	EXP. DATE
CA <input type="checkbox"/>	FC <input type="checkbox"/>	CH <input type="checkbox"/>	HOME PHONE	BUSINESS PHONE	TERMS
C/C <input type="checkbox"/>	WAR <input type="checkbox"/>	INT <input type="checkbox"/>	VEHICLE ID RPBM66701NV0391	ENGINE No. 7 M66BMS103696	DATE AND TIME PROMISED 25/02/23 09:00pm
			SELLING DEALER	DELIVERY KMS	DELIVERY DATE
			DATE AND TIME RECEIVED 10:20am	QUOTE PRICE	AIR PWR TURBO

Labour
J# 1 76NAZZZZ002

* PDI CLEAN
* PDI INSPECTION
* BRAND NEW UNIT
* CHECKED AND EVALUATED CONCERN:
* PERFORMED PDI INSPECTION

Tech(s) : 48061

3125.00

Total - Labour 3125.00

Totals=====

Total Labour. 3125.00
Total Parts.. 0.00
Total Other.. 0.00
Total P.O.L.. 0.00
Total Misc... 0.00
VAT 375.00

Total Invoice 3500.00

[Signature]
02/27/23

[End of Invoice]

ROAD TESTED		ACKNOWLEDGMENT	
ORDER NO.	SUBLET REPAIRS	RECEIVED above vehicle from AUTOHUB CAR CARE SERVICES (ACCS) in good condition and with all repair work enumerated completed to my satisfaction.	
		All works carried out at these premises are subject to a warranty of _____ days or _____ whichever comes first on all labor and materials.	
		SIGNATURE OF OWNER _____	
		I AGREE TO PAY for all works required for all the above described repair at your retail charge. It is understood that any estimate given is provisional and all repairs are undertaken on a cash basis unless prior arrangements for credit have been approved.	
		I have READ AND ACCEPTED your terms and conditions.	

CHECKLIST

RP6MB6CND1NV

12394

PAGE 1

Client :

Chassis # :

039147

Color :

Red

Make/Model :

Vespa S 125

Motor

Engine # :

5103696

Date :

9-30-2022

EMBLEMS

- () Piaggio Emblem (Front)
() PVG Emblem (Crankcase)

SIDE MIRROR

- () LH Side View Mirror
() RH Side View Mirror

ELECTRICAL BUTTONS

- () Start Button
() Horn Button
() High&Low Button
() Passing Button (Optional)
() Left Signal Button
() Right Signal Button
() Cut Off Engine Button (Optional)
() Start & Stop Button
() ASR Button
() Mode
() Saddle Button
() Toggle Switch

LIGHTS

- () Park Light
() High & Low Beam
() Front Right Signal
() Rear Right Signal
() Front Left Signal
() Rear Left Signal
() Backlight
() Brakelights
() Instrumental Panel Gauges
() Plate Light

FLUID LEVELS

- () Engine Oil
() Gear Oil
() Brake Fluid
() Coolant

SCRATCHES

- () No Scratches
() W/ Scratches
*Encircle parts that has/have scratches

COLOR

- () Evenly Painted
() Not Evenly Painted

BATTERY/ HORN

- () Battery
Brand: Panasonic Battery Voltage: _____
() Horn

TIRES

- () Good Quality
() Bad Quality
Brand: Maxxis
Tire Pressure: Front _____ Rear _____

PADS DIAGNOSTIC TOOL

- () PADS Checkup

Fault : _____

Remarks: _____

SADDLE

- () Good Quality
() Bad Quality
KEYS/ MANUAL/ TOOLS
() Master Key
() Duplicate Key
() Service Manual
() Warranty Booklet
() Set of Screw
() Battery Holder
() Plate Holder
() reflectors (Optional)
() Under Body Caps (Optional)
() 1 Set of Tools
() Rear Shock Adjuster
() Screw Driver
() Fuse Removal Tool
() Screw driver (FLOWER KEY)
() Sparkplug Wrench

Remarks :

I understand all the above items as explained to me by the releasing Officer/ Manager. I also agree that any failure on my part to adhere to any of the instructions given that may result in damages on the above mentioned parts will not be covered by warranty.

Inspected by :

W. Noreña

Technician/PDI Personnel

Approved by :

Service Manager

Approved by :

Sales Department

CHECKLIST

RP6MB6701 NV

12394

PAGE 2

Client :

Chassis # :

039147

Color:

Red

Make/Model :


Vespa S 125

Engine # :

7103696

Date :

9-10-2021



W. Brea

LEGEND

S- Scratched

L- Loose

D- Dented

M- Missing

DD-Damaged

F- Faded

Remarks:

CHECKLIST

10888

PAGE 1

Client : Vespa Chassis # : NV039120 Color : Black
 Make/Model : 5125 Engine # : 5103668 Date : 10-10-22

EMBLEMS

- () Piaggio Emblem (Front)
 () PVG Emblem (Crankcase)

SIDE MIRROR

- () LH Side View Mirror
 () RH Side View Mirror

ELECTRICAL BUTTONS

- () Start Button
 () Horn Button
 () High&Low Button
 () Passing Button (Optional)
 () Left Signal Button
 () Right Signal Button
 () Cut Off Engine Button (Optional)
 () Start & Stop Button
 () ASR Button
 () Mode
 () Saddle Button
 () Toggle Switch

LIGHTS

- () Park Light
 () High & Low Beam
 () Front Right Signal
 () Rear Right Signal
 () Front Left Signal
 () Rear Left Signal
 () Backlight
 () Brakelights
 () Instrumental Panel Gauges
 () Plate Light

FLUID LEVELS

- () Engine Oil
 () Gear Oil
 () Brake Fluid
 () Coolant

SCRATCHES

- () No Scratches
 () W/ Scratches
 *Encircle parts that has/have scratches

COLOR

- () Evenly Painted
 () Not Evenly Painted

BATTERY/ HORN

- () Battery
 Brand: _____ Battery Voltage: _____
 () Horn

TIRES

- () Good Quality
 () Bad Quality
 Brand: _____
 Tire Pressure: _____ Front _____ Rear _____

PADS DIAGNOSTIC TOOL

- () PADS Checkup
 Fault : _____
 Remarks: _____

SADDLE

- () Good Quality
 () Bad Quality
KEYS/ MANUAL/ TOOLS
 () Master Key
 () Duplicate Key
 () Service Manual
 () Warranty Booklet
 () Set of Screw
 () Battery Holder
 () Plate Holder
 () reflectors (Optional)
 () Under Body Caps (Optional)
 () 1 Set of Tools
 () Rear Shock Adjuster
 () Screw Driver
 () Fuse Removal Tool
 () Screw driver (FLOWER KEY)
 () Sparkplug Wrench

Remarks :

Completed Accessories to be installed w/ battery

I understand all the above items as explained to me by the releasing Officer/ Manager. I also agree that any failure on my part to adhere to any of the instructions given that may result in damages on the above mentioned parts will not be covered by warranty.

Inspected by : Arado
 Technician/PDI Personnel

Approved by : _____
 Service Manager

Approved by : _____
 Sales Department

CHECKLIST

RRSM6901

10888

PAGE 2

Client :

Vespa
S125

Chassis # :

NY039120

Color :

Black


Make/Model :

Modern
Engine # :

5703648

Date :

10-10-20



LEGEND

S- Scratched L- Loose
D- Dented M- Missing
DD-Damaged F- Faded

Remarks:



AUTOHUB CAR CARE SERVICES (ACCS)

BY: SUPREME AUTOZONE PHILIPPINES INC.

Sitio Buroi Cabrera Road, Brgy. San Juan, Taytay, Rizal

Tel. No. (632) 533-6398

VAT REG. TIN: 236-978-189-00006

BILLING STATEMENT

No: **06794**

Service Invoice		Page 1 of 1		Doc # : ATCJ E24008	
CUSTOMER No. 211806	CUSTOMER NAME AND ADDRESS TIN: MOTOITALIA PHILS. INC.		ADVISOR Aldrin Padilla	COLOR 48054 ORANGE/	TEAM NH GENER
DOC. DATE 27/02/23	#234 ORTIGAS AVENUE		YEAR/MAKE/MODEL 22/NEXTHUB/VESPA S125	TAG No.	
REG. No. UNREG	NORTH GREENHILLS		MODEL No. S125	CAR LINE VESPA	ENG./TRANS.
STOCK No.	SAN JUAN CITY MMN 000		CHASSIS No.	KILOMETERS	PROD. DATE
PURCHASE ORDER No.	DRIVER	CONTACT No.	CONTACT NAME	CONTRACT EXP. KMS	EXP DATE
CA <input type="checkbox"/>	F/C <input type="checkbox"/>	OH <input type="checkbox"/>	HOME PHONE	BUSINESS PHONE	TERMS
C/C <input type="checkbox"/>	WAR <input type="checkbox"/>	INT <input type="checkbox"/>	VEHICLE ID RP8M66701NV0391	ENGINE No. 0 M66BM5103682	DATE AND TIME PROMISED 25/02/23 09:00pm
			SELLING DEALER	DELIVERY KMS	DELIVERY DATE
			TIME RECEIVED 10:21am	QUOTE PRICE	AIR PWR TURBO

Labour
J# 1 76NAZZZZ7002

PDI CLEAN
* PDI INSPECTION
* BRAND NEW UNIT
* CHECKED AND EVALUATED CONCERN:
PERFORMED PDI INSPECTION

Tech(s) : 48048

3125.00

Total - Labour 3125.00

Totals:=====

Total Labour..	3125.00
Total Parts..	0.00
Total Other..	0.00
Total P.O.L..	0.00
Total Misc...	0.00
VAT	375.00
Total Invoice	3500.00

RJP
02/27/23

[End of Invoice]

ROAD TESTED		ACKNOWLEDGMENT	
ORDER NO.	SUBLET REPAIRS	RECEIVED above vehicle from AUTOHUB CAR CARE SERVICES (ACCS) in good condition and with all repair work enumerated completed to my satisfaction.	
		All works carried out at these premises are subject to a warranty of _____ days or _____ whichever comes first on all labor and materials.	
		SIGNATURE OF OWNER _____	
		I AGREE TO PAY for all works required for all the above described repair at your retail charge. It is understood that any estimate given is provisional and all repairs are undertaken on a cash basis unless prior arrangements for credit have been approved.	
		I have READ AND ACCEPTED your terms and conditions.	

CHECKLIST

RD866701

10889

PAGE 1

Client : Vespa

Chassis # : NV039110

Color : Orange

Make/Model : S125

Engine # : 5103682

Date : 10-10-22

EMBLEMS

- ☒ Piaggio Emblem (Front)
- ☒ PVG Emblem (Crankcase)

SIDE MIRROR

- ☒ LH Side View Mirror
- ☒ RH Side View Mirror

ELECTRICAL BUTTONS

- ☒ Start Button
- ☒ Horn Button
- ☒ High&Low Button
- ☐ Passing Button (Optional)
- ☒ Left Signal Button
- ☒ Right Signal Button
- ☐ Cut Off Engine Button (Optional)
- ☐ Start & Stop Button
- ☐ ASR Button
- ☒ Mode
- ☐ Saddle Button
- ☐ Toggle Switch

LIGHTS

- ☐ Park Light
- ☒ High & Low Beam
- ☒ Front Right Signal
- ☒ Rear Right Signal
- ☒ Front Left Signal
- ☒ Rear Left Signal
- ☒ Backlight
- ☒ Brakelights
- ☒ Instrumental Panel Gauges
- ☒ Plate Light

FLUID LEVELS

- ☒ Engine Oil
- ☐ Gear Oil
- ☒ Brake Fluid
- ☐ Coolant

SCRATCHES

- ☐ No Scratches
- ☐ W/ Scratches
- *Encircle parts that has/have scratches

COLOR

- ☐ Evenly Painted
- ☐ Not Evenly Painted

BATTERY/ HORN

- ☒ Battery
- Brand : _____ Battery Voltage : _____
- ☒ Horn

TIRES

- ☒ Good Quality
- ☐ Bad Quality
- Brand : _____
- Tire Pressure : _____ Front _____ Rear _____

PADS DIAGNOSTIC TOOL

- ☐ PADS Checkup
- Fault : _____
- Remarks : _____

SADDLE

- ☒ Good Quality
- ☐ Bad Quality
- KEYS/ MANUAL/ TOOLS**
- ☐ Master Key
- ☐ Duplicate Key
- ☐ Service Manual
- ☐ Warranty Booklet
- ☐ Set of Screw
- ☐ Battery Holder
- ☐ Plate Holder
- ☐ reflectors (Optional)
- ☐ Under Body Caps (Optional)
- ☐ 1 Set of Tools
- ☐ Rear Shock Adjuster
- ☐ Screw Driver
- ☐ Fuse Removal Tool
- ☐ Screw driver (FLOWER KEY)
- ☐ Sparkplug Wrench

Remarks :

Complete Accessories & Tools w/ Battery

I understand all the above items as explained to me by the releasing Officer/ Manager. I also agree that any failure on my part to adhere to any of the instructions given that may result in damages on the above mentioned parts will not be covered by warranty.

Inspected by :

Technician/PDI Personnel

Approved by :

Service Manager

Approved by :

Sales Department

CHECKLIST

10889

PAGE 2

Client :

Vespa

Chassis # :

NV039110

Color:

Orange

Make/Model :


S125

Make/Model
Engine # :

5103682

Date :

10-10-22



LEGEND

S- Scratched

L- Loose

D- Dented

M- Missing

DD-Damaged

F- Faded

Remarks:



AUTOHUB CAR CARE SERVICES (ACCS)

BY: SUPREME AUTOZONE PHILIPPINES INC.

Sitio Buroi Cabrera Road, Brgy. San Juan, Taytay, Rizal

Tel. No.: (632) 533-6398

VAT REG. TIN: 236-978-189-00006

BILLING STATEMENT

No: **06795**

Service Invoice		Page 1 of 1		Doc # : ATCJ E24009	
CUSTOMER No. 211806	CUSTOMER NAME AND ADDRESS TIN: MOTORITALIA PHILS. INC. #234 ORTIGAS AVENUE NORTH GREENHILLS SAN JUAN CITY MMN 000			ADVISOR Aldrin Padilla 480	COLOR GREY/
DOC. DATE 27/02/23	REG. No. UNREG			YEAR/MAKE/MODEL 22/NEXTHUB/VESPA S125	TEAM NH GENER
STOCK No.	PURCHASE ORDER No.			MODEL No. S125	TAG No.
DRIVER			CONTACT No.	CAR LINE VESPA	ENG./TRANS.
HOME PHONE			CONTACT NAME	KILOMETERS	PROD. DATE
BUSINESS PHONE			SELLING DEALER	CONTRACT EXP. KMS	EXP. DATE
TERMS Charge			DELIVERY KMS	DELIVERY DATE	
CA <input type="checkbox"/>	F/C <input type="checkbox"/>	CH <input type="checkbox"/>	VEHICLE ID RPBM66701NV03900	ENGINE No. MC6BMS102613	DATE AND TIME PROMISED 25/02/23 09:00pm
O/C <input type="checkbox"/>	WAR <input type="checkbox"/>	INT <input type="checkbox"/>	TIME RECEIVED 10:21am		QUOTE PRICE AIR PWR TURBO

Labour
J# 1 76NAZZZZZ002

- * PDI CLEAN
- * PDI INSPECTION
- * BRAND NEW UNIT
- * CHECKED AND EVALUATED CONCERN:
PERFORMED PDI INSPECTION

Tech(s) : 48048

3125.00

Total - Labour 3125.00

Totals=====

Total Labour.	3125.00
Total Parts..	0.00
Total Other..	0.00
Total P.O.L..	0.00
Total Misc...	0.00
VAT	375.00
Total Invoice	3500.00

[Signature]
12/23/23

[End of Invoice]

ROAD TESTED		ACKNOWLEDGMENT	
ORDER NO	SUBLET REPAIRS	RECEIVED above vehicle from AUTOHUB CAR CARE SERVICES (ACCS) in good condition and with all repair work enumerated completed to my satisfaction.	
		All works carried out at these premises are subject to a warranty of _____ days or _____ whichever comes first on all labor and materials.	
		SIGNATURE OF OWNER _____	
		I AGREE TO PAY for all works required for all the above described repair at your retail charge. It is understood that any estimate given is provisional and all repairs are undertaken on a cash basis unless prior arrangements for credit have been approved.	
		I have READ AND ACCEPTED your terms and conditions	

CHECKLIST

10890

PAGE 1

REGISTRATION

Client : Vespa

Chassis # : MVO39061

Color: Grey

Make/Model : S125

Engine # : 5102613

Date : 10-10-22

EMBLEMS

- ☒ Piaggio Emblem (Front)
- ☒ PVG Emblem (Crankcase)

SIDE MIRROR

- ☒ LH Side View Mirror
- ☒ RH Side View Mirror

ELECTRICAL BUTTONS

- ☒ Start Button
- ☒ Horn Button
- ☒ High&Low Button
- ☒ Passing Button (Optional)
- ☒ Left Signal Button
- ☒ Right Signal Button
- ☒ Cut Off Engine Button (Optional)
- ☒ Start & Stop Button
- ☒ ASR Button
- ☒ Mode
- ☒ Saddle Button
- ☒ Toggle Switch

LIGHTS

- ☒ Park Light
- ☒ High & Low Beam
- ☒ Front Right Signal
- ☒ Rear Right Signal
- ☒ Front Left Signal
- ☒ Rear Left Signal
- ☒ Backlight
- ☒ Brakelights
- ☒ Instrumental Panel Gauges
- ☒ Plate Light

FLUID LEVELS

- ☒ Engine Oil
- ☒ Gear Oil
- ☒ Brake Fluid
- ☒ Coolant

SCRATCHES

- ☒ No Scratches
- ☒ W/ Scratches
- *Encircle parts that has/have scratches

COLOR

- ☒ Evenly Painted
- ☒ Not Evenly Painted

BATTERY/ HORN

- ☒ Battery
- Brand: _____ Battery Voltage: _____
- ☒ Horn

TIRES

- ☒ Good Quality
- ☒ Bad Quality
- Brand: _____
- Tire Pressure: _____ Front _____ Rear _____

PADS DIAGNOSTIC TOOL

- ☒ PADS Checkup
- Fault : _____
- Remarks: _____

SADDLE

- ☒ Good Quality
- ☒ Bad Quality
- KEYS/ MANUAL/ TOOLS
- ☒ Master Key
- ☒ Duplicate Key
- ☒ Service Manual
- ☒ Warranty Booklet
- ☒ Set of Screw
- ☒ Battery Holder
- ☒ Plate Holder
- ☒ reflectors (Optional)
- ☒ Under Body Caps (Optional)
- ☒ 1 Set of Tools
- ☒ Rear Shock Adjuster
- ☒ Screw Driver
- ☒ Fuse Removal Tool
- ☒ Screw driver (FLOWER KEY)
- ☒ Sparkplug Wrench

Remarks :

Complete Accessories & Tools w/ battery

I understand all the above items as explained to me by the releasing Officer/ Manager. I also agree that any failure on my part to adhere to any of the instructions given that may result in damages on the above mentioned parts will not be covered by warranty.


Inspected by : [Signature]
Technician/PDI Personnel

Approved by : _____
Service Manager

Approved by : _____
Sales Department

CHECKLIST

Client: Vespa Chassis #: 10890 Color: Grey PAGE 2
 Make/Model: 3125 Engine #: 5102613 Date: 10-10-21



LEGEND

S- Scratched L- Loose
 D- Dented M- Missing
 DD-Damaged F- Faded

Remarks:



AUTOHUB CAR CARE SERVICES (ACCS)

BY: SUPREME AUTOZONE PHILIPPINES INC.

Sitio Burol Cabrera Road, Brgy San Juan, Taytay, Rizal

Tel. No. (632) 533-6398

VAT REG. TIN 236-978-189-00006

BILLING STATEMENT

No: **06796**

Service Invoice

Page 1 of 1

Doc # : ATCJ E24011

CUSTOMER No. 271306	CUSTOMER NAME AND ADDRESS TIN: HOSPITALIA PHILS. INC. #234 ORTIGAS AVENUE NORTH GREENHILLS SAN JUAN CITY MMN 000	ADVISOR Aldrin Padilla	COLOR 48004 GREY/	TEAM RM GENER
DOC. DATE 27/02/23		YEAR/MAKE/MODEL 22/NEXTHUB/VESPA S125		TAG No.
REG. No. UNREG		MODEL No. S125	CAR LINE VESPA	ENG./TRANS.
STOCK No.		CHASSIS No.	KILOMETERS	PROD. DATE
PURCHASE ORDER No.	DRIVER	CONTACT No.	CONTACT NAME	CONTRACT EXP. KMS
CA <input type="checkbox"/>	F/C <input type="checkbox"/>	CH <input type="checkbox"/>	HOME PHONE	BUSINESS PHONE
C/C <input type="checkbox"/>	WAR <input type="checkbox"/>	INT <input type="checkbox"/>	TERMS Charge	SELLING DEALER
	VEHICLE ID RP8M66701NV039064	ENGINE No. M66BM5102621	DATE AND TIME PROMISED 25/02/23 09:00pm	TIME RECEIVED 10:21am
			QUOTE PRICE	AIR PWR TURBO

Labour J# 1 76NAZZZZ002	PDI CLEAN * PDI INSPECTION * BRAND NEW UNIT * CHECKED AND EVALUATED CONCERN: PERFORMED PDI INSPECTION	Tech(s) : 48048	3125.00
Total - Labour			3125.00
Totals=====			
Total Labour.			3125.00
Total Parts..			0.00
Total Other..			0.00
Total P.O.L..			0.00
Total Misc...			0.00
VAT			375.00
Total Invoice			3500.00

RAP
02/27/23

[End of Invoice]

ACKNOWLEDGMENT

RECEIVED above vehicle from AUTOHUB CAR CARE SERVICES (ACCS) in good condition and with all repair work enumerated completed to my satisfaction.

All works carried out at these premises are subject to a warranty of _____ days or _____ whichever comes first on all labor and materials

SIGNATURE OF OWNER _____

I AGREE TO PAY for all works required for all the above described repair at your retail charge. It is understood that any estimate given is provisional and all repairs are undertaken on a cash basis unless prior arrangements for credit have been approved.

I have READ AND ACCEPTED your terms and conditions.

ROAD TESTED

ORDER NO. SUBLET REPAIRS

CHECKLIST

10892

PAGE 1

Client :

Chassis # :

Color :

Make/Model :

Engine # :

Date :

EMBLEMS

- () Piaggio Emblem (Front)
() PVG Emblem (Crankcase)

SIDE MIRROR

- () LH Side View Mirror
() RH Side View Mirror

ELECTRICAL BUTTONS

- () Start Button
() Horn Button
() High&Low Button
() Passing Button (Optional)
() Left Signal Button
() Right Signal Button
() Cut Off Engine Button (Optional)
() Start & Stop Button
() ASR Button
() Mode
() Saddle Button
() Toggle Switch

LIGHTS

- () Park Light
() High & Low Beam
() Front Right Signal
() Rear Right Signal
() Front Left Signal
() Rear Left Signal
() Backlight
() Brakelights
() Instrumental Panel Gauges
() Plate Light

FLUID LEVELS

- () Engine Oil
() Gear Oil
() Brake Fluid
() Coolant

SCRATCHES

- () No Scratches
() W/ Scratches
*Encircle parts that has/have scratches

COLOR

- () Evenly Painted
() Not Evenly Painted

BATTERY/ HORN

- () Battery
Brand: Dugnini Battery Voltage: _____
() Horn

TIRES

- () Good Quality
() Bad Quality
Brand: _____
Tire Pressure: _____ Front _____ Rear _____

PADS DIAGNOSTIC TOOL

- () PADS Checkup
Fault : _____
Remarks: _____

SADDLE

- () Good Quality
() Bad Quality
KEYS/ MANUAL/ TOOLS
() Master Key
() Duplicate Key
() Service Manual
() Warranty Booklet
() Set of Screw
() Battery Holder
() Plate Holder
() reflectors (Optional)
() Under Body Caps (Optional)
() 1 Set of Tools
() Rear Shock Adjuster
() Screw Driver
() Fuse Removal Tool
() Screw driver (FLOWER KEY)
() Sparkplug Wrench

Remarks :

Complete tools
Battery
Chassis

I understand all the above items as explained to me by the releasing Officer/ Manager. I also agree that any failure on my part to adhere to any of the instructions given that may result in damages on the above mentioned parts will not be covered by warranty.

Inspected by :

Approved by :

Approved by :

Technician/PDI Personnel

Service Manager

Sales Department

CHECKLIST

RESEMBLING

10892

PAGE 2

Client :


Chassis # : 039014

Color: Grey

Make/Model : S125

Engine # : 5107621

Date : at town



LEGEND

S- Scratched	L- Loose
D- Dented	M- Missing
DD-Damaged	F- Faded

Remarks:

Complete

tools
battery
Accessories

CHECKLIST

10885

PAGE 1

Client :

Vespa

Chassis # :

N-1039141

Color :

Red

Make/Model :

S125

Engine # :

5103693

Date :

10-10-22

EMBLEMS

- ☐ Piaggio Emblem (Front)
- ☐ PVG Emblem (Crankcase)

SIDE MIRROR

- ☐ LH Side View Mirror
- ☐ RH Side View Mirror

ELECTRICAL BUTTONS

- ☐ Start Button
- ☐ Horn Button
- ☐ High&Low Button
- ☐ Passing Button (Optional)
- ☐ Left Signal Button
- ☐ Right Signal Button
- ☐ Cut Off Engine Button (Optional)
- ☐ Start & Stop Button
- ☐ ASR Button
- ☐ Mode
- ☐ Saddle Button
- ☐ Toggle Switch

LIGHTS

- ☐ Park Light
- ☐ High & Low Beam
- ☐ Front Right Signal
- ☐ Rear Right Signal
- ☐ Front Left Signal
- ☐ Rear Left Signal
- ☐ Backlight
- ☐ Brakelights
- ☐ Instrumental Panel Gauges
- ☐ Plate Light

FLUID LEVELS

- ☐ Engine Oil
- ☐ Gear Oil
- ☐ Brake Fluid
- ☐ Coolant

SCRATCHES

- ☐ No Scratches
- ☐ W/ Scratches
- *Encircle parts that has/have scratches

COLOR

- ☐ Evenly Painted
- ☐ Not Evenly Painted

BATTERY/ HORN

- ☐ Battery
- Brand: _____ Battery Voltage: _____
- ☐ Horn

TIRES

- ☐ Good Quality
- ☐ Bad Quality
- Brand: _____
- Tire Pressure: _____ Front _____ Rear _____

PADS DIAGNOSTIC TOOL

- ☐ PADS Checkup

Fault : _____

Remarks: _____

SADDLE

- ☐ Good Quality
- ☐ Bad Quality
- KEYS/ MANUAL/ TOOLS
- ☐ Master Key
- ☐ Duplicate Key
- ☐ Service Manual
- ☐ Warranty Booklet
- ☐ Set of Screw
- ☐ Battery Holder
- ☐ Plate Holder
- ☐ reflectors (Optional)
- ☐ Under Body Caps (Optional)
- ☐ 1 Set of Tools
- ☐ Rear Shock Adjuster
- ☐ Screw Driver
- ☐ Fuse Removal Tool
- ☐ Screw driver (FLOWER KEY)
- ☐ Sparkplug Wrench

Remarks :

Complete Accessories Starts w/ battery

I understand all the above items as explained to me by the releasing Officer/ Manager. I also agree that any failure on my part to adhere to any of the instructions given that may result in damages on the above mentioned parts will not be covered by warranty.

Inspected by :

Technician/PDI Personnel

Approved by :

Service Manager

Approved by :

Sales Department

CHECKLIST

Client :

Vespa

Chassis # :

RP6m6c901

NV039141

Color:

10885

Red

PAGE 2

Make/Model :


S125

Engine # :

5103693

Date :

10-10-22



LEGEND

S- Scratched

D- Dented

DD-Damaged

L- Loose

M- Missing

F- Faded

Remarks:



AUTOHUB CAR CARE SERVICES (ACCS)

BY: SUPREME AUTOZONE PHILIPPINES INC.

Silio Buroi Cabrera Road, Brgy. San Juan, Taytay, Rizal

Tel No (632) 533-6398

VAT REG. TIN 236-978-189-00006

BILLING STATEMENT

No: 06798

Service Invoice		Page 1 of 1		Doc # : ATCJ E24013	
CUSTOMER No. 211806	CUSTOMER NAME AND ADDRESS TIN: AUTOTALIA PHILS. INC. #234 ORTIGAS AVENUE NORTH GREENHILLS SAN JUAN CITY MMN 000			ADVISOR Hidrin Padilla	COLOR 48024 GREY/
DOC. DATE 27/02/23				YEAR/MAKE/MODEL 22/NEXTHUB/VESPA S125	TEAM NH GENER
REG. No. UNREG				MODEL No. S125	TAG No.
STOCK No.				CAR LINE VESPA	ENG./TRANS.
PURCHASE ORDER No.	DRIVER	CONTACT No.	CONTACT NAME	CHASSIS No.	PROD. DATE
CA <input type="checkbox"/>	P/C <input type="checkbox"/>	CH <input type="checkbox"/>	HOME PHONE	BUSINESS PHONE	TERMS
C/C <input type="checkbox"/>	WAR <input type="checkbox"/>	INT <input type="checkbox"/>	VEHICLE ID RP8M66701NV039057	ENGINE No. M66BM5102608	Charge
			DATE AND TIME PROMISED 25/02/23 09:00pm	TIME RECEIVED 10:23am	QUOTE PRICE
			AIR PWR TURBO		

Labour
JW 1 7ENAZZZZZ002

* PDI CLEAN
* PDI INSPECTION
* BRAND NEW UNIT
* CHECKED AND EVALUATED CONCERN:
* PERFORMED PDI INSPECTION

Tech(s) : 48048

3125.00

Totals:===== Total - Labour 3125.00

Total Labour. 3125.00
Total Parts.. 0.00
Total Other.. 0.00
Total P.O.L.. 0.00
Total Misc... 0.00
VAT 375.00

Total Invoice 3500.00

2422
02/27/23

ROAD TESTED

ORDER NO.	SUBLET REPAIRS

ACKNOWLEDGMENT

RECEIVED above vehicle from AUTOHUB CAR CARE SERVICES (ACCS) in good condition and with all repair work enumerated completed to my satisfaction.

All works carried out at these premises are subject to a warranty of _____ days or _____ whichever comes first on all labor and materials.

SIGNATURE OF OWNER _____

I AGREE TO PAY for all works required for all the above described repair at your retail charge. It is understood that any estimate given is provisional and all repairs are undertaken on a cash basis unless prior arrangements for credit have been approved.

I have READ AND ACCEPTED your terms and conditions.

CHECKLIST

10896

PAGE 1

Client :

Chassis # :

Color :

Make/Model :

Engine # :

Date :

EMBLEMS

- () Piaggio Emblem (Front)
() PVG Emblem (Crankcase)

SIDE MIRROR

- () LH Side View Mirror
() RH Side View Mirror

ELECTRICAL BUTTONS

- () Start Button
() Horn Button
() High&Low Button
() Passing Button (Optional)
() Left Signal Button
() Right Signal Button
() Cut Off Engine Button (Optional)
() Start & Stop Button
() ASR Button
() Mode
() Saddle Button
() Toggle Switch

LIGHTS

- () Park Light
() High & Low Beam
() Front Right Signal
() Rear Right Signal
() Front Left Signal
() Rear Left Signal
() Backlight
() Brakelights
() Instrumental Panel Gauges
() Plate Light

FLUID LEVELS

- () Engine Oil
() Gear Oil
() Brake Fluid
() Coolant

SCRATCHES

- () No Scratches
() W/ Scratches
*Encircle parts that has/have scratches

COLOR

- () Evenly Painted
() Not Evenly Painted

BATTERY/ HORN

- () Battery
Brand: Bosch Battery Voltage: 12V
() Horn

TIRES

- () Good Quality
() Bad Quality

Brand: Pirelli
Tire Pressure: Front 30 Rear 30

PADS DIAGNOSTIC TOOL

- () PADS Checkup
Fault : None

Remarks :

SADDLE

- () Good Quality
() Bad Quality

KEYS/ MANUAL/ TOOLS

- () Master Key
() Duplicate Key
() Service Manual
() Warranty Booklet
() Set of Screw
() Battery Holder
() Plate Holder
() reflectors (Optional)
() Under Body Caps (Optional)
() 1 Set of Tools
() Rear Shock Adjuster
() Screw Driver
() Fuse Removal Tool
() Screw driver (FLOWER KEY)
() Sparkplug Wrench

Remarks :

I understand all the above items as explained to me by the releasing Officer/ Manager. I also agree that any failure on my part to adhere to any of the instructions given that may result in damages on the above mentioned parts will not be covered by warranty.

Inspected by :

Approved by :

Approved by :

Technician/PDI Personnel

Service Manager

Sales Department

CHECKLIST

Client :

Chassis # :

10896
689057

Color:

Grey

PAGE 2

Make/Model :


S125

Engine # :

5102608

Date :

10-10-72



LEGEND

S- Scratched
D- Dented
DD-Damaged

L- Loose
M- Missing
F- Faded

Remarks:

Complete fuels
Battery
accessories

CHECKLIST

10897

PAGE 1

Client :

Chassis # :

Color :

Make/Model :

Engine # :

Date :

EMBLEMS

- () Piaggio Emblem (Front)
() PVG Emblem (Crankcase)

SIDE MIRROR

- () LH Side View Mirror
() RH Side View Mirror

ELECTRICAL BUTTONS

- () Start Button
() Horn Button
() High&Low Button
() Passing Button (Optional)
() Left Signal Button
() Right Signal Button
() Cut Off Engine Button (Optional)
() Start & Stop Button
() ASR Button
() Mode
() Saddle Button
() Toggle Switch

LIGHTS

- () Park Light
() High & Low Beam
() Front Right Signal
() Rear Right Signal
() Front Left Signal
() Rear Left Signal
() Backlight
() Brakelights
() Instrumental Panel Gauges
() Plate Light

FLUID LEVELS

- () Engine Oil
() Gear Oil
() Brake Fluid
() Coolant

SCRATCHES

- () No Scratches
() W/ Scratches
*Encircle parts that has/have scratches

COLOR

- () Evenly Painted
() Not Evenly Painted

BATTERY/ HORN

- () Battery
Brand: D. 1910 Battery Voltage: _____
() Horn

TIRES

- () Good Quality
() Bad Quality
Brand: _____
Tire Pressure: Front _____ Rear _____

PADS DIAGNOSTIC TOOL

- () PADS Checkup
Fault : _____
Remarks: _____

SADDLE

- () Good Quality
() Bad Quality
KEYS/ MANUAL/ TOOLS
() Master Key
() Duplicate Key
() Service Manual
() Warranty Booklet
() Set of Screw
() Battery Holder
() Plate Holder
() reflectors (Optional)
() Under Body Caps (Optional)
() 1 Set of Tools
() Rear Shock Adjuster
() Screw Driver
() Fuse Removal Tool
() Screw driver (FLOWER KEY)
() Sparkplug Wrench

Remarks :

I understand all the above items as explained to me by the releasing Officer/ Manager. I also agree that any failure on my part to adhere to any of the instructions given that may result in damages on the above mentioned parts will not be covered by warranty.

Inspected by :

Approved by :

Approved by :

Technician/PDI Personnel

Service Manager

Sales Department

CHECKLIST

Client: _____

Chassis #: 39038

Color: Grey


10897

PAGE 2

Make/Model: S125

Engine #: 5101778

Date: 10-10-2008



LEGEND

S- Scratched

L- Loose

D- Dented

M- Missing

DD-Damaged

F- Faded

Remarks:

Complete faded

THIS DECLARATION STATEMENT SHALL BE VALID FOR FIVE (5) YEARS FROM THE DATE OF ATP.
THIS DOCUMENT IS NOT VALID FOR CLAIMING INPUT TAXES



AUTOHUB CAR CARE SERVICES (ACCS)

BY: SUPREME AUTOZONE PHILIPPINES INC.

Sitio Buroi Cabrera Road, Brgy. San Juan, Taytay, Rizal

Tel. No.: (632) 533-6398

VAT REG. TIN: 236-978-189-00006

BILLING STATEMENT

No: **06800**

Service Invoice		Page 1 of 1		Doc # : ATCJ E24016	
CUSTOMER No. 211806	CUSTOMER NAME AND ADDRESS MOTOITALIA PHILS. INC.			ADVISOR Aldrin Padilla	COLOR 48054 GREY/
DOC. DATE 27/02/23	REG. No. UNREG			YEAR/MAKE/MODEL 22/NEXTHUB/VESPA 3125	TEAM NH GENER
STOCK No.	PURCHASE ORDER No.			MODEL No. 3125	TAG No.
DRIVER			CONTACT No.	CHASSIS No.	ENG./TRANS.
HOME PHONE			BUSINESS PHONE	CONTACT NAME	KILOMETERS
VEHICLE ID RP8M66701NV039034			ENGINE No. M66BM5102625	CONTRACT EXP. KMS	PROD. DATE
CA <input type="checkbox"/> F/C <input type="checkbox"/> CH <input type="checkbox"/>			TERMS Charge	SELLING DEALER	EXP. DATE
C/C <input type="checkbox"/> WAR <input type="checkbox"/> INT <input type="checkbox"/>			DATE AND TIME PROMISED 25/02/23 09:00pm	DELIVERY KMS	DELIVERY DATE
			TIME RECEIVED 10:23am	QUOTE PRICE	AIR <input type="checkbox"/> PWR <input type="checkbox"/> TURBO <input type="checkbox"/>

Labour
J# 1 76NAZZZZZ002

* PDI CLEAN
* PDI INSPECTION
* BRAND NEW UNIT
* CHECKED AND EVALUATED CONCERN:
* PERFORMED MAINTENANCE SERVICE

Tech(s) : 48048

3125.00

Totals=====

Total - Labour 3125.00

Total Labour. 3125.00
Total Parts.. 0.00
Total Other.. 0.00
Total P.O.L.. 0.00
Total Misc... 0.00
VAT 375.00

Total Invoice 3500.00

RJR
02/23/23

[End of Invoice]

ROAD TESTED		ACKNOWLEDGMENT	
ORDER NO.	SUBLET REPAIRS	RECEIVED above vehicle from AUTOHUB CAR CARE SERVICES (ACCS) in good condition and with all repair work enumerated completed to my satisfaction.	I AGREE TO PAY for all works required for all the above described repair at your retail charge. It is understood that any estimate given is provisional and all repairs are undertaken on a cash basis unless prior arrangements for credit have been approved.
		All works carried out at these premises are subject to a warranty of _____ days or _____ whichever comes first on all labor and materials.	I have READ AND ACCEPTED your terms and conditions.
		SIGNATURE OF OWNER _____	

CHECKLIST

10900

PAGE 1

Client :

Chassis # :

Color :

Make/Model :

Engine # :

Date :

EMBLEMS

- ☒ Piaggio Emblem (Front)
- ☒ PVG Emblem (Crankcase)

SIDE MIRROR

- ☒ LH Side View Mirror
- ☒ RH Side View Mirror

ELECTRICAL BUTTONS

- ☒ Start Button
- ☒ Horn Button
- ☒ High&Low Button
- ☒ Passing Button (Optional)
- ☒ Left Signal Button
- ☒ Right Signal Button
- ☒ Cut Off Engine Button (Optional)
- ☒ Start & Stop Button
- ☒ ASR Button
- ☒ Mode
- ☒ Saddle Button
- ☒ Toggle Switch

LIGHTS

- ☒ Park Light
- ☒ High & Low Beam
- ☒ Front Right Signal
- ☒ Rear Right Signal
- ☒ Front Left Signal
- ☒ Rear Left Signal
- ☒ Backlight
- ☒ Brakelights
- ☒ Instrumental Panel Gauges
- ☒ Plate Light

FLUID LEVELS

- ☒ Engine Oil
- ☒ Gear Oil
- ☒ Brake Fluid
- ☒ Coolant

SCRATCHES

- ☒ No Scratches
- ☒ W/ Scratches
- ☒ *Encircle parts that has/have scratches

COLOR

- ☒ Evenly Painted
- ☒ Not Evenly Painted

BATTERY/ HORN

- ☒ Battery - Brand: PRG-PS Battery Voltage: 12V-60Ah(101R)
- ☒ Horn

TIRES

- ☒ Good Quality
- ☒ Bad Quality
- ☒ Brand: _____
- ☒ Tire Pressure: _____ Front _____ Rear _____

PADS DIAGNOSTIC TOOL

- ☒ PADS Checkup
- ☒ Fault : _____
- ☒ Remarks: _____

SADDLE

- ☒ Good Quality
- ☒ Bad Quality
- ☒ KEYS/ MANUAL/ TOOLS
- ☒ Master Key
- ☒ Duplicate Key
- ☒ Service Manual
- ☒ Warranty Booklet
- ☒ Set of Screw
- ☒ Battery Holder
- ☒ Plate Holder
- ☒ reflectors (Optional)
- ☒ Under Body Caps (Optional)
- ☒ 1 Set of Tools
- ☒ Rear Shock Adjuster
- ☒ Screw Driver
- ☒ Fuse Removal Tool
- ☒ Screw driver (FLOWER KEY)
- ☒ Sparkplug Wrench

Remarks :

I understand all the above items as explained to me by the releasing Officer/ Manager. I also agree that any failure on my part to adhere to any of the instructions given that may result in damages on the above mentioned parts will not be covered by warranty.

Inspected by :

Approved by :

Approved by :

Technician/PDI Personnel

Service Manager

Sales Department

CHECKLIST

RP8MB6701 NY

10900

PAGE 2

Client :


Chassis # :

Color:

Make/Model :

Engine # :

Date :



LEGEND

S- Scratched
D- Dented
DD-Damaged

L- Loose
M- Missing
F- Faded

Remarks:



AUTOHUB CAR CARE SERVICES (ACCS)

BY: SUPREME AUTOZONE PHILIPPINES INC.
Sitio Buroi Cabrera Road, Brgy. San Juan, Taytay, Rizal
Tel. No.: (632) 533-6398
VAT REG. TIN: 236-978-189-00006

BILLING STATEMENT

No: 06801

Service Invoice		Page 1 of 1		Doc # : ATCJ E24017	
CUSTOMER No. 211806	CUSTOMER NAME AND ADDRESS TIN: MOTOITALIA PHILS. INC.		ADVISOR Aldrin Padilla	COLOR 4804 WHITE/	TEAM NA GENER
DOC. DATE 27/02/23	#234 ORTIGAS AVENUE		YEAR/MAKE/MODEL 22/NEXTHUB/VESPA S125	TAG No.	
REG. No. UNREG	NORTH GREENHILLS		MODEL No. S125	CAR LINE VESPA	ENG./TRANS.
STOCK No.	SAN JUAN CITY MMN 000		CHASSIS No.	KILOMETERS	PROD. DATE
PURCHASE ORDER No.	DRIVER	CONTACT No.	CONTACT NAME	CONTRACT EXP KMS	EXR DATE
CA <input type="checkbox"/>	F/C <input type="checkbox"/>	CH <input type="checkbox"/>	HOME PHONE	BUSINESS PHONE	TERMS
O/C <input type="checkbox"/>	WAR <input type="checkbox"/>	INT <input type="checkbox"/>	VEHICLE ID	ENGINE No.	Charge
RP8M66701NV039181			M66BM5103671		
DATE AND TIME PROMISED 25/02/23 09:00pm			TIME RECEIVED 10:24am		
QUOTE PRICE			AIR	PWR	TURBO

Labour
J# 1 76NAZZZZZ002

PDI CLEAN
* PDI INSPECTION
* BRAND NEW UNIT
* CHECKED AND REEVALUATED CONCERN:
PERFORMED PDI INSPECTION

Tech(s) : 4804B

3125.00

Totals=====

Total - Labour 3125.00

Total Labour. 3125.00
Total Parts.. 0.00
Total Other.. 0.00
Total P.O.L.. 0.00
Total Misc... 0.00
VAT 375.00

Total Invoice 3500.00

[Signature]
02/27/23

[End of Invoice]

ROAD TESTED		ACKNOWLEDGMENT	
ORDER NO.	SUBLET REPAIRS	RECEIVED above vehicle from AUTOHUB CAR CARE SERVICES (ACCS) in good condition and with all repair work enumerated completed to my satisfaction.	
		All works carried out at these premises are subject to a warranty of _____ days or _____ whichever comes first on all labor and materials.	
		SIGNATURE OF OWNER _____	
		I AGREE TO PAY for all works required for all the above described repair at your retail charge. It is understood that any estimate given is provisional and all repairs are undertaken on a cash basis unless prior arrangements for credit have been approved.	
		I have READ AND ACCEPTED your terms and conditions.	

CHECKLIST

10901

PAGE 1

Client :

Chassis # :

Color:

Make/Model :

Engine # :

Date :

EMBLEMS

- () Piaggio Emblem (Front)
() PVG Emblem (Crankcase)

SIDE MIRROR

- () LH Side View Mirror
() RH Side View Mirror

ELECTRICAL BUTTONS

- () Start Button
() Horn Button
() High&Low Button
() Passing Button (Optional)
() Left Signal Button
() Right Signal Button
() Cut Off Engine Button (Optional)
() Start & Stop Button
() ASR Button
() Mode
() Saddle Button
() Toggle Switch

LIGHTS

- () Park Light
() High & Low Beam
() Front Right Signal
() Rear Right Signal
() Front Left Signal
() Rear Left Signal
() Backlight
() Brakelights
() Instrumental Panel Gauges
() Plate Light

FLUID LEVELS

- () Engine Oil
() Gear Oil
() Brake Fluid
() Coolant

SCRATCHES

- () No Scratches
() W/ Scratches

*Encircle parts that has/have scratches

COLOR

- () Evenly Painted
() Not Evenly Painted

BATTERY/ HORN

Battery

Brand: Battery Voltage:

Horn

TIRES

- () Good Quality
() Bad Quality

Brand: Tire Pressure: Front Rear

PADS DIAGNOSTIC TOOL

PADS Checkup

Fault :

Remarks:

SADDLE

- () Good Quality
() Bad Quality

KEYS/ MANUAL/ TOOLS

- () Master Key
() Duplicate Key
() Service Manual
() Warranty Booklet
() Set of Screw
() Battery Holder
() Plate Holder
() reflectors (Optional)
() Under Body Caps (Optional)
() 1 Set of Tools
() Rear Shock Adjuster
() Screw Driver
() Fuse Removal Tool
() Screw driver (FLOWER KEY)
() Sparkplug Wrench

Remarks :

I understand all the above items as explained to me by the releasing Officer/ Manager. I also agree that any failure on my part to adhere to any of the instructions given that may result in damages on the above mentioned parts will not be covered by warranty.

Inspected by :

Approved by :

Approved by :

Technician/PDI Personnel

Service Manager

Sales Department

RPBMEC 101 NV

10901

PAGE 2

Client :

Chassis #: 39101

Color: 70 W, 30

Make/Model :

malcolm

Engine # : 5703671

Date : 10/10/2024



S- Scratched

L- Loose

D- Dented

M- Missing

DD-Damaged

F- Faded

Remarks:

This image shows a single sheet of white paper with horizontal blue or grey ruling lines. The lines are evenly spaced and run across the width of the page. There is no handwriting or other markings on the paper.

CHECKLIST

10918

PAGE 1

Client :

VESPA

Chassis # :

039KKH

Color:

RED

Make/Model :

S175

Engine # :

5103698

Date :

10-12-22

EMBLEMS

- () Piaggio Emblem (Front)
- () PVG Emblem (Crankcase)

SIDE MIRROR

- () LH Side View Mirror
- () RH Side View Mirror

ELECTRICAL BUTTONS

- () Start Button
- () Horn Button
- () High&Low Button
- () Passing Button (Optional)
- () Left Signal Button
- () Right Signal Button
- () Cut Off Engine Button (Optional)
- () Start & Stop Button
- () ASR Button
- () Mode
- () Saddle Button
- () Toggle Switch

LIGHTS

- () Park Light
- () High & Low Beam
- () Front Right Signal
- () Rear Right Signal
- () Front Left Signal
- () Rear Left Signal
- () Backlight
- () Brakelights
- () Instrumental Panel Gauges
- () Plate Light

FLUID LEVELS

- () Engine Oil
- () Gear Oil
- () Brake Fluid
- () Coolant

SCRATCHES

- () No Scratches
- () W/ Scratches
- *Encircle parts that has/have scratches

COLOR

- () Evenly Painted
- () Not Evenly Painted

BATTERY/ HORN

- () Battery
- Brand: DONGNAI Battery Voltage: 12V
- () Horn

TIRES

- () Good Quality
- () Bad Quality
- Brand: MAXXIS
- Tire Pressure: Front _____ Rear _____

PADS DIAGNOSTIC TOOL

- () PADS Checkup
- Fault : _____
- Remarks: _____

SADDLE

- () Good Quality
- () Bad Quality

KEYS/ MANUAL/ TOOLS

- () Master Key
- () Duplicate Key
- () Service Manual
- () Warranty Booklet
- () Set of Screw
- () Battery Holder
- () Plate Holder
- () reflectors (Optional)
- () Under Body Caps (Optional)
- () 1 Set of Tools
- () Rear Shock Adjuster
- () Screw Driver
- () Fuse Removal Tool
- () Screw driver (FLOWER KEY)
- () Sparkplug Wrench

Remarks :

COMPLETE ACCESSORIES W/ BATTERY

I understand all the above items as explained to me by the releasing Officer/ Manager. I also agree that any failure on my part to adhere to any of the instructions given that may result in damages on the above mentioned parts will not be covered by warranty.

Inspected by :

D. TALAMANCA

Technician/PDI Personnel

Approved by :

Service Manager

Approved by :

Sales Department

CHECKLIST

Client :

VESPA

Chassis # :

039144

Color:

RED

PAGE 2

Make/Model :


S125

Engine # :

5103698

Date :

10-12-27



LEGEND

S- Scratched	L- Loose
D- Dented	M- Missing
DD-Damaged	F- Faded

Remarks:

D. TALAMISAN



AUTOHUB CAR CARE SERVICES (ACCS)

BY: SUPREME AUTOZONE PHILIPPINES INC.

Sitio Buroi Cabrera Road, Brgy. San Juan, Taytay, Rizal

Tel. No.: (632) 533-6398

VAT REG. TIN: 236-978-189-00006

BILLING STATEMENT

No: 06803

Service Invoice		Page 1 of 1		Doc # : ATCJ E24019	
CUSTOMER No. 211806	CUSTOMER NAME AND ADDRESS TIN: MOTOITALIA PHILS. INC.		ADVISOR Aldrin Padilla	COLOR 48054 WHITE/	TEAM NH GENER
DOC. DATE 27/02/23	#234 ORTIGAS AVENUE		YEAR/MAKE/MODEL 22/NEXTHUB/VESPA S125	TAG No.	
REG. No. UNREG	NORTH GREENHILLS		MODEL No. S125	CAR LINE VESPA	ENG./TRANS.
STOCK No.	SAN JUAN CITY MMN 000		CHASSIS No.	KILOMETERS 2	PROD. DATE
PURCHASE ORDER No.	DRIVER	CONTACT No.	CONTACT NAME	CONTRACT EXP. KMS	EXP. DATE
CA <input type="checkbox"/>	F/C <input type="checkbox"/>	OH <input type="checkbox"/>	HOME PHONE	BUSINESS PHONE	TERMS
C/C <input type="checkbox"/>	WAR <input type="checkbox"/>	INT <input type="checkbox"/>	VEHICLE ID RP8M66701NV0390	ENGINE No. 2 M66BM5103691	Charge
			DATE AND TIME PROMISED 25/02/23 09:00pm	TIME RECEIVED 10:25am	QUOTE PRICE
				AIR	PWR
				TURBO	

Labour
J# 1 76NAZZZZZ002

- * PDI CLEAN
- * PDI INSPECTION
- * BRAND NEW UNIT
- * CHECKED AND EVALUATED CONCERN:
PERFORMED PDI INSPECTION

Tech(s) : 48048

3125.00

Totals ----- Total - Labour ----- 3125.00

Total Labour.	3125.00
Total Parts..	0.00
Total Other..	0.00
Total P.O.L..	0.00
Total Misc...	0.00
VAT	375.00

Total Invoice 3500.00

[Signature]
02/27/23

[End of Invoice]

ROAD TESTED		ACKNOWLEDGMENT	
ORDER NO.	SUBLET REPAIRS	RECEIVED above vehicle from AUTOHUB CAR CARE SERVICES (ACCS) in good condition and with all repair work enumerated completed to my satisfaction.	
		All works carried out at these premises are subject to a warranty of _____ days or _____ whichever comes first on all labor and materials.	
		SIGNATURE OF OWNER _____	
		I AGREE TO PAY for all works required for all the above described repair at your retail charge. It is understood that any estimate given is provisional and all repairs are undertaken on a cash basis unless prior arrangements for credit have been approved.	
		I have READ AND ACCEPTED your terms and conditions.	

CHECKLIST

RECEIVED

10919

PAGE 1

Client :

VESPA

Chassis # :

039082

Color :

WHITE

Make/Model :

SPRING 125

Engine # :

5103691

Date :

10-12-22

EMBLEMS

- () Piaggio Emblem (Front)
- () PVG Emblem (Crankcase)

SIDE MIRROR

- () LH Side View Mirror
- () RH Side View Mirror

ELECTRICAL BUTTONS

- () Start Button
- () Horn Button
- () High&Low Button
- () Passing Button (Optional)
- () Left Signal Button
- () Right Signal Button
- () Cut Off Engine Button (Optional)
- () Start & Stop Button
- () ASR Button
- () Mode
- () Saddle Button
- () Toggle Switch

LIGHTS

- () Park Light
- () High & Low Beam
- () Front Right Signal
- () Rear Right Signal
- () Front Left Signal
- () Rear Left Signal
- () Backlight
- () Brakelights
- () Instrumental Panel Gauges
- () Plate Light

FLUID LEVELS

- () Engine Oil
- () Gear Oil
- () Brake Fluid
- () Coolant

Remarks :

SCRATCHES

- () No Scratches
 - () W/ Scratches
- *Encircle parts that has/have scratches

COLOR

- () Evenly Painted
- () Not Evenly Painted

BATTERY/ HORN

- () Battery
- Brand: DUKAKI Battery Voltage: 12V
- () Horn

TIRES

- () Good Quality
- () Bad Quality
- Brand: PIRELLI
- Tire Pressure: Front _____ Rear _____

PADS DIAGNOSTIC TOOL

- () PADS Checkup
- Fault : _____
- Remarks: _____

SADDLE

- () Good Quality
- () Bad Quality
- KEYS/ MANUAL/ TOOLS
- () Master Key
- () Duplicate Key
- () Service Manual
- () Warranty Booklet
- () Set of Screw
- () Battery Holder
- () Plate Holder
- () reflectors (Optional)
- () Under Body Caps (Optional)
- () 1 Set of Tools
- () Rear Shock Adjuster
- () Screw Driver
- () Fuse Removal Tool
- () Screw driver (FLOWER KEY)
- () Sparkplug Wrench

I understand all the above items as explained to me by the releasing Officer/ Manager. I also agree that any failure on my part to adhere to any of the instructions given that may result in damages on the above mentioned parts will not be covered by warranty.

Inspected by :

Technician/PDI Personnel

Approved by :


Service Manager

Approved by :

Sales Department

CHECKLIST

Client : VESPA Chassis # : 039082 Color: WHITE 10919 PAGE 2
 Make/Model : SPRINT 125 Engine # : 5103691 Date : 10-12-22



LEGEND

S- Scratched	L- Loose
D- Dented	M- Missing
DD-Damaged	F- Faded

Remarks:

D. TARAMISAN